

Wzorzec akustyczny (producent; nr typu) Brüel & Kjær; 4228.

Oznaczenia:

A – lądowanie

D – start

Pora dnia

| Data | samolot | operacja* | LAeq | LAmx | LAE |
|------------|---------|-----------|-------|-------|-------|
| 2009-05-01 | E170 | A | 68,80 | 71,80 | 80,50 |
| 2009-05-01 | AT72 | A | 68,60 | 70,70 | 81,40 |
| 2009-05-01 | E170 | A | 68,70 | 70,40 | 79,10 |
| 2009-05-01 | AT72 | A | 71,80 | 74,40 | 82,20 |
| 2009-05-01 | B738 | A | 70,30 | 73,30 | 82,90 |
| 2009-05-01 | AT72 | A | 71,10 | 73,00 | 81,10 |
| 2009-05-01 | A319 | A | 69,30 | 72,10 | 80,00 |
| 2009-05-01 | A320 | A | 71,30 | 73,50 | 82,70 |
| 2009-05-01 | B733 | A | 72,70 | 75,60 | 83,50 |
| 2009-05-01 | B738 | A | 71,50 | 74,50 | 82,90 |
| 2009-05-01 | T154 | A | 69,30 | 73,00 | 81,80 |
| 2009-05-01 | B763 | A | 72,50 | 75,70 | 85,10 |
| 2009-05-01 | A320 | A | 74,90 | 78,60 | 86,70 |
| 2009-05-01 | A320 | A | 70,90 | 73,70 | 82,40 |
| 2009-05-01 | B735 | A | 70,00 | 73,10 | 80,40 |
| 2009-05-01 | A320 | A | 70,80 | 72,90 | 81,90 |
| 2009-05-01 | B734 | A | 70,80 | 74,20 | 82,20 |
| 2009-05-01 | T154 | A | 72,50 | 76,60 | 84,80 |
| 2009-05-01 | B734 | A | 73,60 | 78,60 | 85,60 |
| 2009-05-01 | E170 | A | 69,60 | 71,10 | 80,40 |
| 2009-05-01 | A319 | A | 71,30 | 74,80 | 82,40 |
| 2009-05-01 | B763 | A | 72,50 | 75,30 | 84,80 |
| 2009-05-01 | B735 | A | 71,20 | 73,00 | 82,00 |
| 2009-05-01 | AT45 | A | 69,30 | 70,50 | 79,30 |
| 2009-05-01 | B738 | A | 71,50 | 73,90 | 83,00 |
| 2009-05-01 | AT72 | A | 70,60 | 73,00 | 81,70 |
| 2009-05-01 | A320 | A | 69,80 | 72,00 | 80,20 |
| 2009-05-01 | B735 | A | 72,00 | 74,60 | 82,40 |
| 2009-05-01 | E170 | A | 68,00 | 69,90 | 78,70 |
| 2009-05-01 | B734 | A | 71,30 | 73,40 | 82,50 |
| 2009-05-01 | E170 | A | 69,10 | 71,20 | 80,60 |
| 2009-05-01 | A320 | A | 70,20 | 72,20 | 80,20 |
| 2009-05-01 | A320 | A | 68,70 | 69,70 | 79,10 |
| 2009-05-01 | A321 | A | 71,50 | 73,80 | 82,60 |
| 2009-05-01 | B733 | A | 72,50 | 75,00 | 83,00 |
| 2009-05-01 | A320 | A | 70,50 | 72,60 | 81,90 |
| 2009-05-01 | E190 | A | 71,30 | 73,90 | 82,40 |
| 2009-05-01 | AT45 | A | 68,90 | 70,90 | 79,30 |
| 2009-05-01 | RJ85 | A | 67,40 | 68,90 | 77,80 |
| 2009-05-01 | B738 | A | 71,50 | 74,10 | 82,00 |
| 2009-05-01 | A320 | A | 69,10 | 71,50 | 79,80 |
| 2009-05-01 | B763 | A | 68,40 | 71,70 | 79,50 |
| 2009-05-01 | A319 | A | 70,80 | 73,90 | 81,90 |
| 2009-05-01 | A320 | A | 71,00 | 73,80 | 81,80 |
| 2009-05-01 | AT72 | A | 69,30 | 71,10 | 80,70 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-01 | A319 | A | 71,90 | 74,00 | 81,90 |
| 2009-05-01 | B735 | A | 70,20 | 72,00 | 80,60 |
| 2009-05-01 | E170 | A | 68,60 | 70,30 | 78,60 |
| 2009-05-01 | A319 | A | 69,90 | 72,40 | 80,70 |
| 2009-05-01 | E170 | A | 69,60 | 72,40 | 79,60 |
| 2009-05-01 | AT72 | A | 70,60 | 72,50 | 81,40 |
| 2009-05-01 | AT72 | A | 68,30 | 71,40 | 80,40 |
| 2009-05-01 | A320 | A | 71,80 | 73,30 | 82,20 |
| 2009-05-01 | B734 | A | 72,40 | 77,00 | 82,80 |
| 2009-05-01 | B738 | A | 69,60 | 71,80 | 79,60 |
| 2009-05-01 | B734 | A | 70,70 | 72,30 | 80,70 |
| 2009-05-01 | A320 | A | 69,50 | 71,90 | 80,60 |
| 2009-05-01 | A321 | A | 69,90 | 72,00 | 80,30 |
| 2009-05-01 | B735 | A | 70,00 | 71,80 | 80,80 |
| 2009-05-01 | B734 | A | 70,90 | 73,50 | 80,90 |
| 2009-05-01 | B735 | A | 69,20 | 70,50 | 79,20 |
| 2009-05-01 | B738 | A | 70,40 | 72,50 | 80,40 |
| 2009-05-01 | B752 | A | 70,10 | 72,00 | 81,30 |
| 2009-05-01 | E170 | A | 69,10 | 70,70 | 79,10 |
| 2009-05-01 | E170 | A | 68,80 | 70,10 | 78,80 |
| 2009-05-01 | B733 | A | 72,00 | 74,60 | 82,00 |
| 2009-05-01 | B735 | A | 70,30 | 72,00 | 80,80 |
| 2009-05-01 | E170 | A | 68,50 | 70,60 | 78,90 |
| 2009-05-01 | AT72 | A | 70,20 | 72,10 | 80,70 |
| 2009-05-01 | E170 | A | 69,00 | 70,60 | 79,00 |
| 2009-05-01 | B734 | A | 71,10 | 75,20 | 81,80 |
| 2009-05-02 | AT72 | A | 72,00 | 74,60 | 82,40 |
| 2009-05-02 | B734 | A | 71,90 | 75,80 | 82,70 |
| 2009-05-02 | B734 | A | 71,80 | 75,10 | 82,60 |
| 2009-05-02 | B763 | A | 71,90 | 74,40 | 83,90 |
| 2009-05-02 | A320 | A | 69,10 | 70,50 | 79,10 |
| 2009-05-02 | E170 | A | 69,30 | 71,60 | 80,50 |
| 2009-05-02 | B733 | A | 70,80 | 72,80 | 81,60 |
| 2009-05-02 | B763 | A | 72,50 | 75,30 | 84,80 |
| 2009-05-02 | B733 | A | 70,60 | 72,70 | 81,40 |
| 2009-05-02 | E170 | A | 68,90 | 70,60 | 79,30 |
| 2009-05-02 | A320 | A | 70,70 | 72,90 | 81,80 |
| 2009-05-02 | B735 | A | 72,40 | 75,20 | 82,80 |
| 2009-05-02 | AT72 | A | 71,00 | 73,30 | 81,80 |
| 2009-05-02 | A320 | A | 68,90 | 70,90 | 79,30 |
| 2009-05-02 | AT72 | A | 70,50 | 72,60 | 81,90 |
| 2009-05-02 | E170 | A | 69,50 | 72,10 | 79,90 |
| 2009-05-02 | B733 | A | 70,50 | 72,10 | 80,50 |
| 2009-05-02 | A320 | A | 70,60 | 72,70 | 81,00 |
| 2009-05-02 | B733 | A | 69,50 | 71,80 | 80,60 |
| 2009-05-02 | A320 | A | 69,40 | 71,20 | 79,80 |
| 2009-05-02 | B752 | A | 69,80 | 72,00 | 80,60 |
| 2009-05-02 | B763 | D | 70,00 | 72,50 | 82,30 |
| 2009-05-02 | AT72 | A | 71,20 | 73,00 | 81,20 |
| 2009-05-02 | B735 | A | 72,20 | 76,00 | 82,20 |
| 2009-05-02 | AT72 | A | 70,60 | 73,00 | 81,00 |
| 2009-05-02 | A318 | A | 70,60 | 73,70 | 81,00 |
| 2009-05-02 | AT45 | A | 67,80 | 69,80 | 78,20 |
| 2009-05-02 | B737 | A | 70,10 | 72,60 | 80,10 |
| 2009-05-02 | AT72 | A | 70,00 | 72,30 | 80,70 |
| 2009-05-02 | A320 | A | 68,70 | 69,70 | 78,70 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-02 | B734 | A | 71,90 | 74,00 | 82,30 |
| 2009-05-02 | B738 | A | 70,90 | 73,60 | 80,90 |
| 2009-05-02 | A320 | A | 69,00 | 70,50 | 79,00 |
| 2009-05-02 | B734 | D | 69,90 | 71,50 | 80,70 |
| 2009-05-03 | B752 | A | 71,00 | 72,90 | 82,50 |
| 2009-05-03 | B737 | A | 70,80 | 72,70 | 81,20 |
| 2009-05-03 | B763 | A | 72,00 | 75,00 | 83,80 |
| 2009-05-03 | B763 | A | 71,70 | 73,50 | 83,40 |
| 2009-05-03 | B733 | A | 71,30 | 73,50 | 81,30 |
| 2009-05-03 | E170 | A | 69,80 | 71,00 | 79,80 |
| 2009-05-03 | A320 | A | 70,90 | 73,10 | 82,60 |
| 2009-05-03 | AT45 | A | 69,30 | 71,00 | 79,30 |
| 2009-05-03 | AT72 | A | 71,80 | 74,20 | 82,90 |
| 2009-05-03 | AT72 | A | 67,60 | 71,30 | 78,00 |
| 2009-05-03 | A321 | A | 71,80 | 74,30 | 82,20 |
| 2009-05-03 | A321 | A | 69,50 | 71,50 | 80,60 |
| 2009-05-03 | B738 | A | 72,40 | 75,00 | 83,20 |
| 2009-05-03 | A320 | A | 70,40 | 72,10 | 80,80 |
| 2009-05-03 | A319 | A | 69,00 | 70,70 | 79,00 |
| 2009-05-03 | B735 | A | 70,40 | 72,40 | 80,80 |
| 2009-05-03 | A319 | A | 72,00 | 74,90 | 83,50 |
| 2009-05-03 | A320 | A | 73,70 | 76,70 | 84,80 |
| 2009-05-03 | B752 | A | 70,70 | 72,60 | 80,70 |
| 2009-05-03 | P180 | A | 73,90 | 79,40 | 87,20 |
| 2009-05-03 | C402 | A | 71,70 | 73,80 | 82,50 |
| 2009-05-03 | E170 | A | 69,10 | 72,00 | 79,50 |
| 2009-05-03 | B733 | A | 72,10 | 76,80 | 82,60 |
| 2009-05-03 | B763 | A | 74,00 | 77,40 | 85,70 |
| 2009-05-03 | E170 | A | 67,90 | 70,20 | 79,30 |
| 2009-05-03 | A319 | A | 72,90 | 75,60 | 84,00 |
| 2009-05-03 | A320 | A | 71,50 | 74,90 | 81,50 |
| 2009-05-03 | B735 | A | 69,80 | 71,10 | 79,80 |
| 2009-05-03 | B735 | A | 70,70 | 72,90 | 80,70 |
| 2009-05-03 | AT72 | A | 71,40 | 74,00 | 81,40 |
| 2009-05-03 | B734 | A | 73,00 | 76,90 | 83,50 |
| 2009-05-03 | E170 | A | 68,80 | 71,20 | 79,60 |
| 2009-05-03 | A319 | A | 69,50 | 70,70 | 79,90 |
| 2009-05-03 | E170 | A | 68,50 | 70,30 | 78,50 |
| 2009-05-03 | B735 | A | 73,50 | 78,00 | 83,50 |
| 2009-05-03 | A319 | A | 71,70 | 73,90 | 82,10 |
| 2009-05-03 | AT72 | A | 71,40 | 73,70 | 81,90 |
| 2009-05-03 | E170 | A | 69,10 | 70,30 | 79,10 |
| 2009-05-03 | B735 | A | 71,20 | 72,80 | 81,20 |
| 2009-05-03 | AT72 | A | 68,40 | 70,40 | 78,40 |
| 2009-05-03 | B734 | A | 72,60 | 76,40 | 83,10 |
| 2009-05-03 | AT45 | A | 65,20 | 68,60 | 80,10 |
| 2009-05-03 | AT72 | A | 70,60 | 72,30 | 80,60 |
| 2009-05-03 | B736 | A | 69,70 | 71,60 | 79,70 |
| 2009-05-03 | B734 | A | 72,60 | 75,20 | 83,00 |
| 2009-05-03 | AT72 | A | 70,10 | 72,10 | 81,20 |
| 2009-05-03 | AT72 | A | 68,30 | 70,70 | 80,10 |
| 2009-05-04 | B734 | D | 68,60 | 70,00 | 79,70 |
| 2009-05-04 | B733 | D | 72,20 | 75,30 | 83,30 |
| 2009-05-04 | E170 | D | 70,00 | 71,80 | 81,40 |
| 2009-05-06 | B734 | D | 66,70 | 68,80 | 77,80 |
| 2009-05-08 | YK40 | D | 69,30 | 72,10 | 80,10 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-08 | B738 | D | 68,40 | 71,00 | 79,60 |
| 2009-05-08 | B752 | D | 67,40 | 69,40 | 78,60 |
| 2009-05-08 | B738 | D | 68,30 | 71,20 | 80,80 |
| 2009-05-08 | B738 | D | 68,90 | 71,20 | 81,40 |
| 2009-05-08 | B734 | D | 71,60 | 74,80 | 84,60 |
| 2009-05-09 | AT72 | A | 69,60 | 71,30 | 80,00 |
| 2009-05-09 | B734 | A | 72,40 | 76,10 | 84,40 |
| 2009-05-09 | AT45 | A | 70,20 | 72,50 | 80,20 |
| 2009-05-09 | AT72 | A | 72,10 | 76,60 | 84,70 |
| 2009-05-09 | B734 | A | 71,50 | 77,70 | 89,30 |
| 2009-05-09 | B734 | A | 69,20 | 71,50 | 81,50 |
| 2009-05-09 | A319 | A | 71,60 | 74,40 | 89,40 |
| 2009-05-09 | F70 | A | 69,20 | 70,80 | 81,20 |
| 2009-05-09 | B734 | A | 73,60 | 78,40 | 87,90 |
| 2009-05-09 | CRJ2 | A | 69,10 | 70,80 | 80,30 |
| 2009-05-09 | B733 | A | 71,20 | 74,80 | 83,20 |
| 2009-05-09 | AT45 | A | 69,50 | 72,30 | 81,50 |
| 2009-05-09 | B734 | A | 71,90 | 75,90 | 84,60 |
| 2009-05-09 | A320 | A | 71,30 | 73,20 | 83,10 |
| 2009-05-09 | B763 | A | 73,10 | 75,90 | 86,90 |
| 2009-05-09 | E170 | A | 70,90 | 74,30 | 84,00 |
| 2009-05-09 | A319 | A | 70,50 | 72,60 | 82,30 |
| 2009-05-09 | B763 | A | 72,00 | 75,60 | 85,60 |
| 2009-05-09 | DH8D | A | 71,20 | 75,10 | 83,00 |
| 2009-05-09 | E170 | A | 69,70 | 71,40 | 80,80 |
| 2009-05-09 | AT72 | A | 73,00 | 75,90 | 84,40 |
| 2009-05-09 | B735 | A | 72,00 | 74,80 | 83,50 |
| 2009-05-09 | AT72 | A | 70,60 | 71,90 | 81,70 |
| 2009-05-09 | AT72 | A | 72,10 | 74,70 | 84,90 |
| 2009-05-09 | A320 | A | 72,50 | 75,60 | 83,70 |
| 2009-05-09 | A320 | A | 71,30 | 74,00 | 82,50 |
| 2009-05-09 | B734 | A | 70,60 | 73,00 | 83,20 |
| 2009-05-09 | A320 | A | 70,90 | 73,30 | 82,40 |
| 2009-05-09 | AT72 | A | 70,10 | 71,70 | 80,90 |
| 2009-05-09 | A320 | A | 69,20 | 71,10 | 80,40 |
| 2009-05-09 | A320 | A | 70,10 | 72,10 | 81,30 |
| 2009-05-09 | AT72 | A | 70,80 | 73,20 | 83,10 |
| 2009-05-09 | A320 | A | 71,30 | 74,10 | 83,60 |
| 2009-05-09 | E170 | A | 70,40 | 72,20 | 82,10 |
| 2009-05-09 | B734 | A | 72,10 | 76,70 | 84,60 |
| 2009-05-09 | E170 | A | 68,70 | 69,90 | 79,20 |
| 2009-05-09 | B733 | A | 70,40 | 72,70 | 81,50 |
| 2009-05-09 | A320 | A | 69,50 | 71,30 | 79,90 |
| 2009-05-09 | A320 | A | 71,90 | 75,50 | 84,00 |
| 2009-05-09 | E170 | A | 70,00 | 73,00 | 80,80 |
| 2009-05-09 | B733 | A | 71,90 | 73,80 | 82,70 |
| 2009-05-09 | A320 | A | 71,40 | 73,10 | 81,80 |
| 2009-05-09 | E190 | A | 72,50 | 76,00 | 84,50 |
| 2009-05-09 | B734 | A | 72,20 | 75,10 | 83,00 |
| 2009-05-09 | B752 | A | 70,90 | 72,90 | 82,40 |
| 2009-05-09 | B763 | A | 72,00 | 75,00 | 84,00 |
| 2009-05-09 | A320 | A | 71,60 | 74,30 | 83,40 |
| 2009-05-09 | A320 | A | 74,20 | 78,60 | 87,60 |
| 2009-05-09 | AT72 | A | 70,90 | 74,20 | 83,70 |
| 2009-05-09 | A319 | A | 74,50 | 78,70 | 87,50 |
| 2009-05-09 | B735 | A | 70,80 | 74,30 | 81,20 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-09 | AT45 | A | 69,20 | 70,40 | 79,20 |
| 2009-05-09 | A319 | A | 69,80 | 71,60 | 80,60 |
| 2009-05-09 | B734 | A | 71,20 | 73,50 | 82,00 |
| 2009-05-09 | AT72 | A | 71,40 | 73,20 | 82,20 |
| 2009-05-09 | B737 | A | 71,00 | 73,30 | 81,40 |
| 2009-05-09 | E170 | A | 69,90 | 73,30 | 81,40 |
| 2009-05-09 | B734 | A | 71,10 | 74,20 | 81,90 |
| 2009-05-09 | A319 | A | 69,40 | 71,20 | 79,80 |
| 2009-05-09 | A320 | A | 69,00 | 70,40 | 79,40 |
| 2009-05-09 | YK40 | A | 70,60 | 73,30 | 81,00 |
| 2009-05-09 | B734 | A | 71,20 | 74,70 | 82,00 |
| 2009-05-09 | E170 | A | 69,60 | 71,30 | 79,60 |
| 2009-05-09 | B738 | A | 71,00 | 73,00 | 81,40 |
| 2009-05-09 | A320 | A | 68,40 | 70,10 | 79,20 |
| 2009-05-09 | A318 | A | 70,00 | 71,90 | 80,40 |
| 2009-05-09 | AT72 | A | 70,70 | 72,40 | 81,10 |
| 2009-05-09 | B734 | A | 72,50 | 75,90 | 84,30 |
| 2009-05-09 | A319 | A | 71,80 | 73,80 | 82,60 |
| 2009-05-09 | B733 | A | 70,60 | 72,70 | 81,00 |
| 2009-05-09 | AT45 | A | 68,20 | 68,90 | 78,20 |
| 2009-05-09 | B735 | A | 69,10 | 70,40 | 79,10 |
| 2009-05-09 | B735 | A | 69,80 | 71,20 | 79,80 |
| 2009-05-09 | A320 | A | 71,50 | 74,10 | 82,30 |
| 2009-05-09 | B734 | A | 70,90 | 73,40 | 81,70 |
| 2009-05-09 | E170 | A | 69,20 | 70,90 | 79,20 |
| 2009-05-09 | B735 | A | 71,00 | 73,40 | 81,00 |
| 2009-05-09 | B735 | A | 71,40 | 74,10 | 81,40 |
| 2009-05-09 | B734 | A | 71,90 | 74,80 | 82,70 |
| 2009-05-09 | B733 | A | 70,40 | 72,40 | 80,80 |
| 2009-05-09 | AT72 | A | 71,00 | 73,10 | 82,10 |
| 2009-05-09 | B733 | A | 71,20 | 73,10 | 81,70 |
| 2009-05-09 | AT72 | A | 71,00 | 72,50 | 82,10 |
| 2009-05-09 | AT45 | A | 68,70 | 70,30 | 78,70 |
| 2009-05-09 | B734 | D | 70,10 | 72,60 | 81,60 |
| 2009-05-10 | B703 | A | 82,50 | 88,50 | 96,30 |
| 2009-05-10 | B737 | A | 70,20 | 71,80 | 80,20 |
| 2009-05-10 | B734 | A | 71,80 | 74,10 | 81,80 |
| 2009-05-10 | B763 | A | 72,80 | 75,10 | 84,50 |
| 2009-05-10 | B703 | D | 76,20 | 80,20 | 91,60 |
| 2009-05-10 | B734 | D | 68,90 | 72,10 | 80,00 |
| 2009-05-10 | B763 | D | 71,80 | 74,60 | 83,60 |
| 2009-05-10 | B763 | D | 72,60 | 74,80 | 84,90 |
| 2009-05-10 | B735 | D | 69,60 | 72,30 | 81,10 |
| 2009-05-10 | B738 | D | 67,30 | 69,60 | 78,10 |
| 2009-05-10 | A320 | D | 68,60 | 71,90 | 81,20 |
| 2009-05-10 | B733 | D | 69,60 | 72,90 | 80,10 |
| 2009-05-10 | B733 | D | 69,80 | 72,40 | 81,00 |
| 2009-05-10 | B734 | D | 69,40 | 70,80 | 80,50 |
| 2009-05-10 | E170 | D | 67,40 | 70,40 | 78,60 |
| 2009-05-10 | B735 | D | 68,50 | 70,00 | 78,90 |
| 2009-05-10 | MD87 | D | 75,60 | 79,60 | 89,20 |
| 2009-05-10 | E170 | D | 70,30 | 73,00 | 81,40 |
| 2009-05-10 | B735 | A | 72,40 | 75,80 | 84,20 |
| 2009-05-10 | F100 | A | 69,10 | 70,40 | 80,50 |
| 2009-05-10 | AT72 | A | 68,70 | 69,50 | 79,50 |
| 2009-05-10 | CRJ7 | A | 70,20 | 72,20 | 81,00 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-10 | E190 | A | 70,90 | 72,80 | 82,10 |
| 2009-05-10 | E170 | A | 69,70 | 71,70 | 80,80 |
| 2009-05-10 | AT45 | A | 70,10 | 71,90 | 81,60 |
| 2009-05-10 | E170 | A | 69,50 | 72,00 | 80,00 |
| 2009-05-10 | B737 | A | 71,70 | 73,50 | 84,00 |
| 2009-05-10 | E170 | A | 70,20 | 72,90 | 81,30 |
| 2009-05-10 | E170 | A | 68,60 | 71,30 | 80,10 |
| 2009-05-10 | A320 | A | 72,30 | 75,10 | 85,10 |
| 2009-05-10 | GL5T | A | 69,50 | 71,30 | 80,30 |
| 2009-05-10 | B734 | A | 72,30 | 76,60 | 84,90 |
| 2009-05-10 | E170 | A | 69,30 | 71,80 | 80,50 |
| 2009-05-10 | B734 | A | 73,30 | 76,90 | 84,80 |
| 2009-05-10 | AT72 | A | 72,80 | 76,60 | 85,60 |
| 2009-05-10 | B735 | A | 72,20 | 75,70 | 83,70 |
| 2009-05-10 | B735 | A | 72,10 | 75,80 | 83,60 |
| 2009-05-10 | E170 | A | 70,40 | 73,00 | 81,20 |
| 2009-05-10 | E170 | A | 70,30 | 72,60 | 81,70 |
| 2009-05-10 | B733 | A | 71,90 | 74,70 | 83,30 |
| 2009-05-10 | AT72 | A | 68,60 | 70,00 | 79,40 |
| 2009-05-10 | B738 | A | 72,40 | 74,80 | 84,20 |
| 2009-05-10 | AT72 | A | 71,80 | 74,30 | 84,10 |
| 2009-05-10 | E170 | A | 69,30 | 71,30 | 80,80 |
| 2009-05-10 | AT72 | A | 70,70 | 73,10 | 82,70 |
| 2009-05-10 | B735 | A | 73,10 | 76,30 | 84,20 |
| 2009-05-10 | B733 | A | 71,00 | 73,90 | 83,10 |
| 2009-05-10 | AT72 | A | 73,20 | 75,80 | 84,30 |
| 2009-05-11 | B733 | A | 73,20 | 78,60 | 84,90 |
| 2009-05-11 | AT72 | A | 72,30 | 74,90 | 84,60 |
| 2009-05-11 | AT72 | A | 71,70 | 73,80 | 82,50 |
| 2009-05-11 | E170 | A | 70,00 | 71,40 | 80,80 |
| 2009-05-11 | AT45 | A | 69,30 | 71,40 | 81,10 |
| 2009-05-11 | AT72 | A | 72,80 | 75,50 | 84,30 |
| 2009-05-14 | E170 | A | 69,40 | 71,50 | 79,80 |
| 2009-05-14 | E170 | A | 70,30 | 72,40 | 81,70 |
| 2009-05-14 | AT72 | A | 71,60 | 75,20 | 82,40 |
| 2009-05-14 | A320 | A | 70,90 | 74,70 | 82,40 |
| 2009-05-14 | A319 | A | 69,50 | 70,70 | 79,50 |
| 2009-05-14 | E170 | A | 69,80 | 72,30 | 80,20 |
| 2009-05-14 | B734 | A | 72,40 | 76,50 | 83,50 |
| 2009-05-14 | E170 | A | 68,80 | 71,00 | 78,80 |
| 2009-05-14 | A320 | A | 71,10 | 73,40 | 81,90 |
| 2009-05-14 | AT72 | A | 70,10 | 71,90 | 81,80 |
| 2009-05-14 | E170 | A | 70,20 | 72,00 | 81,40 |
| 2009-05-14 | AT72 | A | 71,50 | 74,90 | 83,20 |
| 2009-05-14 | AT45 | A | 68,10 | 70,30 | 78,90 |
| 2009-05-14 | E170 | A | 70,20 | 72,60 | 80,20 |
| 2009-05-14 | A320 | A | 71,00 | 73,60 | 81,40 |
| 2009-05-14 | B735 | A | 71,60 | 74,10 | 82,00 |
| 2009-05-14 | E170 | A | 68,70 | 71,10 | 80,20 |
| 2009-05-14 | A320 | A | 70,50 | 72,30 | 80,50 |
| 2009-05-14 | B763 | A | 72,80 | 76,10 | 85,60 |
| 2009-05-14 | B733 | A | 71,90 | 74,20 | 81,90 |
| 2009-05-14 | B738 | A | 71,20 | 73,50 | 82,00 |
| 2009-05-14 | AN12 | A | 76,80 | 81,30 | 88,80 |
| 2009-05-14 | CRJ9 | A | 68,50 | 70,00 | 78,50 |
| 2009-05-14 | A320 | A | 69,70 | 71,40 | 79,70 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-14 | B738 | A | 69,70 | 71,70 | 80,50 |
| 2009-05-14 | E170 | A | 70,40 | 72,50 | 81,50 |
| 2009-05-14 | MD11 | A | 75,00 | 78,90 | 88,60 |
| 2009-05-14 | A318 | A | 70,50 | 72,20 | 81,60 |
| 2009-05-14 | B735 | A | 70,10 | 71,40 | 80,50 |
| 2009-05-14 | AT72 | A | 74,00 | 80,10 | 84,80 |
| 2009-05-14 | B735 | A | 72,30 | 74,90 | 82,30 |
| 2009-05-14 | A320 | A | 68,60 | 69,80 | 78,60 |
| 2009-05-14 | E170 | A | 68,80 | 70,80 | 78,80 |
| 2009-05-14 | A319 | A | 69,70 | 71,00 | 80,10 |
| 2009-05-14 | B733 | A | 70,20 | 72,20 | 81,00 |
| 2009-05-14 | E170 | A | 68,90 | 70,50 | 79,30 |
| 2009-05-14 | B734 | A | 72,70 | 76,40 | 84,70 |
| 2009-05-14 | B733 | A | 74,10 | 78,40 | 89,00 |
| 2009-05-14 | E170 | A | 69,70 | 71,40 | 80,10 |
| 2009-05-14 | T154 | A | 72,00 | 74,10 | 83,10 |
| 2009-05-14 | B738 | A | 74,70 | 79,00 | 90,50 |
| 2009-05-14 | B735 | A | 71,90 | 74,30 | 81,90 |
| 2009-05-14 | AT72 | A | 70,70 | 72,40 | 81,10 |
| 2009-05-14 | CRJ7 | A | 71,60 | 73,40 | 81,60 |
| 2009-05-14 | B737 | A | 70,30 | 72,20 | 80,70 |
| 2009-05-14 | E170 | A | 68,70 | 70,10 | 79,10 |
| 2009-05-14 | A320 | A | 71,50 | 75,30 | 82,60 |
| 2009-05-14 | B735 | A | 71,10 | 73,50 | 81,10 |
| 2009-05-14 | B735 | A | 72,90 | 77,20 | 82,90 |
| 2009-05-14 | B735 | A | 71,30 | 75,50 | 82,10 |
| 2009-05-14 | B734 | A | 72,50 | 76,00 | 83,30 |
| 2009-05-14 | B734 | A | 72,60 | 76,10 | 83,40 |
| 2009-05-14 | B733 | A | 70,30 | 71,60 | 80,70 |
| 2009-05-15 | B752 | A | 72,30 | 74,50 | 83,70 |
| 2009-05-15 | E170 | A | 68,80 | 70,30 | 78,80 |
| 2009-05-15 | AT72 | A | 70,50 | 72,70 | 82,00 |
| 2009-05-15 | E170 | A | 70,00 | 71,30 | 80,40 |
| 2009-05-15 | AT45 | A | 69,70 | 71,30 | 79,70 |
| 2009-05-15 | E170 | A | 68,70 | 69,80 | 78,70 |
| 2009-05-15 | AT43 | A | 70,40 | 71,80 | 82,40 |
| 2009-05-15 | B738 | A | 71,10 | 73,30 | 82,30 |
| 2009-05-15 | B733 | A | 72,30 | 74,20 | 83,10 |
| 2009-05-15 | A319 | A | 70,40 | 73,70 | 81,20 |
| 2009-05-15 | A320 | A | 73,20 | 76,40 | 86,00 |
| 2009-05-15 | B738 | A | 71,50 | 73,70 | 83,20 |
| 2009-05-15 | RJ85 | A | 70,90 | 72,60 | 80,90 |
| 2009-05-15 | B735 | A | 71,90 | 74,20 | 83,30 |
| 2009-05-15 | B738 | A | 70,90 | 72,70 | 82,00 |
| 2009-05-15 | A319 | A | 70,00 | 72,60 | 81,50 |
| 2009-05-15 | DH8D | A | 68,40 | 70,10 | 78,80 |
| 2009-05-15 | A320 | A | 70,80 | 73,10 | 82,50 |
| 2009-05-15 | E170 | A | 69,20 | 70,50 | 79,20 |
| 2009-05-15 | A319 | A | 70,40 | 73,50 | 80,80 |
| 2009-05-15 | MD82 | A | 70,60 | 72,80 | 81,40 |
| 2009-05-15 | A320 | A | 72,20 | 76,40 | 85,60 |
| 2009-05-15 | B734 | A | 73,10 | 76,20 | 83,50 |
| 2009-05-15 | E170 | A | 75,70 | 80,20 | 87,40 |
| 2009-05-15 | AT72 | A | 72,40 | 74,70 | 82,80 |
| 2009-05-15 | A320 | A | 70,90 | 73,70 | 82,10 |
| 2009-05-15 | AT72 | A | 70,00 | 71,60 | 80,00 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-15 | B735 | A | 70,20 | 71,40 | 80,60 |
| 2009-05-15 | B738 | A | 71,90 | 73,80 | 83,00 |
| 2009-05-15 | B763 | A | 73,20 | 78,00 | 85,50 |
| 2009-05-15 | AT72 | A | 72,00 | 75,10 | 84,00 |
| 2009-05-15 | B735 | A | 70,30 | 72,10 | 80,70 |
| 2009-05-15 | B734 | A | 72,10 | 74,60 | 82,10 |
| 2009-05-15 | A320 | A | 69,20 | 71,50 | 80,00 |
| 2009-05-15 | B734 | A | 71,10 | 73,80 | 82,20 |
| 2009-05-15 | AT72 | A | 71,00 | 73,10 | 81,40 |
| 2009-05-15 | A321 | A | 70,90 | 73,00 | 81,70 |
| 2009-05-15 | A320 | A | 69,10 | 71,10 | 79,90 |
| 2009-05-15 | A321 | A | 69,90 | 71,90 | 80,70 |
| 2009-05-15 | B733 | A | 70,40 | 72,70 | 80,40 |
| 2009-05-15 | A319 | A | 70,40 | 71,70 | 80,40 |
| 2009-05-15 | A320 | A | 70,10 | 71,90 | 80,50 |
| 2009-05-15 | A320 | A | 70,30 | 72,90 | 81,50 |
| 2009-05-15 | P180 | A | 71,60 | 74,80 | 83,70 |
| 2009-05-15 | E170 | A | 70,80 | 72,70 | 80,80 |
| 2009-05-15 | E190 | A | 69,60 | 71,80 | 80,00 |
| 2009-05-15 | A321 | A | 70,40 | 71,60 | 80,80 |
| 2009-05-15 | T154 | A | 73,10 | 76,40 | 85,10 |
| 2009-05-15 | B733 | A | 69,00 | 70,90 | 79,40 |
| 2009-05-15 | B763 | A | 72,30 | 75,80 | 84,60 |
| 2009-05-15 | A319 | A | 70,10 | 74,40 | 80,90 |
| 2009-05-15 | B735 | A | 72,50 | 75,60 | 82,50 |
| 2009-05-15 | A320 | A | 70,10 | 71,80 | 80,60 |
| 2009-05-15 | E170 | A | 69,70 | 71,00 | 79,70 |
| 2009-05-15 | A319 | A | 70,70 | 72,10 | 80,70 |
| 2009-05-15 | AT72 | A | 68,70 | 70,10 | 78,70 |
| 2009-05-15 | A320 | A | 70,10 | 72,30 | 80,50 |
| 2009-05-15 | B763 | A | 73,30 | 76,80 | 84,50 |
| 2009-05-15 | E170 | A | 69,00 | 70,50 | 79,80 |
| 2009-05-15 | B735 | A | 73,40 | 75,30 | 83,40 |
| 2009-05-15 | E170 | A | 67,90 | 69,70 | 77,90 |
| 2009-05-15 | B734 | A | 72,80 | 77,00 | 82,80 |
| 2009-05-15 | B738 | A | 70,20 | 72,20 | 80,60 |
| 2009-05-15 | T154 | A | 74,20 | 77,80 | 85,00 |
| 2009-05-15 | P180 | A | 71,90 | 75,10 | 84,90 |
| 2009-05-15 | A321 | A | 70,10 | 71,80 | 80,10 |
| 2009-05-15 | AT72 | A | 70,50 | 72,20 | 81,30 |
| 2009-05-15 | MD11 | A | 73,40 | 76,80 | 85,70 |
| 2009-05-15 | B735 | A | 69,50 | 71,00 | 79,50 |
| 2009-05-15 | AT72 | A | 69,90 | 71,30 | 80,30 |
| 2009-05-15 | AT72 | A | 71,30 | 72,80 | 82,00 |
| 2009-05-15 | B737 | A | 70,50 | 72,30 | 80,90 |
| 2009-05-15 | B735 | A | 70,50 | 72,10 | 80,90 |
| 2009-05-15 | A320 | A | 70,20 | 71,90 | 81,00 |
| 2009-05-15 | B735 | A | 70,60 | 73,00 | 80,60 |
| 2009-05-15 | B752 | A | 70,60 | 72,10 | 82,00 |
| 2009-05-15 | B734 | A | 71,70 | 74,50 | 82,80 |
| 2009-05-15 | B734 | A | 71,80 | 74,40 | 82,20 |
| 2009-05-15 | AT45 | A | 69,70 | 71,10 | 79,70 |
| 2009-05-15 | E170 | A | 69,10 | 70,80 | 79,10 |
| 2009-05-15 | AT72 | A | 72,70 | 74,40 | 84,10 |
| 2009-05-15 | E170 | A | 69,40 | 70,90 | 79,80 |
| 2009-05-15 | AT72 | A | 72,10 | 73,70 | 82,60 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-15 | E170 | A | 69,00 | 70,40 | 79,00 |
| 2009-05-15 | B734 | A | 70,10 | 71,60 | 80,90 |
| 2009-05-15 | B735 | A | 70,00 | 71,50 | 80,40 |
| 2009-05-15 | AT72 | A | 71,70 | 73,60 | 82,10 |
| 2009-05-16 | E170 | A | 70,30 | 72,20 | 80,70 |
| 2009-05-16 | B734 | A | 72,10 | 73,60 | 82,10 |
| 2009-05-16 | B734 | A | 72,00 | 75,40 | 83,10 |
| 2009-05-16 | A320 | A | 71,70 | 73,60 | 82,40 |
| 2009-05-16 | E170 | A | 69,70 | 74,20 | 86,00 |
| 2009-05-16 | B734 | A | 71,70 | 75,50 | 84,90 |
| 2009-05-16 | AT45 | A | 67,70 | 71,90 | 78,80 |
| 2009-05-16 | AT45 | A | 69,40 | 72,00 | 82,20 |
| 2009-05-16 | B733 | D | 69,30 | 71,40 | 81,10 |
| 2009-05-16 | A320 | D | 69,50 | 71,30 | 81,00 |
| 2009-05-16 | B735 | D | 69,20 | 71,50 | 79,60 |
| 2009-05-16 | E170 | D | 68,60 | 71,10 | 81,40 |
| 2009-05-16 | B735 | D | 70,40 | 72,40 | 81,50 |
| 2009-05-16 | AT72 | D | 70,90 | 73,50 | 83,20 |
| 2009-05-16 | B763 | D | 73,50 | 77,00 | 86,10 |
| 2009-05-16 | E190 | D | 69,10 | 69,80 | 79,10 |
| 2009-05-16 | B763 | D | 70,00 | 72,40 | 81,50 |
| 2009-05-16 | B738 | A | 71,70 | 74,50 | 82,80 |
| 2009-05-16 | A320 | A | 70,60 | 73,20 | 82,10 |
| 2009-05-16 | A318 | A | 71,40 | 73,40 | 82,20 |
| 2009-05-16 | E170 | A | 70,10 | 72,50 | 80,60 |
| 2009-05-16 | C30J | A | 73,50 | 77,00 | 84,70 |
| 2009-05-16 | B735 | A | 71,90 | 76,60 | 83,70 |
| 2009-05-16 | B733 | A | 75,30 | 79,20 | 86,70 |
| 2009-05-16 | AT72 | A | 72,70 | 76,10 | 84,50 |
| 2009-05-16 | B752 | A | 71,50 | 74,00 | 84,10 |
| 2009-05-16 | E170 | A | 70,30 | 73,00 | 81,50 |
| 2009-05-16 | A319 | A | 72,70 | 75,60 | 85,50 |
| 2009-05-16 | B734 | A | 73,40 | 76,30 | 85,20 |
| 2009-05-16 | DH8D | A | 70,20 | 72,40 | 81,00 |
| 2009-05-16 | B735 | A | 72,70 | 75,70 | 83,80 |
| 2009-05-16 | E170 | A | 69,50 | 71,60 | 80,30 |
| 2009-05-16 | F100 | A | 69,20 | 71,00 | 79,20 |
| 2009-05-16 | AT45 | A | 70,60 | 72,20 | 81,40 |
| 2009-05-16 | B734 | A | 72,00 | 76,90 | 83,40 |
| 2009-05-16 | E170 | A | 69,50 | 71,10 | 80,30 |
| 2009-05-16 | E170 | A | 69,60 | 71,60 | 81,00 |
| 2009-05-16 | B738 | A | 71,10 | 74,60 | 83,40 |
| 2009-05-16 | B735 | A | 70,20 | 72,30 | 82,20 |
| 2009-05-16 | B738 | A | 71,20 | 73,80 | 82,60 |
| 2009-05-16 | AT72 | A | 68,90 | 71,10 | 80,90 |
| 2009-05-16 | B734 | A | 74,10 | 78,50 | 87,40 |
| 2009-05-16 | E170 | A | 69,10 | 72,60 | 80,90 |
| 2009-05-16 | B733 | A | 73,70 | 77,90 | 85,40 |
| 2009-05-16 | E170 | A | 70,60 | 74,00 | 82,90 |
| 2009-05-16 | B734 | A | 72,90 | 77,50 | 85,20 |
| 2009-05-16 | E170 | A | 69,70 | 71,60 | 80,80 |
| 2009-05-16 | AT72 | A | 71,50 | 73,60 | 83,80 |
| 2009-05-16 | B735 | A | 72,70 | 76,80 | 84,80 |
| 2009-05-16 | E170 | A | 70,60 | 73,20 | 81,70 |
| 2009-05-16 | B733 | A | 72,70 | 76,00 | 84,80 |
| 2009-05-16 | AT72 | A | 72,30 | 75,30 | 85,30 |

| | | | | | |
|------------|------|---|-------|-------|--------|
| 2009-05-16 | B734 | A | 72,10 | 75,20 | 83,80 |
| 2009-05-16 | AT45 | A | 71,50 | 73,70 | 83,80 |
| 2009-05-17 | B734 | A | 73,60 | 77,00 | 85,40 |
| 2009-05-17 | AT72 | A | 70,70 | 72,00 | 83,10 |
| 2009-05-17 | AT45 | A | 71,20 | 73,90 | 82,70 |
| 2009-05-17 | B752 | A | 74,30 | 77,60 | 87,70 |
| 2009-05-17 | RJ85 | A | 70,60 | 72,10 | 80,60 |
| 2009-05-17 | E170 | A | 69,90 | 71,20 | 80,30 |
| 2009-05-17 | F70 | A | 67,90 | 70,80 | 79,60 |
| 2009-05-17 | B734 | A | 72,90 | 76,50 | 85,20 |
| 2009-05-17 | B763 | A | 75,10 | 78,20 | 87,90 |
| 2009-05-17 | B733 | A | 72,40 | 76,20 | 83,80 |
| 2009-05-17 | B763 | A | 73,00 | 77,80 | 88,30 |
| 2009-05-17 | C295 | A | 82,90 | 88,00 | 100,60 |
| 2009-05-17 | B735 | A | 80,90 | 86,10 | 98,70 |
| 2009-05-17 | AT72 | A | 77,60 | 81,60 | 91,00 |
| 2009-05-17 | AT72 | A | 74,60 | 78,70 | 92,30 |
| 2009-05-17 | AT45 | A | 74,30 | 78,00 | 92,00 |
| 2009-05-17 | A320 | A | 71,90 | 74,50 | 83,70 |
| 2009-05-17 | AT72 | A | 70,10 | 72,20 | 80,50 |
| 2009-05-17 | AT45 | A | 71,30 | 73,10 | 82,50 |
| 2009-05-17 | AT72 | A | 73,20 | 74,90 | 85,00 |
| 2009-05-17 | A321 | A | 71,70 | 74,00 | 82,80 |
| 2009-05-17 | AT72 | A | 72,40 | 74,20 | 84,40 |
| 2009-05-17 | A321 | A | 72,60 | 75,50 | 84,40 |
| 2009-05-17 | E170 | A | 70,20 | 72,90 | 80,20 |
| 2009-05-17 | B734 | A | 72,70 | 76,20 | 84,10 |
| 2009-05-17 | E170 | A | 69,20 | 70,60 | 80,30 |
| 2009-05-17 | A320 | A | 70,20 | 71,70 | 81,00 |
| 2009-05-17 | A320 | A | 71,10 | 73,00 | 82,60 |
| 2009-05-17 | A319 | A | 71,50 | 74,30 | 83,30 |
| 2009-05-17 | B735 | A | 70,20 | 71,90 | 81,40 |
| 2009-05-17 | A319 | A | 72,30 | 75,90 | 84,90 |
| 2009-05-17 | AT45 | A | 70,30 | 72,10 | 82,30 |
| 2009-05-17 | A320 | A | 71,10 | 73,50 | 83,40 |
| 2009-05-17 | E170 | A | 70,10 | 72,30 | 80,90 |
| 2009-05-17 | E170 | A | 69,80 | 72,10 | 80,20 |
| 2009-05-17 | RJ85 | A | 69,40 | 70,80 | 80,60 |
| 2009-05-17 | B733 | A | 73,80 | 77,30 | 84,90 |
| 2009-05-17 | A320 | A | 69,50 | 71,60 | 80,70 |
| 2009-05-17 | AT45 | A | 69,50 | 71,10 | 80,30 |
| 2009-05-17 | A310 | A | 73,20 | 76,90 | 86,40 |
| 2009-05-17 | A321 | A | 71,40 | 73,40 | 82,20 |
| 2009-05-17 | A320 | A | 71,40 | 73,50 | 83,10 |
| 2009-05-17 | AT45 | A | 70,60 | 72,20 | 81,40 |
| 2009-05-17 | A319 | A | 71,70 | 73,90 | 82,50 |
| 2009-05-17 | B733 | A | 72,00 | 74,60 | 83,10 |
| 2009-05-17 | AT72 | A | 71,00 | 73,80 | 83,60 |
| 2009-05-17 | B733 | A | 72,30 | 76,30 | 85,10 |
| 2009-05-17 | AT72 | A | 73,30 | 76,20 | 85,30 |
| 2009-05-17 | F100 | A | 68,70 | 69,80 | 79,20 |
| 2009-05-17 | B735 | A | 73,40 | 77,20 | 84,50 |
| 2009-05-17 | A319 | A | 71,90 | 74,80 | 84,90 |
| 2009-05-17 | AT45 | A | 69,20 | 70,40 | 79,20 |
| 2009-05-17 | E170 | A | 70,40 | 72,90 | 82,10 |
| 2009-05-17 | B734 | A | 71,80 | 76,20 | 84,10 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-17 | B763 | A | 74,20 | 76,80 | 87,00 |
| 2009-05-17 | E170 | A | 70,10 | 72,30 | 80,10 |
| 2009-05-17 | A319 | A | 72,30 | 75,60 | 82,70 |
| 2009-05-17 | A319 | A | 69,90 | 74,30 | 82,90 |
| 2009-05-17 | E145 | A | 71,40 | 73,70 | 81,40 |
| 2009-05-17 | B734 | A | 71,20 | 73,10 | 83,00 |
| 2009-05-17 | B735 | A | 70,20 | 72,10 | 81,30 |
| 2009-05-17 | AT72 | A | 72,00 | 73,80 | 82,40 |
| 2009-05-17 | AT72 | A | 70,60 | 72,00 | 81,00 |
| 2009-05-17 | E170 | A | 68,50 | 70,80 | 79,70 |
| 2009-05-17 | AT72 | A | 72,50 | 75,50 | 83,60 |
| 2009-05-17 | E170 | A | 70,20 | 72,00 | 80,60 |
| 2009-05-17 | E170 | A | 69,50 | 71,70 | 80,30 |
| 2009-05-17 | E170 | A | 69,20 | 71,00 | 80,40 |
| 2009-05-17 | AT45 | A | 70,20 | 71,90 | 81,30 |
| 2009-05-17 | A319 | A | 71,80 | 74,40 | 84,30 |
| 2009-05-17 | P180 | A | 74,10 | 77,50 | 88,40 |
| 2009-05-17 | A320 | A | 70,20 | 72,50 | 81,60 |
| 2009-05-17 | B738 | A | 71,50 | 73,40 | 82,60 |
| 2009-05-17 | MD82 | A | 69,20 | 70,70 | 79,90 |
| 2009-05-17 | B734 | A | 70,90 | 73,10 | 80,90 |
| 2009-05-17 | A320 | A | 69,10 | 70,60 | 79,50 |
| 2009-05-17 | RJ1H | A | 71,60 | 73,80 | 81,60 |
| 2009-05-17 | A320 | A | 72,70 | 75,50 | 83,90 |
| 2009-05-17 | A320 | A | 69,10 | 71,40 | 80,30 |
| 2009-05-17 | B735 | A | 70,50 | 71,70 | 80,90 |
| 2009-05-17 | A319 | A | 71,00 | 73,30 | 82,40 |
| 2009-05-17 | B735 | A | 71,00 | 73,30 | 81,80 |
| 2009-05-17 | AT72 | A | 72,30 | 74,60 | 83,40 |
| 2009-05-17 | B734 | A | 72,80 | 76,20 | 83,60 |
| 2009-05-17 | DH8D | A | 71,60 | 73,40 | 82,00 |
| 2009-05-17 | B733 | A | 71,80 | 74,60 | 82,20 |
| 2009-05-17 | B735 | A | 71,00 | 74,50 | 81,80 |
| 2009-05-17 | AT72 | A | 72,00 | 75,20 | 83,50 |
| 2009-05-17 | AT45 | A | 69,80 | 71,10 | 80,30 |
| 2009-05-17 | E190 | A | 74,50 | 77,30 | 86,00 |
| 2009-05-17 | CRJ7 | A | 70,50 | 72,60 | 81,30 |
| 2009-05-17 | E170 | A | 69,50 | 70,70 | 79,50 |
| 2009-05-17 | E170 | A | 68,60 | 69,90 | 79,00 |
| 2009-05-17 | B735 | A | 69,90 | 71,50 | 80,70 |
| 2009-05-17 | E170 | A | 70,60 | 72,10 | 81,10 |
| 2009-05-17 | A320 | A | 71,20 | 73,10 | 82,00 |
| 2009-05-17 | B734 | A | 70,80 | 72,30 | 81,90 |
| 2009-05-17 | B752 | A | 72,20 | 74,40 | 83,60 |
| 2009-05-17 | B737 | A | 71,40 | 73,40 | 82,60 |
| 2009-05-17 | AT72 | A | 72,20 | 74,30 | 83,30 |
| 2009-05-17 | E170 | A | 69,50 | 71,30 | 79,50 |
| 2009-05-17 | AT45 | A | 69,50 | 70,80 | 80,00 |
| 2009-05-17 | E170 | A | 69,10 | 71,20 | 79,50 |
| 2009-05-17 | E170 | A | 69,10 | 70,50 | 79,10 |
| 2009-05-17 | E170 | A | 69,10 | 70,50 | 79,50 |
| 2009-05-17 | AT72 | A | 72,60 | 75,40 | 84,70 |
| 2009-05-17 | B734 | A | 72,40 | 75,00 | 82,80 |
| 2009-05-17 | B733 | A | 71,30 | 72,90 | 81,80 |
| 2009-05-17 | B733 | A | 70,40 | 71,60 | 80,40 |
| 2009-05-17 | B735 | A | 70,30 | 72,40 | 81,50 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-17 | AT72 | A | 71,90 | 73,30 | 82,70 |
| 2009-05-18 | A320 | D | 68,80 | 70,80 | 80,60 |
| 2009-05-18 | E190 | D | 69,20 | 73,00 | 82,70 |
| 2009-05-18 | F100 | D | 69,10 | 72,80 | 81,90 |
| 2009-05-18 | B738 | D | 69,10 | 71,70 | 80,20 |
| 2009-05-18 | A320 | D | 68,10 | 69,60 | 78,60 |
| 2009-05-18 | A320 | D | 69,00 | 70,30 | 79,40 |
| 2009-05-18 | B734 | D | 71,10 | 74,70 | 83,90 |
| 2009-05-18 | E170 | D | 67,30 | 69,00 | 77,70 |
| 2009-05-18 | B735 | D | 69,50 | 73,30 | 81,60 |
| 2009-05-18 | B735 | D | 68,60 | 70,50 | 79,00 |
| 2009-05-18 | B733 | D | 68,70 | 71,30 | 79,10 |
| 2009-05-18 | A319 | D | 69,80 | 73,10 | 81,20 |
| 2009-05-18 | A320 | D | 68,20 | 69,80 | 80,30 |
| 2009-05-18 | A320 | D | 69,40 | 73,50 | 81,40 |
| 2009-05-18 | B763 | D | 71,30 | 74,40 | 83,00 |
| 2009-05-18 | B763 | D | 70,10 | 73,10 | 82,90 |
| 2009-05-18 | B738 | D | 70,10 | 73,10 | 81,90 |
| 2009-05-18 | A320 | D | 69,10 | 72,30 | 80,20 |
| 2009-05-18 | B733 | D | 70,70 | 72,80 | 81,10 |
| 2009-05-18 | B738 | D | 69,30 | 70,80 | 80,50 |
| 2009-05-18 | B733 | D | 69,20 | 71,80 | 79,60 |
| 2009-05-18 | P180 | D | 68,40 | 70,90 | 78,40 |
| 2009-05-18 | B763 | D | 71,40 | 74,00 | 84,40 |
| 2009-05-19 | B733 | A | 72,30 | 74,00 | 82,70 |
| 2009-05-19 | E170 | A | 69,50 | 71,20 | 79,50 |
| 2009-05-19 | AT45 | A | 70,40 | 72,20 | 82,10 |
| 2009-05-19 | E145 | A | 68,60 | 69,40 | 78,60 |
| 2009-05-19 | AT72 | A | 70,30 | 71,60 | 81,10 |
| 2009-05-19 | AT72 | A | 71,90 | 73,90 | 83,30 |
| 2009-05-19 | AT43 | A | 71,80 | 73,90 | 84,10 |
| 2009-05-19 | AT72 | A | 68,90 | 70,50 | 80,90 |
| 2009-05-19 | RJ85 | A | 69,10 | 71,00 | 79,60 |
| 2009-05-19 | B736 | A | 69,30 | 71,20 | 80,10 |
| 2009-05-19 | B738 | A | 72,00 | 74,80 | 83,50 |
| 2009-05-19 | A319 | A | 71,10 | 73,60 | 81,60 |
| 2009-05-19 | B738 | A | 70,80 | 73,30 | 82,20 |
| 2009-05-19 | PC12 | A | 68,90 | 70,40 | 79,40 |
| 2009-05-19 | YK40 | A | 70,50 | 73,70 | 80,50 |
| 2009-05-19 | B735 | A | 71,50 | 76,60 | 82,60 |
| 2009-05-19 | B738 | A | 71,20 | 74,20 | 82,30 |
| 2009-05-19 | A319 | A | 70,20 | 72,50 | 80,20 |
| 2009-05-19 | B763 | A | 73,00 | 76,20 | 84,80 |
| 2009-05-19 | AT72 | A | 69,00 | 70,80 | 80,80 |
| 2009-05-19 | B733 | A | 73,20 | 76,70 | 84,60 |
| 2009-05-19 | AT72 | A | 67,70 | 68,50 | 78,10 |
| 2009-05-19 | A320 | A | 70,30 | 72,20 | 81,40 |
| 2009-05-19 | B735 | A | 71,20 | 74,10 | 81,60 |
| 2009-05-19 | AT72 | A | 70,70 | 72,00 | 82,50 |
| 2009-05-19 | AT45 | A | 69,90 | 72,00 | 81,10 |
| 2009-05-19 | E170 | A | 69,20 | 71,00 | 79,20 |
| 2009-05-19 | E170 | A | 67,90 | 70,50 | 79,90 |
| 2009-05-19 | A320 | A | 69,80 | 72,10 | 80,60 |
| 2009-05-19 | A320 | A | 69,90 | 71,70 | 80,30 |
| 2009-05-19 | E170 | A | 68,80 | 70,80 | 80,90 |
| 2009-05-19 | B734 | A | 72,80 | 76,70 | 84,30 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-19 | AT72 | A | 72,90 | 75,20 | 84,70 |
| 2009-05-19 | AT45 | A | 69,80 | 71,00 | 79,80 |
| 2009-05-19 | A321 | A | 70,40 | 72,20 | 81,90 |
| 2009-05-19 | B735 | A | 71,50 | 75,40 | 82,90 |
| 2009-05-19 | A321 | A | 72,30 | 74,70 | 83,40 |
| 2009-05-19 | E170 | A | 69,20 | 71,00 | 80,00 |
| 2009-05-19 | B734 | A | 72,00 | 74,30 | 82,80 |
| 2009-05-19 | A320 | A | 69,70 | 71,20 | 80,10 |
| 2009-05-19 | A319 | A | 70,30 | 74,30 | 81,80 |
| 2009-05-19 | AT72 | A | 73,30 | 75,50 | 85,30 |
| 2009-05-19 | A320 | A | 70,00 | 72,20 | 81,20 |
| 2009-05-19 | B735 | A | 72,10 | 75,60 | 82,90 |
| 2009-05-19 | B733 | A | 72,40 | 75,10 | 83,20 |
| 2009-05-19 | AT72 | A | 71,40 | 73,80 | 83,50 |
| 2009-05-19 | AT45 | A | 68,80 | 70,30 | 79,50 |
| 2009-05-19 | E170 | A | 70,90 | 72,70 | 81,40 |
| 2009-05-19 | B733 | A | 71,20 | 72,70 | 81,60 |
| 2009-05-19 | AT72 | A | 72,60 | 74,20 | 84,40 |
| 2009-05-19 | E170 | A | 69,40 | 71,30 | 80,20 |
| 2009-05-19 | A320 | A | 70,00 | 71,20 | 80,40 |
| 2009-05-19 | A320 | A | 71,00 | 73,30 | 82,20 |
| 2009-05-19 | A319 | A | 70,00 | 72,00 | 81,20 |
| 2009-05-19 | CRJ2 | A | 68,80 | 70,80 | 79,20 |
| 2009-05-19 | B735 | A | 72,60 | 76,10 | 83,00 |
| 2009-05-19 | B738 | A | 70,50 | 72,30 | 81,30 |
| 2009-05-19 | AT72 | A | 72,50 | 75,50 | 85,10 |
| 2009-05-19 | E170 | A | 69,20 | 70,80 | 79,60 |
| 2009-05-19 | B763 | A | 72,50 | 74,80 | 84,50 |
| 2009-05-19 | AT45 | A | 70,20 | 72,00 | 81,00 |
| 2009-05-19 | AT72 | A | 70,10 | 71,80 | 80,50 |
| 2009-05-19 | A320 | A | 72,20 | 74,70 | 83,30 |
| 2009-05-19 | B735 | A | 71,40 | 74,70 | 82,20 |
| 2009-05-19 | AT72 | A | 71,70 | 73,80 | 84,00 |
| 2009-05-19 | A320 | A | 71,20 | 73,60 | 81,60 |
| 2009-05-19 | E170 | A | 68,70 | 70,70 | 79,20 |
| 2009-05-19 | AT72 | A | 70,70 | 73,30 | 82,10 |
| 2009-05-19 | A319 | A | 69,00 | 70,80 | 79,40 |
| 2009-05-19 | B735 | A | 71,00 | 74,10 | 81,40 |
| 2009-05-19 | AT72 | A | 70,70 | 72,70 | 81,80 |
| 2009-05-19 | B735 | A | 71,80 | 74,40 | 82,20 |
| 2009-05-19 | B738 | A | 70,80 | 73,90 | 83,40 |
| 2009-05-19 | AT45 | A | 70,30 | 71,70 | 80,80 |
| 2009-05-19 | E170 | A | 69,20 | 71,00 | 79,20 |
| 2009-05-19 | E170 | A | 69,40 | 71,20 | 80,90 |
| 2009-05-19 | AT72 | A | 72,40 | 75,10 | 85,00 |
| 2009-05-19 | E170 | A | 70,00 | 72,40 | 80,40 |
| 2009-05-19 | A320 | A | 69,80 | 71,60 | 80,60 |
| 2009-05-19 | RJ85 | A | 71,20 | 73,00 | 81,20 |
| 2009-05-19 | CRJ9 | A | 68,30 | 69,60 | 79,10 |
| 2009-05-19 | AT45 | A | 69,90 | 71,90 | 80,70 |
| 2009-05-19 | B737 | A | 71,30 | 72,70 | 82,10 |
| 2009-05-19 | P180 | A | 73,50 | 76,80 | 86,70 |
| 2009-05-19 | E170 | A | 71,00 | 73,40 | 82,10 |
| 2009-05-19 | RJ85 | A | 69,00 | 71,00 | 79,40 |
| 2009-05-19 | AT72 | A | 71,70 | 73,20 | 83,20 |
| 2009-05-19 | A321 | A | 71,20 | 73,40 | 82,00 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-19 | B738 | A | 71,20 | 74,30 | 83,80 |
| 2009-05-19 | A320 | A | 69,40 | 72,60 | 83,40 |
| 2009-05-19 | B752 | A | 72,80 | 74,60 | 84,50 |
| 2009-05-19 | B735 | A | 70,80 | 72,30 | 81,50 |
| 2009-05-19 | A318 | A | 69,80 | 72,50 | 80,60 |
| 2009-05-19 | AT72 | A | 71,30 | 73,60 | 82,40 |
| 2009-05-19 | E190 | A | 70,40 | 72,60 | 81,20 |
| 2009-05-19 | AT72 | A | 70,60 | 71,90 | 80,60 |
| 2009-05-19 | E170 | A | 69,60 | 71,40 | 81,10 |
| 2009-05-19 | E145 | A | 68,40 | 72,40 | 81,40 |
| 2009-05-19 | B734 | A | 72,70 | 77,90 | 85,00 |
| 2009-05-19 | E170 | A | 69,90 | 72,90 | 81,70 |
| 2009-05-19 | DH8D | A | 71,60 | 74,30 | 83,30 |
| 2009-05-19 | AT72 | A | 73,40 | 76,60 | 84,90 |
| 2009-05-19 | AT72 | A | 71,70 | 74,20 | 82,50 |
| 2009-05-19 | E170 | A | 70,80 | 73,20 | 82,00 |
| 2009-05-19 | F100 | A | 69,40 | 71,10 | 79,40 |
| 2009-05-19 | AT45 | A | 69,50 | 72,00 | 80,30 |
| 2009-05-19 | B738 | A | 71,50 | 73,60 | 83,00 |
| 2009-05-19 | B735 | A | 72,60 | 75,20 | 83,40 |
| 2009-05-19 | B733 | A | 73,30 | 77,60 | 86,80 |
| 2009-05-19 | B738 | A | 72,40 | 75,30 | 83,90 |
| 2009-05-19 | MD11 | A | 77,40 | 81,90 | 91,20 |
| 2009-05-19 | B735 | A | 72,00 | 75,30 | 83,50 |
| 2009-05-19 | B737 | A | 71,10 | 73,30 | 82,20 |
| 2009-05-19 | E170 | A | 69,50 | 71,60 | 80,60 |
| 2009-05-19 | A320 | A | 71,00 | 73,30 | 82,20 |
| 2009-05-19 | B735 | A | 71,50 | 74,10 | 82,30 |
| 2009-05-19 | B734 | A | 73,10 | 76,50 | 84,90 |
| 2009-05-19 | B735 | A | 71,00 | 72,70 | 82,10 |
| 2009-05-19 | E170 | A | 69,30 | 71,10 | 79,70 |
| 2009-05-19 | B738 | A | 71,20 | 73,90 | 82,70 |
| 2009-05-19 | AT72 | A | 72,70 | 74,70 | 84,10 |
| 2009-05-19 | T154 | A | 73,70 | 77,00 | 86,00 |
| 2009-05-19 | B462 | A | 68,60 | 69,50 | 78,60 |
| 2009-05-19 | B737 | A | 70,30 | 73,30 | 82,90 |
| 2009-05-19 | E170 | A | 68,90 | 70,60 | 79,70 |
| 2009-05-19 | B735 | A | 71,80 | 74,80 | 83,20 |
| 2009-05-19 | E170 | A | 69,30 | 71,30 | 80,10 |
| 2009-05-19 | B733 | A | 73,60 | 78,30 | 84,40 |
| 2009-05-19 | B738 | A | 70,80 | 72,80 | 82,30 |
| 2009-05-19 | E170 | A | 69,00 | 70,90 | 80,20 |
| 2009-05-19 | AT45 | A | 69,40 | 71,30 | 80,60 |
| 2009-05-19 | AT72 | A | 72,30 | 75,10 | 83,80 |
| 2009-05-19 | E170 | A | 69,80 | 71,80 | 79,80 |
| 2009-05-19 | AT72 | A | 72,10 | 74,00 | 83,20 |
| 2009-05-20 | B462 | A | 69,80 | 70,80 | 79,80 |
| 2009-05-20 | E170 | A | 69,40 | 71,20 | 79,80 |
| 2009-05-20 | AT72 | A | 71,80 | 73,90 | 83,30 |
| 2009-05-20 | AT72 | A | 70,60 | 72,60 | 81,70 |
| 2009-05-20 | B733 | A | 70,20 | 71,80 | 81,40 |
| 2009-05-20 | B734 | A | 73,50 | 77,60 | 85,00 |
| 2009-05-20 | A320 | A | 70,80 | 73,40 | 82,20 |
| 2009-05-20 | AT43 | A | 68,80 | 69,60 | 79,20 |
| 2009-05-20 | B734 | A | 73,40 | 76,50 | 83,90 |
| 2009-05-20 | AT72 | A | 72,30 | 75,00 | 84,30 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-20 | AT72 | A | 70,70 | 72,40 | 82,20 |
| 2009-05-20 | RJ85 | A | 68,20 | 69,10 | 78,20 |
| 2009-05-20 | B735 | A | 70,10 | 72,20 | 81,60 |
| 2009-05-20 | B736 | A | 70,30 | 71,70 | 81,40 |
| 2009-05-20 | B763 | A | 72,20 | 74,40 | 84,50 |
| 2009-05-20 | B738 | A | 72,20 | 75,00 | 83,30 |
| 2009-05-20 | B738 | A | 73,30 | 75,70 | 84,70 |
| 2009-05-20 | RJ85 | A | 71,80 | 73,90 | 82,60 |
| 2009-05-20 | A320 | A | 73,20 | 76,00 | 85,50 |
| 2009-05-20 | F100 | A | 69,60 | 71,50 | 79,60 |
| 2009-05-20 | E170 | A | 69,50 | 71,40 | 80,30 |
| 2009-05-20 | E170 | A | 68,20 | 69,20 | 78,20 |
| 2009-05-20 | B763 | A | 70,10 | 72,80 | 82,60 |
| 2009-05-20 | A319 | A | 71,00 | 73,00 | 81,00 |
| 2009-05-20 | MD82 | A | 69,60 | 72,50 | 80,40 |
| 2009-05-20 | A320 | A | 66,90 | 67,40 | 76,90 |
| 2009-05-20 | E170 | A | 69,70 | 72,10 | 80,90 |
| 2009-05-20 | B735 | A | 71,20 | 74,70 | 82,00 |
| 2009-05-20 | AT72 | A | 69,10 | 71,10 | 80,30 |
| 2009-05-20 | AT72 | A | 68,80 | 71,10 | 80,00 |
| 2009-05-20 | AT72 | A | 70,80 | 73,70 | 81,20 |
| 2009-05-20 | A320 | A | 70,70 | 72,50 | 81,90 |
| 2009-05-20 | A319 | A | 69,80 | 70,90 | 80,30 |
| 2009-05-20 | B734 | A | 72,60 | 76,20 | 83,00 |
| 2009-05-20 | B734 | A | 69,40 | 71,40 | 80,90 |
| 2009-05-20 | B738 | A | 70,10 | 72,70 | 81,30 |
| 2009-05-20 | B735 | A | 71,40 | 77,40 | 85,70 |
| 2009-05-20 | YK40 | A | 67,80 | 70,90 | 80,10 |
| 2009-05-20 | B738 | A | 70,50 | 72,90 | 81,60 |
| 2009-05-20 | B735 | A | 70,50 | 71,50 | 80,50 |
| 2009-05-20 | B733 | A | 72,60 | 75,30 | 83,40 |
| 2009-05-20 | B738 | A | 69,00 | 72,10 | 81,80 |
| 2009-05-20 | A320 | A | 70,10 | 72,00 | 81,80 |
| 2009-05-20 | B735 | A | 70,70 | 75,00 | 82,50 |
| 2009-05-20 | E170 | A | 70,80 | 72,90 | 80,80 |
| 2009-05-20 | B738 | A | 73,00 | 76,90 | 85,30 |
| 2009-05-20 | A321 | A | 70,10 | 72,40 | 80,90 |
| 2009-05-20 | AT72 | A | 69,10 | 70,80 | 79,90 |
| 2009-05-20 | B763 | A | 71,90 | 76,20 | 85,30 |
| 2009-05-20 | B734 | A | 71,60 | 74,80 | 83,70 |
| 2009-05-20 | B733 | A | 71,00 | 73,60 | 81,50 |
| 2009-05-20 | A319 | A | 68,70 | 70,50 | 79,10 |
| 2009-05-20 | A320 | A | 71,90 | 73,30 | 82,70 |
| 2009-05-20 | A320 | A | 69,40 | 70,70 | 80,60 |
| 2009-05-20 | B734 | A | 77,40 | 82,10 | 88,20 |
| 2009-05-20 | F100 | A | 68,40 | 70,10 | 79,60 |
| 2009-05-20 | B738 | A | 69,90 | 72,00 | 81,00 |
| 2009-05-20 | B734 | A | 72,80 | 75,20 | 83,20 |
| 2009-05-20 | DH8D | A | 66,00 | 69,40 | 79,60 |
| 2009-05-20 | DH8D | A | 68,10 | 70,20 | 78,90 |
| 2009-05-20 | A320 | A | 68,80 | 70,20 | 79,60 |
| 2009-05-20 | B738 | A | 69,10 | 71,00 | 79,10 |
| 2009-05-20 | AT72 | A | 69,40 | 71,50 | 80,20 |
| 2009-05-20 | B734 | A | 70,20 | 71,90 | 80,60 |
| 2009-05-20 | AT72 | A | 71,10 | 73,40 | 81,90 |
| 2009-05-20 | E170 | A | 69,20 | 71,80 | 80,30 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-20 | A320 | A | 71,50 | 74,20 | 81,90 |
| 2009-05-20 | YK40 | A | 70,60 | 73,40 | 80,60 |
| 2009-05-20 | CRJ9 | A | 69,90 | 72,10 | 79,90 |
| 2009-05-20 | B734 | A | 72,30 | 75,30 | 83,10 |
| 2009-05-20 | A321 | A | 70,40 | 71,90 | 80,80 |
| 2009-05-20 | A320 | A | 69,50 | 71,20 | 80,00 |
| 2009-05-20 | A318 | A | 70,10 | 71,70 | 80,90 |
| 2009-05-20 | E190 | A | 70,90 | 72,60 | 81,70 |
| 2009-05-20 | A320 | A | 69,20 | 71,10 | 79,60 |
| 2009-05-20 | B735 | A | 69,50 | 71,70 | 80,30 |
| 2009-05-20 | AT72 | A | 70,90 | 72,40 | 81,70 |
| 2009-05-20 | MD11 | A | 75,90 | 80,30 | 89,10 |
| 2009-05-20 | B734 | A | 70,60 | 72,40 | 81,00 |
| 2009-05-20 | AT72 | A | 69,80 | 71,20 | 80,30 |
| 2009-05-20 | B735 | A | 72,50 | 75,50 | 82,50 |
| 2009-05-20 | B735 | A | 71,80 | 73,80 | 81,80 |
| 2009-05-20 | B733 | A | 71,50 | 75,10 | 81,50 |
| 2009-05-20 | AT72 | A | 72,00 | 73,80 | 83,80 |
| 2009-05-20 | B736 | A | 70,90 | 72,90 | 82,00 |
| 2009-05-20 | B734 | A | 70,90 | 72,70 | 81,30 |
| 2009-05-20 | B737 | A | 70,10 | 71,80 | 80,10 |
| 2009-05-20 | E170 | A | 70,10 | 71,60 | 80,10 |
| 2009-05-20 | A320 | A | 70,30 | 71,60 | 80,30 |
| 2009-05-20 | B734 | A | 72,10 | 75,10 | 82,50 |
| 2009-05-20 | B735 | A | 69,00 | 70,40 | 79,40 |
| 2009-05-20 | E170 | A | 70,70 | 72,10 | 81,50 |
| 2009-05-20 | E170 | A | 69,00 | 70,70 | 79,00 |
| 2009-05-20 | B735 | A | 70,90 | 72,70 | 80,90 |
| 2009-05-20 | B733 | A | 72,20 | 74,70 | 83,00 |
| 2009-05-20 | A321 | A | 71,60 | 74,20 | 82,40 |
| 2009-05-20 | E170 | A | 69,50 | 70,80 | 79,50 |
| 2009-05-20 | B735 | A | 71,90 | 74,60 | 81,90 |
| 2009-05-20 | B734 | A | 72,80 | 76,00 | 84,20 |
| 2009-05-20 | E170 | A | 69,50 | 70,90 | 79,90 |
| 2009-05-20 | B735 | A | 71,60 | 74,30 | 82,00 |
| 2009-05-20 | AT72 | A | 71,20 | 73,30 | 81,90 |
| 2009-05-20 | AT72 | A | 70,50 | 72,60 | 82,30 |
| 2009-05-20 | AT72 | A | 70,40 | 72,00 | 81,90 |
| 2009-05-21 | A320 | A | 73,50 | 77,00 | 85,80 |
| 2009-05-21 | B733 | A | 71,00 | 72,60 | 81,40 |
| 2009-05-21 | AT72 | A | 70,00 | 72,10 | 82,30 |
| 2009-05-21 | AT72 | A | 71,90 | 73,70 | 83,40 |
| 2009-05-21 | E170 | A | 69,90 | 71,60 | 79,90 |
| 2009-05-21 | C295 | A | 70,80 | 73,20 | 81,60 |
| 2009-05-21 | AT43 | A | 69,00 | 71,50 | 80,20 |
| 2009-05-21 | A320 | A | 70,70 | 73,00 | 81,50 |
| 2009-05-21 | B734 | A | 72,80 | 76,40 | 83,20 |
| 2009-05-21 | AT72 | A | 70,20 | 71,30 | 80,20 |
| 2009-05-21 | B735 | A | 69,50 | 71,10 | 79,50 |
| 2009-05-21 | RJ85 | A | 69,70 | 71,60 | 79,70 |
| 2009-05-21 | CRJ2 | A | 68,90 | 70,60 | 79,70 |
| 2009-05-21 | B763 | A | 72,60 | 74,70 | 84,30 |
| 2009-05-21 | A321 | A | 72,10 | 74,60 | 83,20 |
| 2009-05-21 | B734 | A | 71,70 | 74,90 | 82,50 |
| 2009-05-21 | B736 | A | 71,10 | 74,30 | 82,20 |
| 2009-05-21 | AT72 | A | 71,30 | 75,30 | 83,90 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-21 | A320 | A | 70,60 | 72,80 | 81,00 |
| 2009-05-21 | E190 | A | 68,80 | 70,60 | 79,60 |
| 2009-05-21 | T154 | A | 77,40 | 83,00 | 89,70 |
| 2009-05-21 | A319 | A | 70,50 | 73,80 | 83,30 |
| 2009-05-21 | B763 | A | 72,80 | 75,20 | 84,80 |
| 2009-05-21 | A319 | A | 71,70 | 74,20 | 83,40 |
| 2009-05-21 | E170 | A | 69,90 | 71,70 | 79,90 |
| 2009-05-21 | CRJ9 | A | 69,00 | 70,80 | 79,80 |
| 2009-05-21 | E170 | A | 71,40 | 73,20 | 81,80 |
| 2009-05-21 | E170 | A | 69,10 | 70,10 | 79,10 |
| 2009-05-21 | E170 | A | 70,90 | 72,50 | 81,70 |
| 2009-05-21 | B735 | A | 72,80 | 75,90 | 83,60 |
| 2009-05-21 | AT45 | A | 68,60 | 69,40 | 79,10 |
| 2009-05-21 | AT72 | A | 70,20 | 72,10 | 82,00 |
| 2009-05-21 | A321 | A | 70,90 | 73,40 | 82,70 |
| 2009-05-21 | A320 | A | 70,10 | 71,70 | 80,50 |
| 2009-05-21 | B734 | A | 72,80 | 77,50 | 85,10 |
| 2009-05-21 | B738 | A | 71,30 | 74,00 | 82,50 |
| 2009-05-21 | A320 | A | 70,80 | 72,40 | 81,20 |
| 2009-05-21 | A320 | A | 69,80 | 71,80 | 80,60 |
| 2009-05-21 | AT72 | A | 70,30 | 71,80 | 81,50 |
| 2009-05-21 | B735 | A | 70,60 | 72,80 | 81,00 |
| 2009-05-21 | B733 | A | 72,00 | 73,70 | 82,80 |
| 2009-05-21 | E170 | A | 70,20 | 72,10 | 80,60 |
| 2009-05-21 | A321 | A | 71,50 | 73,60 | 81,90 |
| 2009-05-21 | B735 | A | 69,80 | 71,40 | 80,60 |
| 2009-05-21 | A319 | A | 69,80 | 72,60 | 81,00 |
| 2009-05-21 | E170 | A | 69,70 | 71,40 | 80,10 |
| 2009-05-21 | A320 | A | 70,40 | 72,30 | 81,10 |
| 2009-05-21 | AT45 | A | 69,50 | 70,50 | 80,30 |
| 2009-05-21 | AT72 | A | 72,70 | 74,70 | 84,10 |
| 2009-05-21 | E170 | A | 71,90 | 74,00 | 81,90 |
| 2009-05-21 | E170 | A | 70,10 | 71,30 | 80,10 |
| 2009-05-21 | E190 | A | 70,40 | 72,10 | 80,80 |
| 2009-05-21 | B735 | A | 71,60 | 73,90 | 82,70 |
| 2009-05-21 | AT72 | A | 71,30 | 73,60 | 82,40 |
| 2009-05-21 | B733 | A | 73,50 | 76,40 | 85,30 |
| 2009-05-21 | B734 | A | 71,80 | 73,90 | 82,60 |
| 2009-05-21 | E170 | A | 70,10 | 72,30 | 80,10 |
| 2009-05-21 | B733 | A | 68,30 | 70,00 | 79,80 |
| 2009-05-21 | A320 | A | 70,90 | 72,30 | 82,40 |
| 2009-05-21 | B735 | A | 70,00 | 72,40 | 80,40 |
| 2009-05-21 | AT72 | A | 71,50 | 73,10 | 83,30 |
| 2009-05-21 | F100 | A | 69,10 | 70,50 | 79,50 |
| 2009-05-21 | E170 | A | 68,50 | 69,90 | 78,50 |
| 2009-05-21 | B763 | A | 72,00 | 74,10 | 83,80 |
| 2009-05-21 | AT72 | A | 72,50 | 74,70 | 84,30 |
| 2009-05-21 | B763 | A | 71,10 | 75,10 | 83,20 |
| 2009-05-21 | B763 | A | 72,30 | 75,80 | 84,30 |
| 2009-05-21 | A320 | A | 69,90 | 72,20 | 81,90 |
| 2009-05-21 | A320 | A | 69,10 | 71,50 | 79,60 |
| 2009-05-21 | AT72 | A | 72,20 | 74,50 | 84,30 |
| 2009-05-21 | AT72 | A | 73,00 | 76,20 | 84,40 |
| 2009-05-21 | B734 | A | 71,70 | 74,90 | 81,70 |
| 2009-05-21 | E170 | A | 68,40 | 69,40 | 78,40 |
| 2009-05-21 | AT72 | A | 72,70 | 74,60 | 83,80 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-21 | E170 | A | 69,40 | 71,50 | 79,40 |
| 2009-05-21 | A320 | A | 69,10 | 70,10 | 79,10 |
| 2009-05-21 | B735 | D | 68,00 | 69,30 | 78,00 |
| 2009-05-21 | B763 | D | 71,20 | 73,90 | 83,50 |
| 2009-05-21 | T154 | D | 72,70 | 76,30 | 84,50 |
| 2009-05-22 | AT45 | A | 71,00 | 73,20 | 82,20 |
| 2009-05-22 | E170 | A | 69,00 | 71,20 | 80,70 |
| 2009-05-22 | E170 | A | 69,80 | 71,40 | 80,60 |
| 2009-05-22 | B733 | A | 72,20 | 75,10 | 83,00 |
| 2009-05-22 | E170 | A | 70,10 | 72,10 | 80,90 |
| 2009-05-22 | AT72 | A | 73,10 | 75,40 | 84,90 |
| 2009-05-22 | E170 | A | 70,30 | 72,30 | 81,10 |
| 2009-05-22 | AT45 | A | 70,60 | 73,60 | 82,40 |
| 2009-05-22 | AT43 | A | 73,10 | 76,10 | 83,80 |
| 2009-05-22 | AT45 | A | 68,70 | 70,40 | 81,50 |
| 2009-05-22 | B733 | A | 71,80 | 74,90 | 83,50 |
| 2009-05-22 | AT72 | A | 69,40 | 70,50 | 79,40 |
| 2009-05-22 | B734 | A | 71,90 | 74,90 | 82,70 |
| 2009-05-22 | B738 | A | 70,50 | 73,90 | 83,10 |
| 2009-05-22 | T154 | A | 74,70 | 79,40 | 88,70 |
| 2009-05-22 | A320 | A | 71,50 | 74,10 | 82,60 |
| 2009-05-22 | CRJ2 | A | 68,50 | 70,60 | 79,60 |
| 2009-05-22 | B738 | A | 72,20 | 75,30 | 84,50 |
| 2009-05-22 | B735 | A | 72,50 | 74,60 | 83,30 |
| 2009-05-22 | A319 | A | 70,70 | 72,80 | 81,90 |
| 2009-05-22 | B763 | A | 72,70 | 75,00 | 85,50 |
| 2009-05-22 | A320 | A | 70,70 | 72,70 | 81,50 |
| 2009-05-22 | B734 | A | 72,70 | 75,20 | 83,50 |
| 2009-05-22 | A319 | A | 70,40 | 72,60 | 81,20 |
| 2009-05-22 | AT72 | A | 73,30 | 76,30 | 85,00 |
| 2009-05-22 | E170 | A | 69,90 | 71,80 | 80,70 |
| 2009-05-22 | AT45 | A | 68,60 | 69,90 | 78,60 |
| 2009-05-22 | AT45 | A | 70,10 | 71,40 | 80,50 |
| 2009-05-22 | AT45 | A | 67,80 | 69,50 | 79,90 |
| 2009-05-22 | B734 | A | 71,30 | 73,70 | 81,70 |
| 2009-05-22 | E170 | A | 68,70 | 70,20 | 79,10 |
| 2009-05-22 | B738 | A | 75,70 | 79,80 | 87,50 |
| 2009-05-22 | AT72 | A | 71,30 | 73,30 | 83,60 |
| 2009-05-22 | B738 | A | 71,40 | 73,30 | 81,80 |
| 2009-05-22 | A320 | A | 70,10 | 71,70 | 80,90 |
| 2009-05-22 | E170 | A | 68,60 | 71,30 | 80,30 |
| 2009-05-22 | A321 | A | 72,10 | 75,60 | 83,80 |
| 2009-05-22 | AT72 | A | 73,00 | 75,80 | 85,10 |
| 2009-05-22 | E170 | A | 69,50 | 71,00 | 79,50 |
| 2009-05-22 | A320 | A | 70,70 | 73,10 | 80,70 |
| 2009-05-22 | B737 | A | 71,80 | 74,70 | 82,60 |
| 2009-05-22 | B734 | A | 70,60 | 71,90 | 81,00 |
| 2009-05-22 | AT72 | A | 73,10 | 75,90 | 84,90 |
| 2009-05-22 | A320 | A | 70,70 | 73,00 | 81,10 |
| 2009-05-22 | A319 | A | 71,20 | 75,40 | 82,00 |
| 2009-05-22 | B733 | A | 71,40 | 74,10 | 81,80 |
| 2009-05-22 | B735 | A | 72,10 | 74,20 | 82,10 |
| 2009-05-22 | E170 | A | 69,70 | 71,50 | 80,10 |
| 2009-05-22 | B735 | A | 70,80 | 72,80 | 81,20 |
| 2009-05-22 | E190 | A | 70,40 | 72,00 | 81,20 |
| 2009-05-22 | YK40 | A | 72,40 | 75,00 | 82,40 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-22 | AT72 | A | 71,30 | 74,10 | 83,90 |
| 2009-05-22 | A320 | A | 71,40 | 73,40 | 81,40 |
| 2009-05-22 | RJ85 | A | 69,30 | 70,60 | 79,70 |
| 2009-05-22 | B738 | A | 71,60 | 73,70 | 82,40 |
| 2009-05-22 | B752 | A | 69,80 | 71,70 | 81,60 |
| 2009-05-22 | B733 | A | 73,50 | 76,60 | 84,30 |
| 2009-05-22 | AT72 | A | 71,80 | 74,60 | 84,10 |
| 2009-05-22 | A320 | A | 70,10 | 71,70 | 80,50 |
| 2009-05-22 | PC12 | A | 69,40 | 71,40 | 79,80 |
| 2009-05-22 | AT45 | A | 68,80 | 70,20 | 79,60 |
| 2009-05-22 | B763 | A | 72,10 | 74,80 | 85,30 |
| 2009-05-22 | A320 | A | 71,20 | 73,40 | 82,40 |
| 2009-05-22 | A320 | A | 71,60 | 74,20 | 82,70 |
| 2009-05-22 | B735 | A | 69,80 | 71,60 | 81,20 |
| 2009-05-22 | AT72 | A | 71,70 | 73,70 | 82,80 |
| 2009-05-22 | A319 | A | 69,70 | 71,90 | 80,90 |
| 2009-05-22 | AT72 | A | 70,30 | 71,70 | 82,40 |
| 2009-05-22 | A319 | A | 70,30 | 72,30 | 80,70 |
| 2009-05-22 | AT72 | A | 70,60 | 73,60 | 83,10 |
| 2009-05-22 | A320 | A | 70,80 | 73,00 | 81,60 |
| 2009-05-22 | B734 | A | 73,50 | 77,40 | 83,90 |
| 2009-05-22 | E170 | A | 69,40 | 71,50 | 79,40 |
| 2009-05-22 | B735 | A | 70,60 | 72,60 | 81,40 |
| 2009-05-22 | AT72 | A | 72,50 | 74,80 | 84,00 |
| 2009-05-22 | E170 | A | 69,10 | 71,40 | 79,50 |
| 2009-05-22 | B734 | A | 72,50 | 75,30 | 84,00 |
| 2009-05-22 | AT72 | A | 71,90 | 75,00 | 84,90 |
| 2009-05-22 | E170 | A | 69,20 | 71,50 | 80,00 |
| 2009-05-22 | E170 | A | 70,70 | 73,90 | 81,10 |
| 2009-05-22 | E170 | A | 69,90 | 71,50 | 79,90 |
| 2009-05-22 | AT45 | A | 70,00 | 73,40 | 81,50 |
| 2009-05-22 | E170 | A | 69,70 | 73,30 | 81,10 |
| 2009-05-22 | AT45 | A | 70,60 | 72,40 | 81,40 |
| 2009-05-22 | A319 | A | 70,30 | 72,00 | 81,40 |
| 2009-05-22 | B738 | A | 73,20 | 76,90 | 85,00 |
| 2009-05-22 | RJ85 | A | 69,90 | 72,10 | 81,30 |
| 2009-05-22 | A320 | A | 71,20 | 73,00 | 82,70 |
| 2009-05-22 | B734 | A | 72,30 | 75,10 | 83,70 |
| 2009-05-22 | AT72 | A | 68,90 | 70,70 | 79,30 |
| 2009-05-22 | P180 | A | 74,60 | 79,40 | 88,80 |
| 2009-05-22 | A320 | A | 70,70 | 73,50 | 83,20 |
| 2009-05-22 | RJ85 | A | 71,00 | 73,00 | 81,00 |
| 2009-05-22 | A321 | A | 71,10 | 74,20 | 84,10 |
| 2009-05-22 | C295 | A | 70,00 | 72,40 | 80,00 |
| 2009-05-22 | E170 | A | 70,10 | 72,20 | 80,90 |
| 2009-05-22 | A320 | A | 70,60 | 72,20 | 82,40 |
| 2009-05-22 | A318 | A | 70,70 | 72,50 | 82,20 |
| 2009-05-22 | AT72 | A | 70,10 | 71,50 | 80,90 |
| 2009-05-22 | SF34 | A | 68,40 | 70,40 | 78,40 |
| 2009-05-22 | E145 | A | 67,30 | 68,40 | 77,70 |
| 2009-05-22 | E170 | A | 71,30 | 75,70 | 83,60 |
| 2009-05-22 | E170 | A | 69,50 | 71,50 | 81,00 |
| 2009-05-22 | T154 | A | 73,90 | 77,00 | 86,20 |
| 2009-05-22 | E170 | A | 72,60 | 75,20 | 84,40 |
| 2009-05-22 | AT72 | A | 72,00 | 74,40 | 84,60 |
| 2009-05-22 | A319 | A | 70,60 | 73,50 | 82,60 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-22 | MD11 | A | 79,40 | 83,90 | 93,40 |
| 2009-05-22 | DH8D | A | 70,30 | 71,90 | 80,70 |
| 2009-05-22 | B734 | A | 72,80 | 76,10 | 84,20 |
| 2009-05-22 | E145 | A | 68,20 | 69,00 | 78,20 |
| 2009-05-22 | AT72 | A | 71,60 | 73,70 | 83,60 |
| 2009-05-22 | B735 | A | 72,60 | 76,10 | 84,00 |
| 2009-05-22 | E170 | A | 70,40 | 72,40 | 81,20 |
| 2009-05-22 | AT72 | A | 73,50 | 75,90 | 85,60 |
| 2009-05-22 | B736 | A | 70,70 | 73,20 | 82,40 |
| 2009-05-22 | AT72 | A | 73,30 | 75,40 | 84,70 |
| 2009-05-22 | CRJ2 | A | 69,10 | 70,90 | 80,30 |
| 2009-05-22 | F100 | A | 70,10 | 72,20 | 81,30 |
| 2009-05-22 | P180 | A | 72,30 | 76,00 | 86,10 |
| 2009-05-22 | E170 | A | 69,50 | 71,10 | 80,30 |
| 2009-05-22 | AT43 | A | 67,50 | 68,20 | 77,90 |
| 2009-05-22 | B737 | A | 72,70 | 75,30 | 84,40 |
| 2009-05-22 | YK40 | A | 73,60 | 76,70 | 84,40 |
| 2009-05-22 | B735 | A | 71,50 | 75,10 | 83,20 |
| 2009-05-22 | A320 | A | 71,10 | 73,50 | 82,80 |
| 2009-05-22 | E170 | A | 69,50 | 71,30 | 80,30 |
| 2009-05-22 | E170 | A | 70,30 | 72,00 | 80,30 |
| 2009-05-22 | B735 | A | 74,00 | 78,60 | 86,30 |
| 2009-05-22 | E170 | A | 69,70 | 71,30 | 80,90 |
| 2009-05-22 | E170 | A | 69,40 | 71,90 | 81,70 |
| 2009-05-22 | E170 | A | 69,20 | 71,40 | 79,60 |
| 2009-05-22 | B734 | A | 72,40 | 76,40 | 84,70 |
| 2009-05-22 | E170 | A | 69,70 | 71,50 | 80,10 |
| 2009-05-22 | B733 | A | 74,00 | 77,10 | 85,50 |
| 2009-05-22 | AT72 | A | 72,40 | 75,30 | 84,50 |
| 2009-05-22 | B734 | A | 73,40 | 77,30 | 84,90 |
| 2009-05-22 | E170 | A | 70,50 | 72,40 | 81,30 |
| 2009-05-22 | AT72 | A | 74,70 | 77,40 | 86,40 |
| 2009-05-22 | E170 | A | 70,80 | 73,30 | 82,60 |
| 2009-05-22 | B734 | A | 71,50 | 75,10 | 83,30 |
| 2009-05-22 | B752 | A | 72,20 | 76,30 | 86,00 |
| 2009-05-22 | B733 | A | 71,60 | 75,50 | 83,90 |
| 2009-05-22 | AT72 | A | 71,20 | 73,00 | 83,50 |
| 2009-05-23 | E170 | A | 71,20 | 74,50 | 83,50 |
| 2009-05-23 | E170 | A | 70,50 | 72,70 | 82,80 |
| 2009-05-23 | E145 | A | 67,90 | 69,00 | 78,70 |
| 2009-05-23 | E170 | A | 69,70 | 71,70 | 81,70 |
| 2009-05-23 | AT72 | A | 73,10 | 75,70 | 85,90 |
| 2009-05-23 | AT45 | A | 71,40 | 74,10 | 83,40 |
| 2009-05-23 | B734 | A | 72,60 | 76,20 | 84,60 |
| 2009-05-23 | AT72 | A | 72,30 | 74,60 | 84,60 |
| 2009-05-23 | B763 | A | 75,40 | 78,40 | 89,00 |
| 2009-05-23 | B734 | A | 73,30 | 78,40 | 86,50 |
| 2009-05-23 | B737 | A | 70,20 | 72,60 | 82,50 |
| 2009-05-23 | AT45 | A | 69,20 | 71,80 | 81,20 |
| 2009-05-23 | AT72 | A | 69,20 | 71,90 | 81,80 |
| 2009-05-23 | B733 | A | 73,30 | 77,60 | 85,10 |
| 2009-05-23 | B763 | A | 75,20 | 79,20 | 88,70 |
| 2009-05-23 | CRJ2 | A | 69,60 | 73,30 | 81,40 |
| 2009-05-23 | B733 | A | 72,50 | 77,60 | 86,10 |
| 2009-05-23 | CRJ2 | A | 68,90 | 69,90 | 79,60 |
| 2009-05-23 | F100 | A | 69,60 | 71,50 | 80,10 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-23 | E170 | A | 69,90 | 72,10 | 81,90 |
| 2009-05-23 | E170 | A | 70,10 | 73,30 | 81,90 |
| 2009-05-23 | B733 | A | 74,10 | 79,00 | 87,10 |
| 2009-05-23 | AT72 | A | 73,40 | 76,30 | 86,80 |
| 2009-05-23 | B735 | A | 71,60 | 74,10 | 83,70 |
| 2009-05-23 | AT72 | A | 72,40 | 75,50 | 84,10 |
| 2009-05-23 | A320 | A | 73,00 | 76,80 | 85,60 |
| 2009-05-23 | A320 | A | 69,90 | 73,10 | 82,90 |
| 2009-05-23 | E170 | A | 70,20 | 72,30 | 81,30 |
| 2009-05-23 | AT72 | A | 68,90 | 70,90 | 80,70 |
| 2009-05-23 | CRJ2 | A | 69,10 | 70,70 | 79,90 |
| 2009-05-23 | B735 | A | 72,00 | 75,40 | 84,50 |
| 2009-05-23 | AT45 | A | 69,30 | 71,30 | 81,80 |
| 2009-05-23 | A320 | A | 70,10 | 73,30 | 83,30 |
| 2009-05-23 | C295 | A | 71,40 | 73,30 | 81,40 |
| 2009-05-23 | A320 | A | 71,20 | 74,70 | 84,50 |
| 2009-05-23 | A320 | A | 72,10 | 76,90 | 85,90 |
| 2009-05-23 | B735 | A | 71,70 | 73,50 | 84,00 |
| 2009-05-23 | AT72 | A | 71,20 | 73,10 | 83,20 |
| 2009-05-23 | E170 | A | 69,60 | 72,40 | 81,70 |
| 2009-05-23 | B734 | A | 72,60 | 77,90 | 85,20 |
| 2009-05-23 | A320 | A | 71,70 | 74,10 | 84,90 |
| 2009-05-23 | AT72 | A | 71,40 | 75,50 | 85,20 |
| 2009-05-23 | A320 | A | 72,00 | 74,60 | 84,60 |
| 2009-05-23 | E170 | A | 69,90 | 72,60 | 81,60 |
| 2009-05-23 | B733 | A | 72,90 | 76,30 | 84,60 |
| 2009-05-23 | B733 | A | 73,50 | 78,00 | 85,50 |
| 2009-05-23 | E170 | A | 70,40 | 73,40 | 82,20 |
| 2009-05-23 | A320 | A | 71,80 | 76,80 | 84,60 |
| 2009-05-23 | MD83 | A | 73,30 | 76,40 | 86,10 |
| 2009-05-23 | AT45 | A | 71,00 | 73,70 | 83,50 |
| 2009-05-23 | E190 | A | 71,20 | 76,20 | 84,00 |
| 2009-05-23 | B763 | A | 73,40 | 77,80 | 87,40 |
| 2009-05-23 | RJ85 | A | 70,30 | 73,30 | 83,10 |
| 2009-05-23 | B752 | A | 75,80 | 80,60 | 89,80 |
| 2009-05-23 | B763 | A | 73,60 | 78,40 | 88,40 |
| 2009-05-23 | E170 | A | 70,70 | 72,80 | 82,50 |
| 2009-05-23 | E170 | A | 70,80 | 73,20 | 82,80 |
| 2009-05-23 | AT45 | A | 71,40 | 73,50 | 82,10 |
| 2009-05-23 | E170 | A | 70,20 | 72,70 | 81,30 |
| 2009-05-23 | B734 | A | 75,60 | 80,50 | 89,30 |
| 2009-05-23 | E170 | A | 71,40 | 74,30 | 83,10 |
| 2009-05-23 | B735 | A | 72,40 | 76,60 | 84,70 |
| 2009-05-23 | A319 | A | 71,70 | 74,80 | 84,30 |
| 2009-05-23 | E170 | A | 71,30 | 73,30 | 82,70 |
| 2009-05-23 | AT72 | A | 74,00 | 77,90 | 86,80 |
| 2009-05-23 | E170 | A | 72,80 | 77,10 | 84,80 |
| 2009-05-23 | E170 | A | 71,10 | 73,90 | 82,90 |
| 2009-05-23 | E170 | A | 70,90 | 73,40 | 83,20 |
| 2009-05-23 | E145 | A | 68,10 | 69,50 | 78,50 |
| 2009-05-23 | B737 | A | 71,40 | 74,40 | 84,60 |
| 2009-05-23 | E145 | A | 69,70 | 70,70 | 80,10 |
| 2009-05-23 | AT45 | A | 71,20 | 74,30 | 83,50 |
| 2009-05-23 | AT72 | A | 68,40 | 70,80 | 80,70 |
| 2009-05-23 | E170 | A | 71,10 | 74,00 | 83,40 |
| 2009-05-23 | AT72 | A | 70,20 | 73,50 | 82,50 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-23 | E145 | A | 69,30 | 71,20 | 80,10 |
| 2009-05-23 | A320 | A | 71,40 | 74,80 | 85,40 |
| 2009-05-23 | A319 | A | 67,30 | 68,20 | 77,70 |
| 2009-05-23 | B734 | A | 73,70 | 77,70 | 86,50 |
| 2009-05-23 | RJ85 | A | 71,00 | 73,40 | 82,80 |
| 2009-05-23 | B737 | A | 71,80 | 75,40 | 85,20 |
| 2009-05-23 | A320 | A | 72,40 | 75,70 | 84,70 |
| 2009-05-23 | A320 | A | 71,00 | 74,50 | 83,80 |
| 2009-05-23 | B738 | A | 72,70 | 76,10 | 85,70 |
| 2009-05-23 | E170 | A | 70,60 | 72,60 | 82,10 |
| 2009-05-23 | A320 | A | 71,60 | 73,70 | 83,90 |
| 2009-05-23 | A320 | A | 72,00 | 75,30 | 85,00 |
| 2009-05-23 | A318 | A | 71,90 | 74,90 | 83,60 |
| 2009-05-23 | AT45 | A | 71,60 | 73,60 | 83,30 |
| 2009-05-23 | RJ1H | A | 70,10 | 72,40 | 80,90 |
| 2009-05-23 | B735 | A | 71,50 | 72,90 | 82,90 |
| 2009-05-23 | A319 | A | 71,60 | 74,50 | 83,90 |
| 2009-05-23 | DH8D | A | 69,90 | 72,10 | 81,00 |
| 2009-05-23 | B735 | A | 72,70 | 76,60 | 85,20 |
| 2009-05-23 | B735 | A | 72,70 | 76,90 | 84,70 |
| 2009-05-23 | E170 | A | 69,80 | 72,40 | 82,30 |
| 2009-05-23 | E170 | A | 71,30 | 73,60 | 83,30 |
| 2009-05-23 | B735 | A | 72,50 | 76,80 | 85,10 |
| 2009-05-23 | AT45 | A | 70,60 | 73,20 | 81,70 |
| 2009-05-23 | F100 | A | 70,40 | 72,70 | 81,50 |
| 2009-05-23 | E170 | A | 69,50 | 72,00 | 81,00 |
| 2009-05-23 | E170 | A | 69,30 | 71,70 | 81,60 |
| 2009-05-23 | B734 | A | 72,10 | 76,20 | 84,40 |
| 2009-05-23 | B735 | A | 72,20 | 76,50 | 85,60 |
| 2009-05-23 | E170 | A | 69,60 | 71,30 | 80,40 |
| 2009-05-23 | B735 | A | 72,60 | 76,90 | 85,20 |
| 2009-05-23 | AT72 | A | 70,10 | 71,50 | 80,90 |
| 2009-05-23 | E170 | A | 69,10 | 71,60 | 80,20 |
| 2009-05-23 | E170 | A | 70,50 | 73,00 | 82,00 |
| 2009-05-23 | E170 | A | 70,70 | 73,50 | 82,20 |
| 2009-05-23 | B733 | A | 72,80 | 75,90 | 83,90 |
| 2009-05-23 | AT72 | A | 71,50 | 74,10 | 83,20 |
| 2009-05-23 | E170 | A | 69,80 | 73,10 | 82,10 |
| 2009-05-23 | AT45 | A | 68,10 | 70,10 | 79,90 |
| 2009-05-23 | B733 | A | 71,90 | 75,90 | 84,00 |
| 2009-05-23 | B734 | A | 72,50 | 75,30 | 84,30 |
| 2009-05-23 | B752 | A | 70,90 | 73,30 | 84,50 |
| 2009-05-23 | E170 | A | 70,10 | 72,00 | 81,20 |
| 2009-05-23 | B734 | A | 72,80 | 78,60 | 86,40 |
| 2009-05-23 | AT72 | A | 70,70 | 71,70 | 81,50 |
| 2009-05-24 | B734 | A | 73,60 | 77,90 | 85,60 |
| 2009-05-24 | AT72 | A | 73,80 | 76,80 | 86,80 |
| 2009-05-24 | E170 | A | 70,30 | 72,10 | 81,70 |
| 2009-05-24 | B735 | A | 72,40 | 76,00 | 84,40 |
| 2009-05-24 | B763 | A | 72,50 | 75,60 | 86,10 |
| 2009-05-24 | RJ85 | A | 69,00 | 70,50 | 80,10 |
| 2009-05-24 | CRJ2 | A | 69,00 | 70,70 | 80,20 |
| 2009-05-24 | B763 | A | 72,60 | 76,70 | 86,80 |
| 2009-05-24 | B734 | A | 73,40 | 77,10 | 85,70 |
| 2009-05-24 | F100 | A | 68,40 | 70,40 | 79,90 |
| 2009-05-24 | B733 | A | 72,30 | 75,40 | 84,10 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-24 | AT45 | A | 69,40 | 70,50 | 80,50 |
| 2009-05-24 | AT72 | A | 73,30 | 76,00 | 85,60 |
| 2009-05-24 | A321 | A | 71,60 | 74,40 | 83,10 |
| 2009-05-24 | AT72 | A | 73,90 | 76,10 | 84,70 |
| 2009-05-24 | AT45 | A | 70,80 | 73,30 | 81,90 |
| 2009-05-24 | A321 | A | 70,40 | 73,90 | 82,90 |
| 2009-05-24 | AT72 | A | 71,60 | 75,70 | 85,00 |
| 2009-05-24 | A321 | A | 72,50 | 75,40 | 85,00 |
| 2009-05-24 | B737 | A | 70,30 | 73,80 | 83,50 |
| 2009-05-24 | E170 | A | 69,50 | 72,40 | 82,10 |
| 2009-05-24 | E170 | A | 70,70 | 73,10 | 82,50 |
| 2009-05-24 | A320 | A | 71,10 | 73,30 | 82,90 |
| 2009-05-24 | A320 | A | 71,20 | 73,60 | 81,60 |
| 2009-05-24 | A319 | A | 70,00 | 71,50 | 81,40 |
| 2009-05-24 | E170 | A | 70,80 | 72,20 | 81,90 |
| 2009-05-24 | E170 | A | 68,30 | 71,10 | 79,80 |
| 2009-05-24 | B735 | A | 69,90 | 72,00 | 81,40 |
| 2009-05-24 | A320 | A | 70,30 | 72,40 | 81,10 |
| 2009-05-24 | A319 | A | 72,90 | 75,10 | 84,70 |
| 2009-05-24 | B733 | A | 72,20 | 77,60 | 90,00 |
| 2009-05-24 | B733 | A | 68,70 | 71,30 | 82,50 |
| 2009-05-24 | AT45 | A | 70,90 | 73,80 | 88,60 |
| 2009-05-24 | E170 | A | 70,30 | 72,40 | 81,10 |
| 2009-05-24 | B763 | A | 72,70 | 76,00 | 85,50 |
| 2009-05-24 | B738 | A | 72,20 | 75,10 | 84,00 |
| 2009-05-24 | A320 | A | 68,90 | 71,20 | 80,30 |
| 2009-05-24 | A320 | A | 71,50 | 73,90 | 83,30 |
| 2009-05-24 | A320 | A | 72,00 | 74,70 | 84,30 |
| 2009-05-24 | AT45 | A | 70,70 | 72,50 | 82,20 |
| 2009-05-24 | A319 | A | 72,20 | 73,50 | 83,00 |
| 2009-05-24 | B733 | A | 71,50 | 73,00 | 82,60 |
| 2009-05-24 | B733 | A | 70,70 | 73,20 | 82,50 |
| 2009-05-24 | A319 | A | 71,30 | 73,60 | 82,50 |
| 2009-05-24 | F100 | A | 70,00 | 72,30 | 80,80 |
| 2009-05-24 | B735 | A | 69,40 | 71,90 | 80,60 |
| 2009-05-24 | AT72 | A | 73,00 | 76,00 | 85,30 |
| 2009-05-24 | B735 | A | 73,40 | 76,40 | 83,80 |
| 2009-05-24 | DH8D | A | 68,80 | 70,60 | 78,80 |
| 2009-05-24 | C130 | A | 75,50 | 79,50 | 87,60 |
| 2009-05-24 | A319 | A | 71,30 | 73,50 | 82,50 |
| 2009-05-24 | AT45 | A | 70,30 | 72,20 | 81,70 |
| 2009-05-24 | B735 | A | 72,40 | 75,70 | 83,50 |
| 2009-05-24 | B734 | A | 72,50 | 76,60 | 84,20 |
| 2009-05-24 | AT72 | A | 72,90 | 75,80 | 84,40 |
| 2009-05-24 | AT72 | A | 69,80 | 72,20 | 81,30 |
| 2009-05-24 | E170 | A | 69,80 | 71,90 | 80,20 |
| 2009-05-24 | B734 | A | 72,50 | 77,10 | 84,80 |
| 2009-05-24 | E170 | A | 70,50 | 72,90 | 81,60 |
| 2009-05-24 | E170 | A | 70,00 | 72,70 | 80,80 |
| 2009-05-24 | E170 | A | 70,30 | 73,10 | 82,10 |
| 2009-05-24 | B734 | A | 72,10 | 75,00 | 83,60 |
| 2009-05-24 | E170 | A | 70,00 | 72,30 | 81,40 |
| 2009-05-24 | A319 | A | 71,70 | 75,10 | 82,50 |
| 2009-05-24 | RJ85 | A | 69,70 | 71,70 | 80,10 |
| 2009-05-24 | A320 | A | 70,40 | 71,70 | 81,80 |
| 2009-05-24 | B734 | A | 72,60 | 76,60 | 84,60 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-24 | MD87 | A | 69,80 | 74,00 | 82,80 |
| 2009-05-24 | A320 | A | 71,60 | 73,80 | 82,70 |
| 2009-05-24 | AT72 | A | 70,60 | 73,50 | 83,40 |
| 2009-05-24 | RJ85 | A | 73,00 | 75,40 | 84,20 |
| 2009-05-24 | A320 | A | 70,00 | 71,80 | 80,80 |
| 2009-05-24 | E170 | A | 69,00 | 70,30 | 79,00 |
| 2009-05-24 | A320 | A | 69,40 | 71,20 | 80,20 |
| 2009-05-24 | A319 | A | 70,90 | 72,90 | 81,70 |
| 2009-05-24 | B735 | A | 70,80 | 72,90 | 81,20 |
| 2009-05-24 | E170 | A | 69,70 | 71,70 | 80,10 |
| 2009-05-24 | AT72 | A | 70,60 | 73,10 | 81,40 |
| 2009-05-24 | AT72 | A | 70,70 | 73,00 | 81,80 |
| 2009-05-24 | E170 | A | 70,60 | 72,20 | 80,60 |
| 2009-05-24 | E170 | A | 69,50 | 70,70 | 79,90 |
| 2009-05-24 | DH8D | A | 69,50 | 71,10 | 79,50 |
| 2009-05-24 | B733 | A | 72,30 | 75,60 | 83,40 |
| 2009-05-24 | AT72 | A | 69,20 | 70,40 | 79,20 |
| 2009-05-24 | B735 | A | 72,50 | 75,60 | 84,00 |
| 2009-05-24 | B735 | A | 72,00 | 75,50 | 83,50 |
| 2009-05-24 | F100 | A | 69,90 | 71,20 | 79,90 |
| 2009-05-24 | E190 | A | 70,80 | 73,20 | 82,60 |
| 2009-05-24 | B737 | A | 71,00 | 73,20 | 82,50 |
| 2009-05-24 | B738 | A | 69,90 | 71,40 | 80,30 |
| 2009-05-24 | B737 | A | 70,30 | 72,80 | 80,80 |
| 2009-05-24 | B752 | A | 71,80 | 73,80 | 82,90 |
| 2009-05-24 | A320 | A | 70,90 | 73,10 | 81,70 |
| 2009-05-24 | B735 | A | 72,60 | 75,10 | 83,80 |
| 2009-05-24 | B734 | A | 72,20 | 75,10 | 83,00 |
| 2009-05-24 | B735 | A | 70,20 | 71,60 | 81,60 |
| 2009-05-24 | B735 | A | 72,10 | 77,00 | 82,90 |
| 2009-05-24 | E170 | A | 70,20 | 72,70 | 81,70 |
| 2009-05-24 | AT72 | A | 71,40 | 73,40 | 82,60 |
| 2009-05-24 | B734 | A | 72,90 | 75,90 | 84,40 |
| 2009-05-24 | E170 | A | 69,20 | 70,50 | 79,20 |
| 2009-05-24 | B733 | A | 71,90 | 74,60 | 82,70 |
| 2009-05-24 | B734 | A | 71,90 | 74,60 | 82,70 |
| 2009-05-24 | B733 | A | 72,00 | 74,50 | 82,40 |
| 2009-05-24 | AT72 | A | 71,90 | 74,30 | 83,10 |
| 2009-05-24 | B734 | A | 73,00 | 76,00 | 84,10 |
| 2009-05-24 | AT45 | A | 71,70 | 73,90 | 82,50 |
| 2009-05-25 | E170 | A | 69,70 | 71,60 | 80,50 |
| 2009-05-25 | E170 | A | 69,10 | 71,00 | 79,50 |
| 2009-05-25 | AT72 | A | 71,80 | 74,70 | 83,50 |
| 2009-05-25 | RJ85 | A | 70,70 | 72,50 | 81,10 |
| 2009-05-25 | A319 | A | 69,90 | 71,90 | 80,70 |
| 2009-05-25 | E190 | A | 68,70 | 70,50 | 79,50 |
| 2009-05-25 | B735 | A | 72,50 | 74,30 | 82,90 |
| 2009-05-25 | B738 | A | 73,30 | 76,60 | 85,90 |
| 2009-05-25 | F100 | A | 69,80 | 71,30 | 80,20 |
| 2009-05-25 | B763 | A | 72,50 | 74,90 | 84,50 |
| 2009-05-25 | CRJ2 | A | 68,30 | 70,40 | 79,10 |
| 2009-05-25 | MD87 | A | 71,50 | 75,50 | 84,80 |
| 2009-05-25 | B735 | A | 72,90 | 76,50 | 83,70 |
| 2009-05-25 | B735 | A | 71,40 | 73,30 | 82,50 |
| 2009-05-25 | A320 | A | 70,10 | 72,00 | 81,20 |
| 2009-05-25 | A320 | A | 69,90 | 71,90 | 81,00 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-25 | B735 | A | 71,30 | 75,00 | 82,40 |
| 2009-05-25 | A321 | A | 71,20 | 73,10 | 83,00 |
| 2009-05-25 | E170 | A | 69,70 | 73,00 | 80,10 |
| 2009-05-25 | E170 | A | 69,10 | 71,10 | 79,50 |
| 2009-05-25 | AT45 | A | 70,00 | 71,60 | 81,10 |
| 2009-05-25 | E170 | A | 69,60 | 71,40 | 79,60 |
| 2009-05-25 | B735 | A | 72,80 | 76,80 | 83,90 |
| 2009-05-25 | AT45 | A | 68,90 | 71,10 | 80,10 |
| 2009-05-25 | A319 | A | 69,90 | 72,70 | 81,70 |
| 2009-05-25 | DH8D | A | 70,30 | 72,60 | 81,10 |
| 2009-05-25 | AT72 | A | 69,80 | 72,20 | 81,30 |
| 2009-05-25 | AT72 | A | 71,20 | 72,90 | 82,00 |
| 2009-05-25 | E170 | A | 69,10 | 72,40 | 80,90 |
| 2009-05-25 | A320 | A | 70,80 | 73,60 | 82,80 |
| 2009-05-25 | B735 | A | 69,80 | 72,90 | 83,00 |
| 2009-05-25 | AT72 | A | 72,30 | 76,10 | 84,80 |
| 2009-05-25 | E170 | A | 69,50 | 70,80 | 79,50 |
| 2009-05-25 | AT72 | A | 72,40 | 76,20 | 84,90 |
| 2009-05-25 | PC12 | A | 69,80 | 72,20 | 79,80 |
| 2009-05-25 | B734 | A | 71,70 | 75,80 | 82,80 |
| 2009-05-25 | B734 | A | 71,60 | 75,50 | 83,40 |
| 2009-05-25 | A321 | A | 71,70 | 74,20 | 83,20 |
| 2009-05-25 | B734 | A | 72,50 | 77,30 | 84,20 |
| 2009-05-25 | B734 | A | 71,80 | 75,10 | 83,00 |
| 2009-05-25 | A319 | A | 70,10 | 72,20 | 81,20 |
| 2009-05-25 | A320 | A | 70,80 | 72,90 | 81,90 |
| 2009-05-25 | A320 | A | 70,50 | 72,50 | 82,20 |
| 2009-05-25 | B734 | A | 74,10 | 78,90 | 86,10 |
| 2009-05-25 | B735 | A | 73,20 | 77,10 | 84,30 |
| 2009-05-25 | B733 | A | 70,20 | 71,90 | 81,00 |
| 2009-05-25 | A319 | A | 71,80 | 73,80 | 82,90 |
| 2009-05-25 | E170 | A | 68,30 | 69,90 | 78,80 |
| 2009-05-25 | B763 | A | 73,20 | 77,00 | 86,60 |
| 2009-05-25 | A320 | A | 72,40 | 75,30 | 84,90 |
| 2009-05-25 | E170 | A | 69,30 | 71,90 | 80,10 |
| 2009-05-25 | E170 | A | 69,70 | 71,00 | 80,10 |
| 2009-05-25 | E170 | A | 70,50 | 72,70 | 81,60 |
| 2009-05-25 | B735 | A | 70,80 | 74,90 | 83,20 |
| 2009-05-25 | B763 | A | 73,00 | 75,30 | 86,00 |
| 2009-05-25 | B735 | A | 70,90 | 73,80 | 82,00 |
| 2009-05-25 | AT45 | A | 69,40 | 71,10 | 80,20 |
| 2009-05-25 | B738 | A | 71,90 | 76,10 | 85,50 |
| 2009-05-25 | E145 | A | 70,20 | 72,50 | 80,60 |
| 2009-05-25 | B733 | A | 71,80 | 75,50 | 82,60 |
| 2009-05-25 | A320 | A | 70,90 | 73,50 | 82,90 |
| 2009-05-25 | YK40 | A | 71,40 | 73,80 | 81,80 |
| 2009-05-25 | B763 | A | 71,50 | 73,70 | 83,80 |
| 2009-05-25 | CRJ2 | A | 68,90 | 70,70 | 79,60 |
| 2009-05-25 | A319 | A | 69,20 | 71,90 | 81,50 |
| 2009-05-25 | B738 | A | 72,20 | 74,50 | 84,70 |
| 2009-05-25 | A320 | A | 70,90 | 72,80 | 82,00 |
| 2009-05-25 | A320 | A | 70,40 | 72,10 | 81,90 |
| 2009-05-25 | E170 | A | 71,20 | 73,00 | 82,00 |
| 2009-05-25 | B735 | A | 71,20 | 73,60 | 82,40 |
| 2009-05-25 | AT72 | A | 71,70 | 74,70 | 83,20 |
| 2009-05-25 | E170 | A | 69,30 | 71,80 | 80,10 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-25 | C295 | A | 70,00 | 72,80 | 81,40 |
| 2009-05-25 | A320 | A | 70,80 | 73,60 | 82,60 |
| 2009-05-25 | AT72 | A | 71,70 | 74,90 | 83,50 |
| 2009-05-25 | E170 | A | 69,60 | 71,40 | 80,40 |
| 2009-05-25 | E170 | A | 69,70 | 72,00 | 80,80 |
| 2009-05-25 | B735 | A | 73,10 | 77,80 | 85,90 |
| 2009-05-25 | B735 | A | 71,90 | 75,50 | 82,70 |
| 2009-05-25 | E170 | A | 68,70 | 70,50 | 78,70 |
| 2009-05-25 | AT72 | A | 71,00 | 73,90 | 81,80 |
| 2009-05-25 | GLF4 | A | 68,00 | 70,10 | 79,10 |
| 2009-05-25 | E170 | A | 69,20 | 70,80 | 79,20 |
| 2009-05-25 | E170 | A | 70,30 | 73,20 | 80,30 |
| 2009-05-25 | RJ85 | A | 68,20 | 69,50 | 78,20 |
| 2009-05-25 | CRJ9 | A | 70,10 | 71,90 | 80,10 |
| 2009-05-25 | B737 | A | 71,00 | 74,00 | 83,70 |
| 2009-05-25 | A320 | A | 71,70 | 73,70 | 82,80 |
| 2009-05-25 | A320 | A | 68,80 | 71,60 | 81,20 |
| 2009-05-25 | A320 | A | 71,40 | 73,30 | 82,90 |
| 2009-05-25 | A320 | A | 70,10 | 72,00 | 80,90 |
| 2009-05-25 | YK40 | A | 70,60 | 73,60 | 80,60 |
| 2009-05-25 | E170 | A | 67,90 | 68,90 | 77,90 |
| 2009-05-25 | B735 | A | 71,00 | 72,40 | 81,80 |
| 2009-05-25 | E170 | A | 69,40 | 73,00 | 80,50 |
| 2009-05-25 | A320 | A | 69,60 | 71,70 | 80,40 |
| 2009-05-25 | A318 | A | 70,30 | 72,60 | 80,70 |
| 2009-05-25 | E170 | A | 68,90 | 71,10 | 80,40 |
| 2009-05-25 | A320 | A | 69,00 | 70,20 | 79,80 |
| 2009-05-25 | GLF4 | A | 71,20 | 73,80 | 81,70 |
| 2009-05-25 | A319 | A | 70,00 | 71,40 | 80,40 |
| 2009-05-25 | B733 | A | 71,20 | 73,40 | 82,40 |
| 2009-05-25 | AT72 | A | 71,30 | 73,70 | 82,70 |
| 2009-05-25 | AT72 | A | 70,70 | 72,60 | 81,40 |
| 2009-05-25 | A320 | A | 71,00 | 73,30 | 82,50 |
| 2009-05-25 | AT72 | A | 72,30 | 75,20 | 84,60 |
| 2009-05-25 | B734 | A | 73,30 | 76,30 | 84,10 |
| 2009-05-25 | A319 | A | 72,50 | 74,80 | 83,90 |
| 2009-05-25 | B735 | A | 72,60 | 76,30 | 83,40 |
| 2009-05-25 | B734 | A | 75,30 | 79,10 | 87,10 |
| 2009-05-25 | E170 | A | 70,60 | 72,50 | 81,10 |
| 2009-05-25 | B737 | A | 70,30 | 72,00 | 81,40 |
| 2009-05-25 | B735 | A | 72,00 | 74,40 | 82,00 |
| 2009-05-25 | B734 | A | 70,10 | 71,60 | 80,90 |
| 2009-05-25 | E170 | A | 69,10 | 70,60 | 79,10 |
| 2009-05-25 | A320 | A | 70,70 | 72,40 | 81,10 |
| 2009-05-25 | B734 | A | 71,80 | 74,60 | 82,20 |
| 2009-05-25 | B735 | A | 71,80 | 74,70 | 82,60 |
| 2009-05-25 | B734 | A | 72,50 | 75,70 | 83,60 |
| 2009-05-25 | B733 | A | 71,50 | 74,50 | 82,30 |
| 2009-05-25 | E170 | A | 68,50 | 70,50 | 78,90 |
| 2009-05-25 | AT72 | A | 71,10 | 72,80 | 81,90 |
| 2009-05-25 | B733 | A | 70,40 | 72,40 | 81,20 |
| 2009-05-25 | B738 | A | 70,70 | 72,40 | 81,10 |
| 2009-05-25 | AT72 | A | 69,10 | 70,40 | 80,30 |
| 2009-05-25 | B735 | A | 71,00 | 73,80 | 81,80 |
| 2009-05-26 | B733 | A | 68,40 | 69,30 | 79,20 |
| 2009-05-26 | B738 | A | 73,20 | 76,10 | 84,00 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-26 | AT72 | A | 70,90 | 72,90 | 81,30 |
| 2009-05-26 | AT72 | A | 69,40 | 71,40 | 80,90 |
| 2009-05-26 | AT43 | A | 71,50 | 74,10 | 82,60 |
| 2009-05-26 | A319 | A | 69,00 | 70,30 | 79,00 |
| 2009-05-26 | B738 | A | 72,10 | 74,70 | 82,90 |
| 2009-05-26 | B734 | A | 70,60 | 73,80 | 81,00 |
| 2009-05-26 | E190 | A | 70,10 | 72,60 | 80,90 |
| 2009-05-26 | B752 | D | 67,10 | 69,30 | 79,10 |
| 2009-05-26 | YK40 | D | 67,90 | 70,80 | 78,30 |
| 2009-05-26 | MD11 | D | 73,90 | 79,30 | 89,00 |
| 2009-05-26 | B734 | D | 69,60 | 73,70 | 83,60 |
| 2009-05-26 | MD82 | D | 72,00 | 77,00 | 85,60 |
| 2009-05-26 | F100 | D | 68,90 | 71,70 | 80,90 |
| 2009-05-26 | A320 | D | 68,90 | 70,60 | 79,30 |
| 2009-05-26 | A320 | D | 70,30 | 72,20 | 82,10 |
| 2009-05-26 | B734 | D | 69,80 | 72,60 | 81,50 |
| 2009-05-26 | A320 | D | 68,30 | 69,60 | 78,30 |
| 2009-05-26 | B763 | D | 68,70 | 72,80 | 81,50 |
| 2009-05-26 | B735 | D | 67,70 | 69,00 | 79,20 |
| 2009-05-26 | B738 | D | 69,00 | 70,80 | 79,00 |
| 2009-05-26 | A320 | D | 67,00 | 68,40 | 78,10 |
| 2009-05-26 | B735 | D | 67,70 | 70,50 | 78,80 |
| 2009-05-26 | B763 | D | 72,90 | 76,50 | 84,90 |
| 2009-05-26 | B735 | D | 67,60 | 70,60 | 79,70 |
| 2009-05-27 | B734 | A | 72,10 | 73,70 | 82,50 |
| 2009-05-27 | A320 | A | 69,80 | 71,60 | 80,60 |
| 2009-05-27 | CL30 | D | 68,20 | 70,30 | 78,60 |
| 2009-05-27 | B734 | D | 68,30 | 69,80 | 78,70 |
| 2009-05-27 | B733 | D | 69,80 | 72,30 | 80,60 |
| 2009-05-27 | B734 | D | 70,60 | 73,40 | 82,90 |
| 2009-05-27 | B734 | D | 71,20 | 75,70 | 82,60 |
| 2009-05-27 | MD11 | D | 73,50 | 79,30 | 88,40 |
| 2009-05-27 | AT72 | A | 71,30 | 73,90 | 83,10 |
| 2009-05-27 | A320 | A | 71,50 | 74,00 | 82,60 |
| 2009-05-27 | AT72 | A | 72,90 | 76,30 | 85,20 |
| 2009-05-27 | E170 | A | 70,00 | 72,80 | 80,80 |
| 2009-05-27 | AT72 | A | 72,50 | 75,50 | 84,20 |
| 2009-05-27 | AT45 | A | 70,80 | 72,50 | 81,60 |
| 2009-05-27 | E170 | A | 70,70 | 73,50 | 80,70 |
| 2009-05-27 | B735 | A | 71,30 | 74,40 | 83,30 |
| 2009-05-27 | E170 | A | 70,80 | 72,20 | 81,60 |
| 2009-05-27 | A320 | A | 69,90 | 71,80 | 81,00 |
| 2009-05-27 | B734 | A | 73,80 | 77,80 | 85,80 |
| 2009-05-27 | AT72 | A | 71,60 | 73,70 | 83,10 |
| 2009-05-27 | B735 | A | 73,00 | 76,80 | 84,80 |
| 2009-05-27 | B738 | A | 71,80 | 76,00 | 85,30 |
| 2009-05-27 | AT72 | A | 72,50 | 75,20 | 86,30 |
| 2009-05-27 | A320 | A | 71,60 | 74,40 | 83,60 |
| 2009-05-27 | B734 | A | 72,50 | 77,10 | 84,00 |
| 2009-05-27 | A321 | A | 73,50 | 77,30 | 86,10 |
| 2009-05-27 | BE9L | A | 74,20 | 77,50 | 84,20 |
| 2009-05-27 | B734 | A | 71,10 | 73,70 | 83,70 |
| 2009-05-27 | B738 | A | 72,80 | 76,20 | 86,00 |
| 2009-05-27 | B735 | A | 70,10 | 72,50 | 82,90 |
| 2009-05-27 | B733 | A | 72,60 | 75,70 | 84,40 |
| 2009-05-27 | AT72 | A | 72,90 | 75,60 | 85,50 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-27 | B752 | A | 71,50 | 75,20 | 87,20 |
| 2009-05-27 | D328 | A | 70,10 | 72,80 | 83,30 |
| 2009-05-27 | E145 | A | 68,10 | 69,60 | 78,10 |
| 2009-05-27 | A320 | A | 73,00 | 76,40 | 86,10 |
| 2009-05-27 | E170 | A | 70,00 | 72,50 | 82,80 |
| 2009-05-27 | A320 | A | 71,90 | 73,90 | 84,50 |
| 2009-05-27 | A320 | A | 70,80 | 73,20 | 83,30 |
| 2009-05-27 | A318 | A | 71,50 | 74,80 | 84,90 |
| 2009-05-27 | E170 | A | 69,40 | 72,70 | 82,50 |
| 2009-05-27 | E170 | A | 70,40 | 73,20 | 82,20 |
| 2009-05-27 | E190 | A | 70,40 | 73,90 | 81,20 |
| 2009-05-27 | AT45 | A | 71,00 | 73,70 | 82,40 |
| 2009-05-27 | CRJ2 | A | 69,40 | 71,40 | 81,70 |
| 2009-05-27 | RJ85 | A | 69,60 | 71,30 | 80,70 |
| 2009-05-27 | E170 | A | 71,10 | 73,70 | 83,70 |
| 2009-05-27 | YK40 | A | 73,70 | 77,80 | 85,50 |
| 2009-05-27 | A321 | A | 72,70 | 77,30 | 86,30 |
| 2009-05-27 | B763 | A | 75,50 | 79,70 | 89,30 |
| 2009-05-27 | A320 | A | 72,60 | 75,10 | 84,70 |
| 2009-05-27 | B733 | A | 73,90 | 77,50 | 85,70 |
| 2009-05-27 | YK40 | A | 72,00 | 74,80 | 84,00 |
| 2009-05-27 | A319 | A | 71,80 | 74,90 | 84,60 |
| 2009-05-27 | A320 | A | 70,30 | 73,10 | 82,00 |
| 2009-05-27 | LJ45 | A | 69,00 | 71,90 | 82,20 |
| 2009-05-27 | AT72 | A | 71,80 | 76,00 | 85,20 |
| 2009-05-27 | AT72 | A | 71,50 | 74,70 | 84,10 |
| 2009-05-27 | E170 | A | 72,20 | 74,80 | 83,00 |
| 2009-05-27 | F100 | A | 70,10 | 72,80 | 82,40 |
| 2009-05-27 | A320 | A | 71,10 | 73,60 | 82,20 |
| 2009-05-27 | A319 | A | 71,80 | 74,40 | 83,80 |
| 2009-05-27 | E170 | A | 70,80 | 73,40 | 82,50 |
| 2009-05-27 | B738 | A | 72,50 | 75,40 | 84,30 |
| 2009-05-27 | B735 | A | 73,80 | 76,60 | 84,90 |
| 2009-05-27 | B734 | A | 72,70 | 77,30 | 86,00 |
| 2009-05-27 | A320 | A | 71,10 | 75,00 | 84,50 |
| 2009-05-27 | DH8D | A | 69,40 | 71,80 | 80,80 |
| 2009-05-27 | AT72 | A | 72,80 | 75,90 | 86,30 |
| 2009-05-27 | B734 | A | 73,50 | 78,10 | 86,50 |
| 2009-05-27 | AT72 | A | 72,10 | 75,70 | 83,60 |
| 2009-05-27 | B735 | A | 72,80 | 77,20 | 84,80 |
| 2009-05-27 | B738 | A | 72,30 | 76,00 | 85,10 |
| 2009-05-27 | A319 | A | 71,30 | 72,50 | 82,80 |
| 2009-05-27 | E170 | A | 70,80 | 73,00 | 83,60 |
| 2009-05-27 | E170 | A | 72,30 | 75,00 | 85,10 |
| 2009-05-27 | AT72 | A | 74,30 | 76,60 | 86,10 |
| 2009-05-27 | E145 | A | 67,60 | 70,00 | 78,80 |
| 2009-05-27 | E170 | A | 70,10 | 74,10 | 81,60 |
| 2009-05-27 | E170 | A | 71,30 | 73,80 | 83,60 |
| 2009-05-27 | H25B | A | 70,30 | 73,10 | 80,30 |
| 2009-05-27 | AT45 | A | 70,60 | 74,30 | 83,40 |
| 2009-05-27 | B734 | A | 73,90 | 77,50 | 86,00 |
| 2009-05-27 | CRJ2 | A | 69,30 | 71,10 | 80,40 |
| 2009-05-27 | E170 | A | 69,90 | 71,90 | 81,60 |
| 2009-05-27 | RJ85 | A | 69,10 | 71,60 | 81,40 |
| 2009-05-27 | B734 | A | 73,50 | 78,40 | 86,30 |
| 2009-05-27 | AT45 | A | 68,60 | 70,70 | 79,80 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-27 | CRJ9 | A | 70,40 | 72,50 | 81,50 |
| 2009-05-27 | B738 | A | 70,10 | 73,90 | 83,90 |
| 2009-05-27 | B737 | A | 71,40 | 73,60 | 83,40 |
| 2009-05-27 | AN26 | A | 73,70 | 77,10 | 85,20 |
| 2009-05-27 | A320 | A | 70,60 | 73,70 | 82,70 |
| 2009-05-27 | A320 | A | 70,30 | 73,10 | 82,60 |
| 2009-05-27 | AT72 | A | 72,80 | 75,30 | 84,60 |
| 2009-05-27 | AT72 | A | 72,50 | 74,10 | 85,20 |
| 2009-05-27 | B734 | A | 73,10 | 77,60 | 86,30 |
| 2009-05-27 | A320 | A | 69,60 | 72,40 | 82,10 |
| 2009-05-27 | A321 | A | 72,10 | 75,00 | 84,20 |
| 2009-05-27 | RJ85 | A | 68,20 | 70,90 | 80,00 |
| 2009-05-27 | A321 | A | 72,10 | 75,80 | 84,70 |
| 2009-05-27 | B735 | A | 73,90 | 78,00 | 85,00 |
| 2009-05-27 | E170 | A | 70,30 | 73,60 | 82,90 |
| 2009-05-27 | A318 | A | 70,70 | 74,50 | 83,50 |
| 2009-05-27 | E190 | A | 71,60 | 74,90 | 83,10 |
| 2009-05-27 | AT72 | A | 71,50 | 74,30 | 84,50 |
| 2009-05-27 | MD11 | A | 76,60 | 82,70 | 91,70 |
| 2009-05-27 | B734 | A | 72,70 | 75,40 | 84,50 |
| 2009-05-27 | B735 | A | 70,30 | 72,90 | 83,10 |
| 2009-05-27 | E170 | A | 70,70 | 71,80 | 81,50 |
| 2009-05-27 | B735 | A | 73,20 | 77,20 | 85,00 |
| 2009-05-27 | DH8D | A | 67,80 | 69,40 | 79,00 |
| 2009-05-27 | B733 | A | 70,50 | 72,70 | 81,30 |
| 2009-05-27 | E170 | A | 70,10 | 72,60 | 80,90 |
| 2009-05-27 | E170 | A | 70,00 | 71,50 | 82,00 |
| 2009-05-27 | F100 | A | 68,90 | 70,40 | 79,70 |
| 2009-05-27 | B738 | A | 73,50 | 76,80 | 84,30 |
| 2009-05-27 | AT72 | A | 72,20 | 76,20 | 85,90 |
| 2009-05-27 | B734 | A | 73,60 | 76,50 | 84,70 |
| 2009-05-27 | CRJ7 | A | 69,70 | 71,40 | 80,10 |
| 2009-05-27 | B734 | A | 72,70 | 75,90 | 84,50 |
| 2009-05-27 | B737 | A | 70,50 | 72,80 | 82,00 |
| 2009-05-27 | E170 | A | 69,70 | 71,80 | 80,20 |
| 2009-05-27 | F2TH | A | 69,70 | 72,90 | 80,80 |
| 2009-05-27 | C295 | A | 70,40 | 72,50 | 81,20 |
| 2009-05-27 | E170 | A | 70,80 | 73,40 | 82,30 |
| 2009-05-27 | E170 | A | 70,10 | 72,60 | 81,20 |
| 2009-05-27 | A320 | A | 71,00 | 74,10 | 83,00 |
| 2009-05-27 | B735 | A | 70,50 | 72,10 | 82,00 |
| 2009-05-27 | B735 | A | 71,10 | 72,60 | 82,60 |
| 2009-05-27 | B734 | A | 74,30 | 79,20 | 87,10 |
| 2009-05-27 | E170 | A | 71,20 | 73,70 | 81,60 |
| 2009-05-27 | E170 | A | 69,30 | 70,60 | 80,10 |
| 2009-05-27 | B734 | A | 71,60 | 74,40 | 83,70 |
| 2009-05-27 | B735 | A | 72,30 | 76,00 | 84,60 |
| 2009-05-27 | B733 | A | 71,40 | 73,50 | 83,50 |
| 2009-05-27 | E170 | A | 70,20 | 71,60 | 81,70 |
| 2009-05-27 | E170 | A | 70,90 | 72,90 | 82,30 |
| 2009-05-27 | B734 | A | 73,20 | 76,80 | 85,00 |
| 2009-05-27 | AT72 | A | 71,20 | 73,40 | 83,20 |
| 2009-05-27 | AT72 | A | 71,20 | 73,20 | 82,60 |
| 2009-05-27 | B735 | A | 72,50 | 76,00 | 84,30 |
| 2009-05-27 | B734 | A | 71,00 | 72,50 | 83,10 |
| 2009-05-27 | E170 | A | 69,60 | 71,80 | 81,00 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-27 | AT72 | A | 71,20 | 73,50 | 83,50 |
| 2009-05-27 | AN26 | A | 71,50 | 73,90 | 81,90 |
| 2009-05-28 | B733 | A | 69,30 | 70,90 | 79,30 |
| 2009-05-28 | AT43 | A | 71,20 | 74,40 | 81,20 |
| 2009-05-28 | E170 | A | 67,50 | 68,50 | 77,50 |
| 2009-05-28 | B734 | A | 73,00 | 76,10 | 84,10 |
| 2009-05-28 | A319 | A | 70,10 | 71,70 | 80,10 |
| 2009-05-28 | RJ85 | A | 70,30 | 72,90 | 80,30 |
| 2009-05-28 | B736 | A | 68,50 | 70,30 | 79,90 |
| 2009-05-28 | CRJ7 | A | 68,10 | 69,00 | 78,10 |
| 2009-05-28 | B735 | A | 70,30 | 74,00 | 80,70 |
| 2009-05-28 | B763 | A | 72,30 | 74,90 | 85,10 |
| 2009-05-28 | B763 | A | 71,60 | 74,20 | 85,00 |
| 2009-05-28 | RJ1H | A | 68,30 | 70,30 | 78,30 |
| 2009-05-28 | E145 | A | 67,60 | 68,70 | 77,60 |
| 2009-05-28 | E170 | A | 68,40 | 70,60 | 79,90 |
| 2009-05-28 | B735 | A | 72,20 | 75,60 | 83,30 |
| 2009-05-28 | A319 | A | 69,70 | 71,60 | 80,90 |
| 2009-05-28 | B735 | A | 71,50 | 74,10 | 82,30 |
| 2009-05-28 | A320 | A | 72,00 | 74,00 | 82,80 |
| 2009-05-28 | AT72 | A | 71,70 | 74,00 | 83,50 |
| 2009-05-28 | E170 | A | 69,50 | 71,60 | 79,50 |
| 2009-05-28 | A320 | A | 70,80 | 72,90 | 81,20 |
| 2009-05-28 | E170 | A | 70,50 | 72,80 | 80,50 |
| 2009-05-28 | B738 | A | 73,10 | 77,00 | 84,50 |
| 2009-05-28 | B738 | A | 70,30 | 71,60 | 81,10 |
| 2009-05-28 | A320 | A | 72,00 | 74,30 | 82,40 |
| 2009-05-28 | B734 | A | 70,80 | 74,20 | 82,00 |
| 2009-05-28 | A320 | A | 70,80 | 72,60 | 81,20 |
| 2009-05-28 | A320 | A | 70,70 | 73,40 | 81,10 |
| 2009-05-28 | B735 | A | 71,30 | 74,40 | 81,70 |
| 2009-05-28 | A321 | A | 72,20 | 75,00 | 83,60 |
| 2009-05-28 | B734 | A | 70,50 | 72,70 | 81,30 |
| 2009-05-28 | E170 | A | 70,70 | 72,50 | 81,80 |
| 2009-05-28 | B735 | A | 72,00 | 76,20 | 82,80 |
| 2009-05-28 | A320 | A | 70,00 | 72,00 | 80,80 |
| 2009-05-28 | A319 | A | 71,10 | 72,70 | 81,90 |
| 2009-05-28 | A320 | A | 75,50 | 78,90 | 87,00 |
| 2009-05-28 | E170 | A | 68,40 | 70,00 | 78,80 |
| 2009-05-28 | T134 | A | 75,70 | 80,00 | 88,90 |
| 2009-05-28 | E170 | A | 69,30 | 71,20 | 80,10 |
| 2009-05-28 | E190 | A | 70,50 | 72,90 | 83,80 |
| 2009-05-28 | B733 | A | 70,50 | 71,80 | 80,50 |
| 2009-05-28 | AT45 | A | 69,50 | 71,40 | 79,90 |
| 2009-05-28 | B734 | A | 73,10 | 76,40 | 83,80 |
| 2009-05-28 | B733 | A | 72,10 | 73,70 | 82,10 |
| 2009-05-28 | A320 | A | 71,70 | 74,20 | 83,50 |
| 2009-05-28 | A319 | A | 69,00 | 71,90 | 79,00 |
| 2009-05-28 | B763 | A | 72,80 | 75,20 | 84,90 |
| 2009-05-28 | B752 | A | 70,70 | 73,40 | 82,50 |
| 2009-05-28 | B735 | A | 70,40 | 72,70 | 81,50 |
| 2009-05-28 | E170 | A | 70,80 | 73,30 | 80,80 |
| 2009-05-28 | E170 | A | 69,70 | 72,40 | 81,20 |
| 2009-05-28 | AT45 | A | 70,20 | 72,30 | 80,20 |
| 2009-05-28 | AT72 | A | 72,30 | 74,60 | 83,50 |
| 2009-05-28 | E170 | A | 70,50 | 72,80 | 81,20 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-28 | AN28 | A | 69,70 | 72,90 | 83,10 |
| 2009-05-28 | B735 | A | 69,10 | 72,40 | 81,70 |
| 2009-05-28 | E170 | A | 69,50 | 71,00 | 79,50 |
| 2009-05-28 | AT72 | A | 72,50 | 75,30 | 83,60 |
| 2009-05-28 | E170 | A | 68,90 | 70,40 | 78,90 |
| 2009-05-28 | B734 | A | 71,70 | 75,60 | 83,50 |
| 2009-05-28 | E170 | A | 69,90 | 71,40 | 80,40 |
| 2009-05-28 | A320 | A | 72,20 | 74,70 | 84,30 |
| 2009-05-28 | A319 | A | 70,70 | 73,80 | 82,80 |
| 2009-05-28 | CRJ9 | A | 69,80 | 72,60 | 81,20 |
| 2009-05-28 | B737 | A | 73,60 | 76,10 | 84,40 |
| 2009-05-28 | RJ85 | A | 75,60 | 78,50 | 86,70 |
| 2009-05-28 | B738 | A | 71,50 | 74,00 | 82,70 |
| 2009-05-28 | A320 | A | 70,40 | 71,80 | 80,80 |
| 2009-05-28 | A320 | A | 71,10 | 72,80 | 81,10 |
| 2009-05-28 | AT45 | A | 72,50 | 75,00 | 84,00 |
| 2009-05-28 | B733 | A | 73,50 | 75,70 | 84,70 |
| 2009-05-28 | RJ85 | A | 70,50 | 72,20 | 80,50 |
| 2009-05-28 | AT72 | A | 68,10 | 70,70 | 79,90 |
| 2009-05-28 | B735 | A | 71,10 | 73,50 | 81,90 |
| 2009-05-28 | MD11 | A | 75,20 | 79,80 | 89,50 |
| 2009-05-28 | A320 | A | 70,90 | 72,90 | 82,30 |
| 2009-05-28 | E170 | A | 70,20 | 73,40 | 81,90 |
| 2009-05-28 | AT72 | A | 73,60 | 77,00 | 86,90 |
| 2009-05-28 | C295 | A | 70,50 | 72,80 | 80,50 |
| 2009-05-28 | AT45 | A | 68,90 | 70,40 | 79,30 |
| 2009-05-28 | AT72 | A | 71,70 | 74,00 | 83,20 |
| 2009-05-28 | DH8D | A | 69,10 | 71,00 | 79,90 |
| 2009-05-28 | E170 | A | 70,50 | 72,60 | 81,30 |
| 2009-05-28 | YK40 | A | 72,60 | 76,20 | 83,40 |
| 2009-05-28 | B733 | A | 72,30 | 75,80 | 84,30 |
| 2009-05-28 | E170 | A | 70,30 | 72,50 | 81,50 |
| 2009-05-28 | E170 | A | 76,40 | 80,30 | 90,90 |
| 2009-05-28 | B735 | A | 70,20 | 72,20 | 81,60 |
| 2009-05-28 | B735 | A | 71,10 | 72,80 | 82,20 |
| 2009-05-28 | F100 | A | 69,90 | 72,10 | 80,70 |
| 2009-05-28 | A319 | A | 71,90 | 74,20 | 84,20 |
| 2009-05-28 | DH8D | A | 70,90 | 73,10 | 81,70 |
| 2009-05-28 | CRJ7 | A | 70,80 | 73,30 | 81,60 |
| 2009-05-28 | B734 | A | 73,40 | 78,60 | 85,50 |
| 2009-05-28 | SF34 | A | 70,60 | 72,80 | 81,00 |
| 2009-05-28 | B734 | A | 71,00 | 72,90 | 82,50 |
| 2009-05-28 | B737 | A | 72,00 | 74,60 | 83,80 |
| 2009-05-28 | E170 | A | 68,90 | 70,80 | 79,70 |
| 2009-05-28 | A320 | A | 71,10 | 73,10 | 82,30 |
| 2009-05-28 | B734 | A | 72,00 | 76,60 | 84,30 |
| 2009-05-28 | E170 | A | 68,60 | 70,80 | 80,90 |
| 2009-05-28 | B735 | A | 72,80 | 77,50 | 84,80 |
| 2009-05-28 | E170 | A | 70,20 | 73,50 | 84,00 |
| 2009-05-28 | B735 | A | 73,40 | 77,40 | 85,40 |
| 2009-05-28 | B734 | A | 72,20 | 76,20 | 85,40 |
| 2009-05-28 | B734 | A | 73,30 | 78,70 | 86,90 |
| 2009-05-28 | B735 | A | 72,80 | 76,80 | 85,60 |
| 2009-05-28 | SF34 | A | 69,20 | 71,00 | 79,20 |
| 2009-05-28 | E170 | A | 72,10 | 75,50 | 83,90 |
| 2009-05-28 | E170 | A | 70,60 | 73,70 | 82,60 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-28 | E170 | A | 71,40 | 74,90 | 84,20 |
| 2009-05-28 | E145 | A | 68,10 | 69,80 | 78,10 |
| 2009-05-28 | YK40 | A | 72,80 | 77,30 | 86,20 |
| 2009-05-28 | AT72 | A | 69,20 | 72,90 | 81,00 |
| 2009-05-28 | B733 | A | 73,10 | 76,10 | 85,20 |
| 2009-05-28 | AN28 | A | 67,80 | 69,10 | 77,80 |
| 2009-05-28 | E170 | A | 71,60 | 75,10 | 84,20 |
| 2009-05-28 | B733 | A | 73,90 | 78,40 | 86,70 |
| 2009-05-28 | E170 | A | 70,00 | 72,80 | 82,10 |
| 2009-05-28 | E170 | A | 70,70 | 74,40 | 83,30 |
| 2009-05-29 | AT72 | A | 74,60 | 77,10 | 85,80 |
| 2009-05-29 | B462 | A | 72,80 | 75,20 | 83,90 |
| 2009-05-29 | E170 | A | 69,60 | 71,30 | 80,40 |
| 2009-05-29 | AT72 | A | 72,90 | 75,40 | 85,70 |
| 2009-05-29 | E170 | A | 70,20 | 73,10 | 82,50 |
| 2009-05-29 | E170 | A | 70,00 | 72,60 | 80,80 |
| 2009-05-29 | AT72 | A | 69,50 | 71,80 | 81,80 |
| 2009-05-29 | B733 | A | 72,90 | 75,70 | 84,90 |
| 2009-05-29 | AT72 | A | 71,70 | 73,80 | 82,90 |
| 2009-05-29 | AT72 | A | 72,50 | 76,00 | 84,20 |
| 2009-05-29 | A320 | A | 71,70 | 74,10 | 83,50 |
| 2009-05-29 | A319 | A | 71,30 | 73,30 | 82,50 |
| 2009-05-29 | RJ85 | A | 70,80 | 72,80 | 81,60 |
| 2009-05-29 | YK40 | A | 74,00 | 76,50 | 84,80 |
| 2009-05-29 | B738 | A | 71,70 | 74,50 | 83,10 |
| 2009-05-29 | GLF4 | A | 70,10 | 71,60 | 81,50 |
| 2009-05-29 | F70 | A | 70,10 | 72,10 | 80,90 |
| 2009-05-29 | CRJ7 | A | 69,90 | 71,40 | 80,60 |
| 2009-05-29 | B735 | A | 72,70 | 78,10 | 85,70 |
| 2009-05-29 | A320 | A | 70,70 | 73,10 | 83,70 |
| 2009-05-29 | A320 | A | 70,20 | 72,60 | 82,20 |
| 2009-05-29 | F100 | A | 71,70 | 73,60 | 82,10 |
| 2009-05-29 | E170 | A | 71,00 | 73,80 | 82,10 |
| 2009-05-29 | CRJ9 | A | 71,10 | 74,00 | 81,90 |
| 2009-05-29 | B733 | A | 73,50 | 77,50 | 85,50 |
| 2009-05-29 | B763 | A | 76,20 | 79,50 | 89,20 |
| 2009-05-29 | AT72 | A | 69,20 | 70,40 | 80,00 |
| 2009-05-29 | E170 | A | 70,70 | 73,10 | 81,90 |
| 2009-05-29 | E170 | A | 70,20 | 72,50 | 81,60 |
| 2009-05-29 | T154 | A | 75,60 | 80,10 | 88,40 |
| 2009-05-29 | A319 | A | 70,90 | 73,10 | 82,40 |
| 2009-05-29 | A319 | A | 71,40 | 74,40 | 83,50 |
| 2009-05-29 | B735 | A | 72,80 | 76,20 | 83,90 |
| 2009-05-29 | AT72 | A | 72,60 | 75,10 | 84,30 |
| 2009-05-29 | E170 | A | 69,50 | 71,70 | 80,60 |
| 2009-05-29 | B735 | A | 72,60 | 76,10 | 84,70 |
| 2009-05-29 | E170 | A | 70,00 | 72,00 | 81,10 |
| 2009-05-29 | AT45 | A | 71,00 | 73,10 | 82,50 |
| 2009-05-29 | B735 | A | 71,90 | 76,10 | 84,20 |
| 2009-05-29 | B738 | A | 73,20 | 77,20 | 86,20 |
| 2009-05-29 | E170 | A | 69,90 | 72,30 | 79,90 |
| 2009-05-29 | AT72 | A | 71,20 | 74,00 | 84,40 |
| 2009-05-29 | B735 | A | 72,40 | 75,70 | 83,80 |
| 2009-05-29 | B735 | A | 72,80 | 76,30 | 84,00 |
| 2009-05-29 | A320 | A | 70,50 | 72,20 | 81,90 |
| 2009-05-29 | B738 | A | 72,30 | 76,10 | 85,70 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-29 | E170 | A | 70,30 | 71,90 | 81,40 |
| 2009-05-29 | A321 | A | 72,40 | 75,50 | 84,40 |
| 2009-05-29 | AT72 | A | 72,40 | 75,10 | 83,80 |
| 2009-05-29 | E170 | A | 70,00 | 72,40 | 81,50 |
| 2009-05-29 | A320 | A | 70,20 | 72,50 | 81,00 |
| 2009-05-29 | B733 | A | 71,60 | 74,30 | 82,80 |
| 2009-05-29 | A319 | A | 70,80 | 73,00 | 82,30 |
| 2009-05-29 | CRJ2 | A | 69,40 | 71,80 | 79,40 |
| 2009-05-29 | A320 | A | 70,60 | 72,70 | 82,00 |
| 2009-05-29 | AT72 | A | 72,40 | 75,40 | 84,20 |
| 2009-05-29 | E170 | A | 70,00 | 71,20 | 80,00 |
| 2009-05-29 | AT45 | A | 70,10 | 72,20 | 80,50 |
| 2009-05-29 | E170 | A | 71,20 | 73,50 | 82,90 |
| 2009-05-29 | RJ85 | A | 69,70 | 71,20 | 80,10 |
| 2009-05-29 | E170 | A | 70,40 | 72,00 | 81,10 |
| 2009-05-29 | E170 | A | 70,30 | 75,00 | 84,20 |
| 2009-05-29 | AT45 | A | 70,10 | 72,70 | 82,40 |
| 2009-05-29 | B738 | A | 73,80 | 78,10 | 86,60 |
| 2009-05-29 | E190 | A | 72,50 | 75,30 | 83,60 |
| 2009-05-29 | B733 | A | 72,50 | 75,10 | 84,50 |
| 2009-05-29 | A320 | A | 71,00 | 73,00 | 82,10 |
| 2009-05-29 | A320 | A | 71,40 | 74,10 | 83,80 |
| 2009-05-29 | AT72 | A | 73,20 | 76,00 | 85,20 |
| 2009-05-29 | CRJ2 | A | 69,30 | 71,00 | 79,30 |
| 2009-05-29 | B763 | A | 73,60 | 77,00 | 86,10 |
| 2009-05-29 | A319 | A | 71,90 | 74,40 | 83,30 |
| 2009-05-29 | AT72 | A | 71,50 | 73,00 | 82,90 |
| 2009-05-29 | A320 | A | 71,80 | 76,90 | 87,30 |
| 2009-05-29 | A320 | A | 71,00 | 73,20 | 82,70 |
| 2009-05-29 | B763 | A | 73,10 | 76,70 | 86,90 |
| 2009-05-29 | E170 | A | 69,80 | 71,60 | 80,90 |
| 2009-05-29 | B734 | A | 73,10 | 76,40 | 84,50 |
| 2009-05-29 | F100 | A | 69,70 | 71,20 | 80,10 |
| 2009-05-29 | B735 | A | 71,00 | 72,60 | 82,10 |
| 2009-05-29 | PC12 | A | 71,30 | 73,50 | 82,40 |
| 2009-05-29 | AT72 | A | 72,90 | 75,70 | 84,70 |
| 2009-05-29 | DH8D | A | 71,80 | 74,20 | 83,00 |
| 2009-05-29 | AT72 | A | 72,20 | 74,80 | 84,20 |
| 2009-05-29 | A319 | A | 71,60 | 73,70 | 82,70 |
| 2009-05-29 | AT45 | A | 71,10 | 73,40 | 82,90 |
| 2009-05-29 | A320 | A | 72,00 | 74,10 | 83,50 |
| 2009-05-29 | E170 | A | 70,80 | 73,40 | 82,30 |
| 2009-05-29 | B734 | A | 73,20 | 76,40 | 84,00 |
| 2009-05-29 | B734 | A | 74,00 | 77,70 | 85,80 |
| 2009-05-29 | E170 | A | 70,00 | 72,60 | 81,40 |
| 2009-05-29 | E170 | A | 70,70 | 72,90 | 81,80 |
| 2009-05-29 | AT72 | A | 73,10 | 75,90 | 84,80 |
| 2009-05-29 | E170 | A | 69,90 | 71,90 | 80,30 |
| 2009-05-29 | B734 | A | 72,70 | 76,30 | 83,80 |
| 2009-05-29 | E170 | A | 70,30 | 72,50 | 80,70 |
| 2009-05-29 | AT72 | A | 74,00 | 76,40 | 85,80 |
| 2009-05-29 | AT72 | A | 73,40 | 76,20 | 85,70 |
| 2009-05-29 | B734 | A | 71,90 | 73,60 | 82,70 |
| 2009-05-29 | E170 | A | 70,70 | 72,50 | 81,40 |
| 2009-05-29 | A319 | A | 70,10 | 72,10 | 80,50 |
| 2009-05-29 | E170 | A | 70,80 | 73,10 | 81,60 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-29 | YK40 | A | 72,00 | 75,80 | 82,40 |
| 2009-05-29 | B738 | A | 71,70 | 75,10 | 83,20 |
| 2009-05-29 | CRJ9 | A | 70,00 | 71,90 | 80,40 |
| 2009-05-29 | A320 | A | 70,30 | 71,90 | 81,10 |
| 2009-05-29 | B737 | A | 72,20 | 75,10 | 84,00 |
| 2009-05-29 | AT45 | A | 70,00 | 72,60 | 81,20 |
| 2009-05-29 | B735 | A | 72,10 | 76,10 | 83,60 |
| 2009-05-29 | A321 | A | 70,70 | 72,60 | 81,80 |
| 2009-05-29 | RJ1H | A | 71,60 | 74,00 | 82,40 |
| 2009-05-29 | E170 | A | 71,70 | 74,90 | 84,70 |
| 2009-05-29 | A320 | A | 70,00 | 72,40 | 81,20 |
| 2009-05-29 | A320 | A | 70,30 | 72,20 | 81,10 |
| 2009-05-29 | A318 | A | 70,80 | 73,00 | 81,20 |
| 2009-05-29 | B735 | A | 70,10 | 71,10 | 80,50 |
| 2009-05-29 | AT72 | A | 73,30 | 76,70 | 86,10 |
| 2009-05-29 | MD11 | A | 77,30 | 82,30 | 91,50 |
| 2009-05-29 | B735 | A | 71,60 | 74,90 | 83,10 |
| 2009-05-29 | E170 | A | 70,00 | 71,80 | 80,70 |
| 2009-05-29 | A320 | A | 72,40 | 75,50 | 85,10 |
| 2009-05-29 | AT72 | A | 73,40 | 75,40 | 85,20 |
| 2009-05-29 | E145 | A | 68,60 | 69,90 | 78,60 |
| 2009-05-29 | B737 | A | 71,20 | 73,70 | 83,00 |
| 2009-05-29 | E170 | A | 69,90 | 71,70 | 80,30 |
| 2009-05-29 | AT72 | A | 71,50 | 74,00 | 83,50 |
| 2009-05-29 | E170 | A | 69,90 | 71,60 | 81,00 |
| 2009-05-29 | B735 | A | 72,50 | 75,40 | 83,30 |
| 2009-05-29 | YK40 | A | 71,20 | 73,30 | 81,60 |
| 2009-05-29 | F100 | A | 69,60 | 71,10 | 80,40 |
| 2009-05-29 | B733 | A | 73,00 | 76,60 | 84,70 |
| 2009-05-29 | YK40 | A | 70,30 | 72,20 | 80,70 |
| 2009-05-29 | CRJ7 | A | 69,70 | 71,60 | 80,40 |
| 2009-05-29 | B752 | A | 72,80 | 74,60 | 84,50 |
| 2009-05-29 | E170 | A | 70,00 | 71,60 | 80,80 |
| 2009-05-29 | B737 | A | 70,30 | 72,20 | 81,40 |
| 2009-05-29 | E170 | A | 69,90 | 71,40 | 80,30 |
| 2009-05-29 | A320 | A | 70,60 | 72,60 | 82,30 |
| 2009-05-29 | E170 | A | 69,10 | 70,80 | 79,60 |
| 2009-05-29 | B735 | A | 70,40 | 72,30 | 81,50 |
| 2009-05-29 | B734 | A | 71,30 | 73,00 | 82,40 |
| 2009-05-29 | E170 | A | 69,60 | 71,90 | 80,80 |
| 2009-05-29 | E170 | A | 70,20 | 72,40 | 80,60 |
| 2009-05-29 | B752 | A | 73,00 | 75,80 | 86,20 |
| 2009-05-29 | E170 | A | 69,30 | 70,90 | 79,70 |
| 2009-05-29 | B734 | A | 72,40 | 77,00 | 84,20 |
| 2009-05-29 | AT72 | A | 71,30 | 73,30 | 83,60 |
| 2009-05-29 | B735 | A | 72,40 | 75,50 | 83,20 |
| 2009-05-29 | B733 | A | 70,50 | 72,10 | 81,30 |
| 2009-05-29 | E170 | A | 70,40 | 71,80 | 80,80 |
| 2009-05-29 | AT72 | A | 73,30 | 75,30 | 84,80 |
| 2009-05-29 | AT45 | A | 69,40 | 71,80 | 81,40 |
| 2009-05-29 | B735 | A | 70,10 | 72,20 | 81,60 |
| 2009-05-29 | B733 | A | 73,10 | 77,70 | 84,20 |
| 2009-05-30 | E170 | A | 70,80 | 72,40 | 82,00 |
| 2009-05-30 | E170 | A | 71,60 | 74,40 | 83,60 |
| 2009-05-30 | E170 | A | 69,20 | 70,40 | 80,00 |
| 2009-05-30 | AT72 | A | 72,40 | 75,10 | 84,70 |

| | | | | | |
|------------|------|---|-------|-------------------------------|-------|
| 2009-05-30 | B734 | A | 72,10 | 77,00 | 83,60 |
| 2009-05-30 | AT72 | A | 71,00 | 74,40 | 84,00 |
| 2009-05-30 | B734 | A | 72,80 | 76,50 | 85,10 |
| 2009-05-30 | AT72 | A | 72,50 | 75,70 | 84,50 |
| 2009-05-30 | B735 | D | 68,40 | 71,10 | 80,40 |
| 2009-05-30 | A320 | D | 67,60 | 68,80 | 78,40 |
| 2009-05-30 | A320 | D | 70,20 | 72,50 | 82,50 |
| 2009-05-30 | B763 | D | 72,00 | 75,30 | 83,80 |
| 2009-05-30 | B763 | D | 72,30 | 74,20 | 84,80 |
| 2009-05-30 | E170 | D | 68,90 | 70,20 | 79,70 |
| 2009-05-30 | B763 | D | 72,10 | 75,20 | 84,80 |
| 2009-05-30 | B763 | D | 71,30 | 73,50 | 84,10 |
| 2009-05-30 | B734 | D | 69,60 | 71,90 | 81,00 |
| 2009-05-30 | B734 | D | 69,30 | 72,00 | 81,40 |
| 2009-05-31 | B734 | D | 67,90 | 69,90 | 80,40 |
| 2009-05-31 | B703 | D | 77,60 | 82,60 | 93,00 |
| 2009-05-31 | A320 | D | 68,40 | 69,70 | 79,50 |
| 2009-05-31 | E170 | D | 69,10 | 71,30 | 79,90 |
| 2009-05-31 | B734 | D | 68,40 | 70,20 | 78,40 |
| 2009-05-31 | B735 | D | 67,40 | 68,50 | 78,50 |
| 2009-05-31 | B763 | D | 71,80 | 75,40 | 85,40 |
| 2009-05-31 | B763 | D | 71,60 | 75,00 | 84,80 |
| 2009-05-31 | A320 | D | 69,20 | 71,90 | 81,50 |
| 2009-05-31 | B738 | D | 68,10 | 70,30 | 81,40 |
| 2009-05-31 | B733 | D | 68,90 | 70,40 | 81,00 |
| 2009-05-31 | A320 | D | 67,90 | 69,20 | 79,40 |
| 2009-05-31 | B733 | D | 69,20 | 71,30 | 81,50 |
| 2009-05-31 | B735 | D | 68,70 | 70,60 | 80,50 |
| 2009-05-31 | B763 | D | 71,50 | 75,90 | 85,10 |
| 2009-05-31 | E190 | D | 67,90 | 70,20 | 79,30 |
| | | | | Srednia L _{AE} | 83,24 |
| | | | | Odchylenie stand. σ | 2,54 |
| | | | | Przedział ufności Δ | 0,11 |

Poziom równowazny dla pory dnia: L_{Aeq}, LT = 56,46 dB.

Pora nocna

| Data | samolot | operacja* | L _{Aeq} | L _{Amax} | L _{AE} |
|------------|---------|-----------|------------------|-------------------|-----------------|
| 2009-05-01 | E170 | A | 70,00 | 71,60 | 80,00 |
| 2009-05-01 | B733 | A | 70,20 | 71,60 | 80,20 |
| 2009-05-01 | A320 | A | 68,90 | 70,50 | 78,90 |
| 2009-05-01 | A320 | A | 69,50 | 71,00 | 79,50 |
| 2009-05-02 | B738 | A | 71,70 | 74,30 | 82,90 |
| 2009-05-02 | B735 | A | 71,60 | 74,10 | 81,60 |
| 2009-05-02 | B735 | D | 68,90 | 70,00 | 78,50 |
| 2009-05-03 | B738 | A | 72,10 | 74,50 | 83,30 |
| 2009-05-03 | AT43 | A | 68,80 | 70,60 | 80,30 |
| 2009-05-03 | B734 | A | 71,50 | 73,90 | 82,20 |
| 2009-05-03 | B733 | A | 71,40 | 73,90 | 81,80 |
| 2009-05-04 | B752 | A | 72,10 | 74,30 | 82,90 |
| 2009-05-04 | AN12 | A | 76,20 | 80,60 | 88,00 |
| 2009-05-04 | B733 | A | 73,60 | 76,40 | 84,70 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-04 | E170 | A | 69,10 | 70,90 | 78,10 |
| 2009-05-04 | B462 | A | 70,60 | 72,00 | 79,00 |
| 2009-05-08 | B734 | D | 72,10 | 75,20 | 84,60 |
| 2009-05-08 | B734 | D | 70,60 | 73,00 | 82,90 |
| 2009-05-09 | B738 | A | 71,10 | 73,70 | 82,60 |
| 2009-05-09 | E170 | A | 69,00 | 71,60 | 79,80 |
| 2009-05-09 | B734 | A | 71,00 | 72,80 | 81,50 |
| 2009-05-09 | A320 | A | 71,00 | 72,60 | 81,70 |
| 2009-05-09 | A320 | A | 70,10 | 71,80 | 80,10 |
| 2009-05-10 | B738 | A | 72,20 | 74,60 | 83,00 |
| 2009-05-10 | AT43 | A | 71,30 | 73,70 | 81,70 |
| 2009-05-10 | B734 | A | 72,70 | 75,50 | 82,70 |
| 2009-05-10 | B733 | A | 72,70 | 74,70 | 82,70 |
| 2009-05-10 | E170 | A | 71,30 | 73,70 | 82,50 |
| 2009-05-10 | A320 | A | 70,30 | 72,80 | 82,60 |
| 2009-05-10 | A320 | A | 70,80 | 72,50 | 81,90 |
| 2009-05-11 | B752 | A | 73,30 | 76,20 | 86,10 |
| 2009-05-11 | B462 | A | 73,20 | 75,60 | 83,60 |
| 2009-05-11 | E170 | A | 69,70 | 71,20 | 80,10 |
| 2009-05-11 | B738 | A | 70,90 | 73,20 | 82,40 |
| 2009-05-11 | B735 | A | 72,80 | 76,60 | 84,20 |
| 2009-05-11 | AN26 | A | 72,40 | 76,70 | 83,90 |
| 2009-05-14 | E170 | A | 69,40 | 70,80 | 79,80 |
| 2009-05-14 | E170 | A | 68,70 | 70,20 | 78,70 |
| 2009-05-14 | AN26 | A | 73,30 | 77,10 | 84,10 |
| 2009-05-14 | AT72 | A | 69,60 | 71,20 | 80,40 |
| 2009-05-14 | AT72 | A | 70,70 | 73,40 | 82,50 |
| 2009-05-14 | B734 | A | 72,30 | 75,30 | 83,10 |
| 2009-05-14 | B733 | A | 72,10 | 75,20 | 83,30 |
| 2009-05-14 | AT72 | A | 70,90 | 73,10 | 82,90 |
| 2009-05-14 | B734 | A | 71,70 | 75,00 | 82,50 |
| 2009-05-14 | A320 | A | 69,60 | 71,40 | 80,40 |
| 2009-05-14 | B735 | A | 70,70 | 72,40 | 81,90 |
| 2009-05-14 | A320 | A | 69,50 | 71,10 | 80,20 |
| 2009-05-14 | A320 | A | 69,70 | 71,50 | 80,50 |
| 2009-05-14 | P180 | A | 74,10 | 79,00 | 87,10 |
| 2009-05-14 | AN26 | D | 76,70 | 81,40 | 88,50 |
| 2009-05-15 | C295 | A | 70,20 | 72,00 | 80,70 |
| 2009-05-15 | B734 | A | 71,10 | 73,90 | 81,90 |
| 2009-05-15 | B734 | A | 73,10 | 76,10 | 84,20 |
| 2009-05-15 | E170 | A | 69,00 | 71,00 | 79,40 |
| 2009-05-15 | MD11 | A | 76,10 | 80,30 | 89,30 |
| 2009-05-15 | B734 | A | 72,10 | 75,20 | 82,50 |
| 2009-05-15 | B733 | A | 70,90 | 72,30 | 80,90 |
| 2009-05-15 | B733 | A | 72,70 | 74,70 | 83,50 |
| 2009-05-15 | AT72 | A | 69,20 | 71,10 | 80,00 |
| 2009-05-15 | A320 | A | 69,10 | 70,70 | 79,50 |
| 2009-05-15 | A320 | A | 69,20 | 70,70 | 80,40 |
| 2009-05-15 | A320 | A | 69,60 | 71,20 | 79,60 |
| 2009-05-15 | B734 | A | 72,40 | 76,20 | 82,80 |
| 2009-05-15 | YK40 | A | 70,30 | 71,40 | 78,80 |
| 2009-05-16 | B738 | A | 71,80 | 73,80 | 82,20 |
| 2009-05-16 | E170 | A | 69,90 | 71,60 | 79,90 |
| 2009-05-16 | A320 | A | 70,60 | 74,30 | 83,70 |
| 2009-05-16 | A320 | A | 71,60 | 74,70 | 83,60 |
| 2009-05-16 | E170 | A | 69,50 | 71,80 | 80,90 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-16 | E145 | A | 69,00 | 70,80 | 79,80 |
| 2009-05-16 | A320 | A | 70,70 | 73,70 | 82,10 |
| 2009-05-17 | B738 | A | 71,30 | 75,10 | 83,90 |
| 2009-05-17 | AT43 | A | 68,60 | 70,10 | 80,90 |
| 2009-05-17 | B733 | A | 70,80 | 72,40 | 81,90 |
| 2009-05-17 | B734 | A | 73,00 | 76,80 | 85,30 |
| 2009-05-17 | B734 | A | 73,00 | 76,20 | 83,40 |
| 2009-05-17 | A320 | A | 71,30 | 73,20 | 82,10 |
| 2009-05-17 | A320 | A | 69,90 | 71,70 | 80,30 |
| 2009-05-17 | B734 | A | 72,30 | 75,40 | 82,80 |
| 2009-05-17 | A320 | A | 73,70 | 76,00 | 84,90 |
| 2009-05-18 | B752 | A | 81,10 | 86,10 | 93,40 |
| 2009-05-18 | B752 | A | 73,00 | 75,90 | 85,00 |
| 2009-05-18 | B733 | A | 72,20 | 75,00 | 82,60 |
| 2009-05-18 | E170 | A | 69,90 | 71,90 | 79,90 |
| 2009-05-18 | B738 | A | 72,40 | 74,40 | 83,20 |
| 2009-05-18 | E170 | A | 69,50 | 71,10 | 79,50 |
| 2009-05-18 | A320 | A | 70,60 | 72,50 | 81,10 |
| 2009-05-19 | T154 | A | 74,40 | 77,60 | 86,50 |
| 2009-05-19 | B738 | A | 73,50 | 76,70 | 85,80 |
| 2009-05-19 | B733 | A | 71,10 | 72,60 | 81,90 |
| 2009-05-19 | MD11 | A | 78,10 | 82,30 | 91,40 |
| 2009-05-19 | B738 | A | 71,80 | 74,20 | 83,30 |
| 2009-05-19 | B733 | A | 71,90 | 74,90 | 83,00 |
| 2009-05-19 | AT72 | A | 68,10 | 69,20 | 78,90 |
| 2009-05-19 | AT72 | A | 70,90 | 73,50 | 82,60 |
| 2009-05-19 | A320 | A | 70,70 | 72,40 | 82,20 |
| 2009-05-19 | A320 | A | 73,20 | 76,70 | 86,00 |
| 2009-05-19 | B735 | A | 71,80 | 74,30 | 82,20 |
| 2009-05-19 | E170 | A | 71,20 | 72,40 | 81,90 |
| 2009-05-19 | A320 | A | 69,80 | 71,90 | 81,00 |
| 2009-05-20 | B738 | A | 72,50 | 74,80 | 83,60 |
| 2009-05-20 | B733 | A | 72,70 | 75,30 | 83,80 |
| 2009-05-20 | MD11 | A | 77,90 | 82,40 | 91,50 |
| 2009-05-20 | E170 | A | 69,40 | 71,20 | 80,20 |
| 2009-05-20 | E170 | A | 69,10 | 71,30 | 79,50 |
| 2009-05-20 | B737 | A | 70,80 | 72,80 | 81,20 |
| 2009-05-20 | B733 | A | 70,60 | 72,00 | 80,60 |
| 2009-05-20 | AT72 | A | 71,80 | 74,10 | 83,00 |
| 2009-05-20 | A320 | A | 69,50 | 71,30 | 79,50 |
| 2009-05-20 | B734 | A | 72,90 | 76,00 | 84,40 |
| 2009-05-20 | A320 | A | 69,70 | 71,80 | 79,70 |
| 2009-05-20 | AN26 | D | 69,60 | 71,30 | 79,20 |
| 2009-05-20 | A320 | A | 69,70 | 71,20 | 79,70 |
| 2009-05-20 | B734 | D | 69,80 | 71,90 | 82,10 |
| 2009-05-21 | B738 | A | 71,30 | 73,20 | 81,70 |
| 2009-05-21 | MD11 | A | 77,20 | 81,60 | 90,20 |
| 2009-05-21 | E170 | A | 68,80 | 69,90 | 77,20 |
| 2009-05-21 | E170 | A | 69,50 | 71,60 | 79,90 |
| 2009-05-21 | E170 | D | 68,90 | 70,50 | 79,30 |
| 2009-05-21 | B735 | D | 68,90 | 70,40 | 80,30 |
| 2009-05-22 | MD11 | A | 76,30 | 80,70 | 89,80 |
| 2009-05-22 | AT72 | A | 72,60 | 75,10 | 85,40 |
| 2009-05-22 | AT72 | A | 73,30 | 76,50 | 86,10 |
| 2009-05-22 | A320 | A | 70,80 | 73,20 | 82,30 |
| 2009-05-22 | B735 | A | 72,60 | 75,40 | 84,70 |

| | | | | | |
|------------|------|---|-------|-------|-------|
| 2009-05-22 | A320 | A | 71,50 | 73,20 | 83,00 |
| 2009-05-22 | A320 | A | 71,00 | 73,40 | 82,10 |
| 2009-05-22 | B738 | A | 67,80 | 68,50 | 76,20 |
| 2009-05-23 | B738 | A | 73,60 | 76,50 | 85,00 |
| 2009-05-23 | E170 | A | 69,60 | 71,70 | 81,10 |
| 2009-05-23 | A320 | A | 70,70 | 73,60 | 82,40 |
| 2009-05-23 | E170 | A | 70,30 | 73,20 | 81,50 |
| 2009-05-23 | A320 | A | 71,60 | 74,10 | 83,60 |
| 2009-05-23 | B734 | D | 70,80 | 73,20 | 83,40 |
| 2009-05-24 | B752 | D | 72,10 | 76,50 | 85,50 |
| 2009-05-24 | B738 | A | 72,10 | 75,60 | 85,80 |
| 2009-05-24 | B734 | A | 72,10 | 74,30 | 83,80 |
| 2009-05-24 | AT43 | A | 73,50 | 77,50 | 86,50 |
| 2009-05-24 | B733 | A | 71,60 | 74,30 | 83,10 |
| 2009-05-24 | AT72 | A | 70,40 | 72,50 | 81,20 |
| 2009-05-24 | A320 | A | 70,70 | 73,10 | 82,70 |
| 2009-05-24 | B738 | A | 70,20 | 72,40 | 81,00 |
| 2009-05-24 | A320 | A | 70,20 | 72,10 | 80,60 |
| 2009-05-24 | B734 | A | 71,70 | 74,70 | 82,90 |
| 2009-05-24 | A320 | A | 69,50 | 71,20 | 80,30 |
| 2009-05-25 | B752 | A | 73,90 | 77,50 | 87,30 |
| 2009-05-25 | B733 | A | 70,40 | 72,20 | 80,40 |
| 2009-05-25 | B463 | A | 69,00 | 70,10 | 79,00 |
| 2009-05-25 | B734 | A | 73,20 | 76,50 | 84,70 |
| 2009-05-25 | B735 | A | 70,60 | 73,50 | 81,40 |
| 2009-05-25 | A320 | A | 69,20 | 70,80 | 79,60 |
| 2009-05-25 | A320 | A | 69,10 | 69,80 | 80,20 |
| 2009-05-25 | E170 | A | 68,90 | 70,40 | 78,90 |
| 2009-05-25 | A320 | A | 71,00 | 73,00 | 82,20 |
| 2009-05-26 | B738 | A | 71,90 | 74,10 | 82,40 |
| 2009-05-26 | B733 | A | 71,90 | 73,60 | 82,30 |
| 2009-05-26 | E170 | D | 69,60 | 71,00 | 79,60 |
| 2009-05-27 | AN26 | A | 72,50 | 75,10 | 82,90 |
| 2009-05-27 | AT45 | A | 68,00 | 69,40 | 79,10 |
| 2009-05-27 | AT72 | A | 69,40 | 70,80 | 79,80 |
| 2009-05-27 | B733 | A | 72,20 | 75,60 | 84,20 |
| 2009-05-27 | A320 | A | 71,00 | 73,40 | 82,40 |
| 2009-05-27 | A320 | A | 70,90 | 72,90 | 82,30 |
| 2009-05-27 | B734 | A | 73,10 | 77,00 | 84,60 |
| 2009-05-27 | A320 | A | 70,70 | 72,30 | 82,10 |
| 2009-05-27 | E170 | A | 70,30 | 72,60 | 81,70 |
| 2009-05-27 | YK40 | A | 71,90 | 75,40 | 83,70 |
| 2009-05-28 | B738 | A | 71,70 | 74,20 | 82,80 |
| 2009-05-28 | E170 | A | 69,00 | 70,50 | 79,80 |
| 2009-05-28 | MD11 | A | 75,40 | 78,70 | 88,40 |
| 2009-05-28 | SF34 | A | 68,90 | 70,40 | 78,90 |
| 2009-05-28 | AT72 | A | 72,30 | 75,50 | 85,30 |
| 2009-05-28 | B733 | A | 73,30 | 78,00 | 86,50 |
| 2009-05-28 | AN26 | A | 72,60 | 76,40 | 84,30 |
| 2009-05-28 | SF34 | A | 69,70 | 72,00 | 80,10 |
| 2009-05-28 | AT72 | A | 69,80 | 72,20 | 83,20 |
| 2009-05-28 | B735 | A | 74,00 | 78,90 | 87,00 |
| 2009-05-28 | AN26 | A | 72,80 | 76,70 | 84,80 |
| 2009-05-28 | A320 | A | 70,40 | 73,30 | 83,80 |
| 2009-05-28 | A320 | A | 71,30 | 73,70 | 83,90 |
| 2009-05-28 | A320 | A | 71,80 | 74,30 | 84,10 |

| | | | | | |
|------------|------|---|-------|-------------------------------|-------|
| 2009-05-28 | E170 | A | 71,60 | 74,80 | 84,40 |
| 2009-05-29 | E170 | A | 72,10 | 76,70 | 84,40 |
| 2009-05-29 | MD11 | A | 78,30 | 83,60 | 92,50 |
| 2009-05-29 | SF34 | A | 68,30 | 69,40 | 77,90 |
| 2009-05-29 | E170 | A | 69,60 | 71,50 | 80,00 |
| 2009-05-29 | E170 | A | 69,80 | 71,50 | 80,20 |
| 2009-05-29 | AT72 | A | 73,70 | 76,70 | 85,40 |
| 2009-05-29 | B733 | A | 70,40 | 72,10 | 81,60 |
| 2009-05-29 | B738 | A | 71,60 | 73,60 | 82,80 |
| 2009-05-29 | CRJ2 | A | 69,20 | 71,10 | 79,20 |
| 2009-05-29 | A320 | A | 70,10 | 71,30 | 80,90 |
| 2009-05-29 | B735 | A | 71,50 | 74,50 | 82,70 |
| 2009-05-29 | A320 | A | 69,90 | 71,70 | 81,10 |
| 2009-05-29 | A320 | A | 69,90 | 71,60 | 80,70 |
| 2009-05-30 | AN28 | A | 72,50 | 75,90 | 83,60 |
| 2009-05-30 | B738 | A | 72,70 | 75,00 | 84,20 |
| 2009-05-30 | B735 | D | 69,10 | 71,30 | 80,20 |
| 2009-05-31 | E170 | D | 68,10 | 69,20 | 79,20 |
| 2009-05-31 | B734 | D | 69,10 | 71,00 | 80,50 |
| | | | | Średnia L _{AE} | 83,62 |
| | | | | Odchylenie stand. σ | 3,02 |
| | | | | Przedział ufności Δ | 0,42 |

Poziom równoważny dla pory nocy: L_{Aeq} , $LT = 50,05$ dB.