



Świadectwo legalizacji nr 3830-LB12-431-450.3/1042/TW/06 wydane dnia 26.09.2006 r. przez Prezesa Głównego Urzędu Miar w Warszawie, ważne do dnia 30.09.2008 r.

Wzorzec akustyczny (producent; nr typu) Brüel & Kjær; 4228.

**Oznaczenia:**

A - lądowanie

D - start

**Pora dnia**

Data	samolot	operacja	L <sub>Aeq</sub>	L <sub>Amax</sub>	L <sub>AE</sub>
01-04-2008	MD11	D	74,40	78,20	89,30
01-04-2008	A321	D	69,50	71,60	82,10
01-04-2008	B735	D	70,40	72,90	82,50
01-04-2008	E170	D	67,40	68,80	79,90
01-04-2008	E170	D	68,70	72,50	84,50
01-04-2008	B735	D	69,70	71,70	82,00
01-04-2008	E170	D	68,30	69,80	79,70
01-04-2008	T154	D	75,20	79,10	89,50
01-04-2008	B735	D	70,60	73,00	83,20
01-04-2008	E170	D	67,70	69,90	80,50
01-04-2008	B733	D	70,80	73,30	83,30
01-04-2008	RJ1H	D	68,30	70,50	80,80
01-04-2008	E170	A	69,30	70,80	80,10
01-04-2008	E190	A	72,40	75,00	83,90
01-04-2008	F900	A	69,80	72,10	81,90
01-04-2008	B738	A	72,20	74,90	83,90
01-04-2008	AT72	A	70,90	72,80	80,90
01-04-2008	AT72	A	71,40	73,80	83,20
01-04-2008	A320	A	70,70	72,90	81,90
01-04-2008	A319	A	70,80	73,00	81,90
01-04-2008	E170	A	71,00	73,00	82,20
01-04-2008	E170	A	71,40	73,30	81,80
01-04-2008	AT45	A	70,50	71,50	80,90
01-04-2008	E170	A	70,50	72,40	81,30
01-04-2008	AT45	A	71,00	73,00	82,20
01-04-2008	B734	A	73,20	77,30	84,60
01-04-2008	B735	A	73,40	77,70	84,20
01-04-2008	E170	A	71,70	74,30	83,40
01-04-2008	AT72	A	73,00	75,90	84,10
01-04-2008	B734	A	72,90	75,50	84,70
01-04-2008	DH8D	A	71,30	73,10	81,70
01-04-2008	AT72	A	67,50	68,30	77,90
01-04-2008	E170	A	70,80	73,10	82,30
01-04-2008	E170	A	71,50	73,70	83,30
01-04-2008	E170	A	72,20	74,40	82,60
01-04-2008	A321	A	70,30	71,90	81,10
01-04-2008	B734	A	71,40	73,10	82,20
01-04-2008	E170	A	70,90	72,70	81,30
01-04-2008	A319	A	71,30	73,60	82,70
01-04-2008	AT72	A	72,70	74,70	83,50

01-04-2008	E170	A	71,20	73,10	82,00
01-04-2008	B735	A	72,50	74,80	83,70
01-04-2008	A319	A	70,30	73,00	81,70
01-04-2008	B737	A	70,90	73,40	83,20
01-04-2008	AT45	A	70,50	72,50	80,90
01-04-2008	P180	A	75,90	80,40	90,10
01-04-2008	B733	A	72,10	75,60	83,60
01-04-2008	A321	A	72,10	74,30	83,60
01-04-2008	A320	A	71,30	73,40	82,80
01-04-2008	RJ85	A	68,40	70,30	78,90
01-04-2008	B734	A	71,70	74,60	83,50
01-04-2008	AT72	A	71,10	73,10	81,90
01-04-2008	E170	A	70,30	71,70	80,70
01-04-2008	AT45	A	69,70	70,50	79,70
01-04-2008	B735	A	73,70	77,30	84,10
01-04-2008	B733	A	71,50	74,20	82,30
01-04-2008	B735	A	72,10	73,90	82,90
01-04-2008	E190	A	71,50	74,40	82,90
01-04-2008	A318	A	71,40	74,00	82,80
01-04-2008	AT72	A	73,00	75,80	84,50
01-04-2008	A320	A	70,40	72,50	81,60
01-04-2008	AT72	A	71,80	73,60	82,90
01-04-2008	B733	A	72,20	74,30	83,30
01-04-2008	E170	A	70,20	72,20	81,00
01-04-2008	F70	A	69,00	70,10	79,00
01-04-2008	AT45	A	70,50	72,30	81,70
01-04-2008	B735	A	72,20	75,60	84,20
01-04-2008	E170	A	69,50	71,10	80,30
01-04-2008	E170	A	69,30	70,90	79,70
01-04-2008	B735	A	70,70	72,10	81,50
01-04-2008	F100	A	69,30	70,90	79,70
01-04-2008	AT72	A	71,40	73,00	81,80
01-04-2008	MD11	A	77,30	82,00	91,10
01-04-2008	B734	A	72,60	75,50	83,70
01-04-2008	B736	A	71,00	72,30	82,10
01-04-2008	CRJ2	A	68,80	70,10	78,80
01-04-2008	CRJ2	A	66,10	73,00	76,90
01-04-2008	B738	A	71,90	74,30	83,40
01-04-2008	B735	A	72,70	75,00	83,50
01-04-2008	E170	A	69,80	71,60	79,80
01-04-2008	B752	A	71,10	73,80	82,80
01-04-2008	B738	A	72,90	74,90	83,70
01-04-2008	AT45	A	70,30	71,70	80,70
01-04-2008	E170	A	69,70	71,20	79,70
01-04-2008	A320	A	72,30	74,90	83,50
01-04-2008	B737	A	71,30	73,50	82,10
01-04-2008	A320	A	71,80	74,20	83,00
01-04-2008	E170	A	70,80	72,60	81,20
01-04-2008	B738	A	73,10	76,00	84,90
01-04-2008	B735	A	72,80	78,20	85,10
01-04-2008	E170	A	69,40	70,90	79,80
01-04-2008	B735	A	71,30	73,50	82,00
01-04-2008	E170	A	69,10	71,10	79,10
01-04-2008	E170	A	70,60	72,10	81,10
01-04-2008	B735	A	72,50	74,70	83,20
01-04-2008	E170	A	70,00	71,80	80,00

01-04-2008	AT72	A	70,90	72,60	81,70
01-04-2008	E170	A	70,20	72,00	80,70
01-04-2008	E145	A	68,40	69,90	78,40
01-04-2008	C25A	A	70,50	77,60	80,90
01-04-2008	AT72	A	71,20	72,90	82,30
01-04-2008	AT45	A	70,50	72,00	80,50
01-04-2008	E170	A	71,00	73,20	82,10
01-04-2008	B735	A	72,60	76,10	83,40
01-04-2008	E170	A	69,80	70,90	80,20
01-04-2008	B733	A	71,70	73,20	82,50
01-04-2008	AT72	A	68,90	71,10	80,40
02-04-2008	B735	A	71,50	73,40	82,30
02-04-2008	AT45	A	70,60	72,30	81,00
02-04-2008	E170	A	69,50	71,40	80,00
02-04-2008	E170	A	70,10	72,60	80,90
02-04-2008	E170	A	69,70	71,60	79,70
02-04-2008	AT72	A	71,20	73,50	82,60
02-04-2008	AT72	A	72,70	74,80	84,20
02-04-2008	A320	A	72,30	74,50	83,70
02-04-2008	AT72	A	69,30	70,70	80,50
02-04-2008	AT43	A	70,70	72,30	80,70
02-04-2008	B752	A	72,90	75,30	84,90
02-04-2008	AT72	A	74,80	77,10	85,20
02-04-2008	B734	A	72,10	74,30	83,60
02-04-2008	B734	A	75,20	78,80	85,90
02-04-2008	B736	A	68,70	71,90	84,60
02-04-2008	C525	A	67,60	71,10	78,40
02-04-2008	B738	A	69,20	72,90	83,50
02-04-2008	B738	A	71,80	73,70	83,20
02-04-2008	B734	D	71,40	74,30	84,20
02-04-2008	MD11	D	78,50	84,70	93,70
02-04-2008	B735	D	70,70	73,60	82,10
02-04-2008	A320	D	69,00	71,10	81,00
02-04-2008	T154	D	74,40	79,90	89,10
02-04-2008	E170	D	70,90	73,60	83,20
02-04-2008	B733	D	71,70	76,30	84,70
02-04-2008	B735	D	69,90	72,20	80,70
02-04-2008	B762	D	73,80	79,30	88,30
02-04-2008	A320	D	70,80	74,90	85,30
02-04-2008	E170	D	68,40	71,50	81,40
02-04-2008	E170	D	68,00	70,90	81,60
02-04-2008	B763	D	74,80	78,60	88,40
02-04-2008	B763	D	72,80	76,20	87,00
02-04-2008	B738	D	70,10	72,50	83,30
02-04-2008	A320	D	71,30	73,60	83,60
02-04-2008	AN26	D	68,80	71,00	80,80
02-04-2008	B752	D	69,30	73,60	79,30
02-04-2008	E170	D	69,70	73,00	83,30
02-04-2008	T154	D	70,30	73,00	81,50
02-04-2008	B733	D	74,30	78,60	86,90
02-04-2008	B733	D	70,70	72,70	81,10
02-04-2008	B735	D	70,70	72,70	81,80
02-04-2008	MD11	D	73,40	78,70	88,40
02-04-2008	B734	D	71,70	74,60	84,00
03-04-2008	E170	A	69,70	71,50	80,50
03-04-2008	AT45	A	71,20	73,40	82,60

03-04-2008	B735	A	74,20	78,50	85,30
03-04-2008	E170	A	71,30	73,30	82,80
03-04-2008	AT72	A	70,20	72,50	82,30
03-04-2008	B734	A	74,00	77,20	85,40
03-04-2008	E170	A	70,90	73,20	82,00
03-04-2008	AT72	A	70,20	72,10	81,90
03-04-2008	AT45	A	71,10	74,10	82,80
03-04-2008	AT43	A	72,00	75,00	83,80
03-04-2008	AT72	A	71,40	73,60	83,40
03-04-2008	A320	A	71,50	73,80	82,70
03-04-2008	AT72	A	69,80	71,50	81,50
03-04-2008	B738	A	72,30	74,30	83,80
03-04-2008	B462	A	69,40	71,00	79,80
03-04-2008	A319	A	70,80	72,50	81,20
03-04-2008	JS32	A	66,70	70,20	81,30
03-04-2008	JS32	A	68,10	71,00	79,30
03-04-2008	B738	A	72,50	74,90	84,00
03-04-2008	B763	A	74,10	76,20	86,10
03-04-2008	B734	A	72,80	76,20	83,60
03-04-2008	B752	A	72,60	74,70	84,60
03-04-2008	B738	A	72,60	75,10	84,10
03-04-2008	A320	A	71,30	73,10	82,50
03-04-2008	A320	A	73,50	76,20	84,60
03-04-2008	CRJ2	A	68,90	70,80	79,30
03-04-2008	E170	A	72,10	74,90	83,30
03-04-2008	B763	A	74,10	77,30	86,40
03-04-2008	E170	A	71,80	74,00	82,90
03-04-2008	DH8D	A	69,70	70,70	79,70
03-04-2008	B737	A	73,50	78,60	85,60
03-04-2008	B762	A	75,10	78,50	88,10
03-04-2008	B735	A	72,80	77,00	84,30
03-04-2008	T154	A	74,80	77,20	86,80
03-04-2008	B735	A	74,10	77,40	85,20
03-04-2008	B733	A	72,60	74,50	83,40
03-04-2008	A319	A	71,60	74,00	82,80
03-04-2008	B735	A	73,80	77,00	84,60
03-04-2008	E170	A	70,20	72,40	81,40
03-04-2008	E170	A	70,20	72,00	80,70
03-04-2008	E170	A	69,90	72,50	81,10
03-04-2008	AT72	A	70,30	72,50	81,40
03-04-2008	E145	A	68,20	69,20	78,60
03-04-2008	AT72	A	74,20	77,10	86,20
03-04-2008	AT72	A	71,40	73,20	84,00
03-04-2008	E170	A	71,00	72,70	83,30
03-04-2008	A319	A	73,80	77,60	86,30
03-04-2008	B733	A	72,70	74,90	83,90
03-04-2008	E170	A	71,50	73,70	82,90
03-04-2008	B738	A	73,80	76,70	86,40
03-04-2008	A320	A	71,10	73,20	82,90
03-04-2008	A321	A	73,10	75,60	84,90
03-04-2008	B735	A	71,80	74,30	83,50
03-04-2008	B733	A	72,10	74,10	83,20
03-04-2008	AT72	A	74,40	77,50	86,90
03-04-2008	A320	A	74,70	79,00	87,70
03-04-2008	RJ1H	A	70,00	71,40	80,00
03-04-2008	B734	A	71,40	74,00	83,40

03-04-2008	B738	A	72,80	76,30	85,40
03-04-2008	A319	A	70,70	73,10	82,50
03-04-2008	AT45	A	71,00	72,40	81,70
03-04-2008	E170	A	71,60	73,80	83,10
03-04-2008	B734	A	73,60	78,60	85,10
03-04-2008	E170	A	72,20	74,40	83,00
03-04-2008	B462	A	70,80	72,00	81,20
03-04-2008	MD82	A	72,30	75,20	84,80
03-04-2008	A320	A	71,10	73,10	82,90
03-04-2008	RJ85	A	69,90	71,20	81,00
03-04-2008	E170	A	69,30	71,30	80,50
03-04-2008	E170	A	70,90	72,60	81,70
03-04-2008	AT72	A	74,40	77,50	86,20
03-04-2008	E170	A	72,10	74,20	83,20
03-04-2008	E190	A	72,60	75,10	83,40
03-04-2008	B461	A	70,90	72,30	81,70
03-04-2008	A320	A	71,60	74,70	84,40
03-04-2008	A319	A	72,10	73,90	84,20
03-04-2008	F100	A	70,70	72,00	81,10
03-04-2008	AT72	A	71,70	74,40	84,30
03-04-2008	B735	A	73,00	75,10	84,50
03-04-2008	B762	A	74,00	76,00	86,60
03-04-2008	E170	A	70,70	74,00	83,00
03-04-2008	E170	A	71,20	73,20	82,90
03-04-2008	CRJ2	A	69,80	72,00	80,90
03-04-2008	AT72	A	74,90	76,90	86,60
03-04-2008	T154	A	76,20	80,50	89,40
03-04-2008	E170	A	71,40	74,20	83,10
03-04-2008	AT45	A	71,70	73,30	83,50
03-04-2008	DH8D	A	70,10	71,40	80,50
03-04-2008	B752	A	72,80	76,50	85,80
03-04-2008	B735	A	74,00	77,80	86,00
03-04-2008	B735	A	74,10	78,00	85,90
03-04-2008	E170	A	70,70	72,50	82,20
03-04-2008	B735	A	72,70	75,10	84,50
03-04-2008	E170	A	70,90	73,10	82,30
03-04-2008	E170	A	69,80	71,40	81,30
03-04-2008	E170	A	70,20	73,00	81,40
03-04-2008	AT72	A	74,40	77,30	86,50
03-04-2008	B733	A	72,10	76,50	85,80
03-04-2008	A319	A	72,60	75,00	85,20
03-04-2008	E170	A	70,40	72,20	81,50
03-04-2008	B734	A	73,50	77,50	85,30
03-04-2008	E170	A	70,20	72,10	81,30
03-04-2008	AT72	A	71,80	74,80	85,00
03-04-2008	B733	A	72,50	76,70	85,10
03-04-2008	CL30	A	71,20	73,40	82,00
03-04-2008	E145	A	67,60	70,00	78,10
03-04-2008	E145	A	70,50	76,30	87,00
03-04-2008	B735	A	72,00	74,20	84,30
03-04-2008	B737	A	71,80	74,20	83,20
03-04-2008	AT45	A	71,30	74,80	84,10
03-04-2008	B734	A	72,90	76,80	85,00
03-04-2008	A319	A	70,50	72,70	82,80
03-04-2008	AT72	A	73,90	76,50	86,70
03-04-2008	AT45	A	70,50	73,80	83,50

03-04-2008	AT72	A	69,40	71,70	81,40
03-04-2008	RJ85	A	71,00	73,70	82,20
03-04-2008	A320	A	70,80	73,00	81,90
03-04-2008	YK40	A	72,00	74,40	82,40
03-04-2008	B735	A	74,10	77,10	85,30
03-04-2008	B733	A	72,70	74,00	83,90
03-04-2008	RJ85	A	70,90	73,00	81,70
03-04-2008	MD11	A	78,20	83,70	92,80
03-04-2008	A320	A	72,90	76,10	86,90
03-04-2008	B734	A	72,80	76,90	85,60
03-04-2008	E190	A	73,10	75,40	85,60
03-04-2008	B735	A	72,60	75,60	84,30
03-04-2008	AT72	A	74,20	76,60	86,80
03-04-2008	A318	A	71,00	75,60	83,60
03-04-2008	E170	A	70,60	72,70	82,10
03-04-2008	B733	A	72,40	75,00	84,40
03-04-2008	AT72	A	74,90	77,00	86,90
03-04-2008	E170	A	70,30	72,50	81,70
03-04-2008	B733	A	71,50	73,50	83,80
03-04-2008	B735	A	73,10	75,80	84,20
03-04-2008	DH8D	A	70,40	72,20	80,80
03-04-2008	A319	A	72,00	74,30	83,50
03-04-2008	B738	A	72,30	74,50	84,30
03-04-2008	B733	A	73,40	75,50	85,20
03-04-2008	SF34	A	69,20	70,40	79,20
03-04-2008	F100	A	70,80	72,60	81,90
03-04-2008	AT72	A	74,50	76,90	86,00
03-04-2008	CRJ2	A	70,30	71,90	80,70
03-04-2008	AT45	A	71,60	73,80	82,70
03-04-2008	B735	A	73,10	76,00	84,80
03-04-2008	E170	A	70,80	72,70	82,20
03-04-2008	E170	A	70,70	72,40	82,10
03-04-2008	B738	A	73,70	75,70	84,80
03-04-2008	AT72	A	74,40	77,00	86,90
03-04-2008	AT45	A	70,90	72,60	82,00
03-04-2008	E170	A	71,10	73,10	82,80
03-04-2008	B737	A	72,20	74,70	84,50
03-04-2008	E170	A	71,00	73,00	82,20
03-04-2008	A320	A	73,10	77,20	84,90
03-04-2008	GLF4	A	69,50	70,70	81,00
03-04-2008	E170	A	70,00	71,70	81,10
03-04-2008	B735	A	74,70	78,40	87,00
03-04-2008	E145	A	69,10	69,90	79,10
03-04-2008	E170	A	70,60	72,50	81,70
03-04-2008	B733	A	73,40	77,00	85,70
03-04-2008	E170	A	70,40	72,60	81,90
03-04-2008	B735	A	73,90	77,60	85,30
03-04-2008	E170	A	71,70	73,00	82,80
03-04-2008	E170	A	71,40	73,40	83,10
03-04-2008	E170	A	70,60	72,80	81,80
03-04-2008	AT72	A	69,10	71,00	80,50
03-04-2008	B735	A	73,80	77,30	85,30
03-04-2008	AT72	A	72,40	74,30	84,40
03-04-2008	SF34	A	71,60	73,30	82,40
03-04-2008	E170	A	70,50	72,60	82,00
03-04-2008	B734	A	72,20	75,00	84,30

03-04-2008	AN26	A	72,40	75,30	83,60
04-04-2008	E170	A	70,20	72,50	81,30
04-04-2008	B733	A	73,20	76,20	84,60
04-04-2008	E170	A	69,80	71,60	80,90
04-04-2008	B735	A	73,40	77,10	85,40
04-04-2008	AT72	A	72,40	76,00	85,80
04-04-2008	E170	A	70,40	72,60	81,90
04-04-2008	E170	A	69,90	72,20	81,70
04-04-2008	E170	A	70,60	72,70	82,10
04-04-2008	AT72	A	69,10	70,40	79,90
04-04-2008	AT72	A	69,20	70,90	80,60
04-04-2008	E170	A	70,90	73,20	82,40
04-04-2008	B752	A	72,40	75,40	84,90
04-04-2008	AT43	A	71,00	73,10	82,10
04-04-2008	A320	A	71,00	72,80	82,10
04-04-2008	B463	A	69,90	72,20	81,60
04-04-2008	AT72	A	73,80	78,00	85,60
04-04-2008	A320	A	71,90	74,30	84,50
04-04-2008	A320	A	71,40	73,40	82,80
04-04-2008	B734	A	74,30	79,80	86,60
04-04-2008	A320	A	72,20	75,00	84,50
04-04-2008	RJ85	A	71,90	73,50	82,70
04-04-2008	B462	A	69,60	71,40	80,40
04-04-2008	F70	A	69,40	70,60	79,40
04-04-2008	AT72	A	72,90	75,50	85,00
04-04-2008	AT72	A	70,00	71,90	82,60
04-04-2008	B762	A	71,90	75,30	86,70
04-04-2008	CRJ2	A	69,90	71,60	81,00
04-04-2008	F100	A	70,00	71,90	82,00
04-04-2008	E190	A	71,40	74,10	84,50
04-04-2008	B738	A	73,70	77,50	87,10
04-04-2008	B735	A	73,70	77,90	86,20
04-04-2008	B735	A	74,40	80,00	86,70
04-04-2008	DH8D	A	69,60	71,30	80,40
04-04-2008	B763	A	73,70	77,00	88,00
04-04-2008	E145	A	68,80	69,90	79,60
04-04-2008	B737	A	72,00	74,50	84,50
04-04-2008	E170	A	69,90	71,40	81,40
04-04-2008	E170	A	70,30	72,60	82,90
04-04-2008	E170	A	69,90	71,70	82,20
04-04-2008	AT72	A	72,60	75,70	84,90
04-04-2008	E170	A	70,90	73,00	82,70
04-04-2008	T154	A	77,60	81,80	90,80
04-04-2008	A320	A	71,20	74,20	84,50
04-04-2008	B738	A	75,60	79,40	89,40
04-04-2008	B735	A	73,90	77,60	86,20
04-04-2008	AT72	A	72,10	74,80	84,60
04-04-2008	B734	A	74,20	79,40	87,80
04-04-2008	B735	A	74,20	78,60	87,40
04-04-2008	E170	A	70,60	72,60	82,30
04-04-2008	B734	A	74,30	78,60	87,10
04-04-2008	YK40	A	78,20	82,70	92,00
04-04-2008	B733	A	73,70	76,70	85,10
04-04-2008	B735	A	74,40	78,60	87,40
04-04-2008	AT72	A	69,60	72,70	84,40
04-04-2008	B733	A	72,90	78,70	87,10



04-04-2008	A320	A	73,50	76,80	85,60
04-04-2008	B735	A	73,40	78,40	86,80
04-04-2008	B734	A	74,70	78,60	86,50
04-04-2008	E170	A	70,80	73,60	82,90
04-04-2008	A320	A	72,00	74,80	84,10
04-04-2008	A321	A	72,50	75,40	84,80
04-04-2008	B752	A	73,90	77,30	87,30
04-04-2008	AT72	A	74,40	78,10	86,20
04-04-2008	B735	A	72,50	76,80	85,50
04-04-2008	A320	A	76,10	81,00	89,50
04-04-2008	A319	A	72,00	74,60	84,10
04-04-2008	E170	A	69,20	72,00	82,00
04-04-2008	E170	A	69,60	72,80	83,40
04-04-2008	AT72	A	72,10	77,00	85,40
04-04-2008	B734	A	73,00	77,00	84,80
04-04-2008	E170	A	69,70	73,30	82,20
04-04-2008	B738	A	72,20	76,60	85,40
04-04-2008	RJ85	A	70,30	72,40	82,10
04-04-2008	MD82	A	72,50	75,50	85,50
04-04-2008	E170	A	70,30	73,60	82,10
04-04-2008	C25A	A	69,30	71,50	80,80
04-04-2008	E170	A	71,70	74,00	83,50
04-04-2008	AT72	A	71,40	74,30	84,60
04-04-2008	CL60	A	69,80	72,50	80,20
04-04-2008	AT72	A	74,20	77,00	86,80
04-04-2008	E190	A	73,20	77,90	85,50
04-04-2008	B733	A	73,50	77,20	86,30
04-04-2008	A320	A	72,40	75,00	84,70
04-04-2008	B733	A	73,20	76,80	85,50
04-04-2008	AT72	A	70,10	73,00	81,60
04-04-2008	A320	A	71,80	74,40	83,90
04-04-2008	B762	A	74,20	76,60	87,70
04-04-2008	A319	A	71,90	76,80	85,30
04-04-2008	E170	A	71,30	73,40	82,70
04-04-2008	F100	A	72,50	76,80	84,20
04-04-2008	E170	A	72,10	75,60	84,70
04-04-2008	T154	A	76,30	81,30	89,30
04-04-2008	AT45	A	70,60	73,30	82,10
04-04-2008	E170	A	71,20	74,40	82,30
04-04-2008	CRJ2	A	70,80	73,90	82,30
04-04-2008	B735	A	73,10	76,80	85,20
04-04-2008	DH8D	A	71,30	73,60	82,10
04-04-2008	B735	A	73,00	76,70	85,10
04-04-2008	B735	A	72,80	77,00	85,60
04-04-2008	AT45	A	71,90	74,60	84,20
04-04-2008	AN26	A	72,80	77,50	86,00
04-04-2008	E145	A	68,90	70,40	78,90
04-04-2008	E170	A	71,80	74,90	84,30
04-04-2008	E145	A	69,30	72,50	80,80
04-04-2008	B734	A	75,00	79,40	87,60
04-04-2008	A319	A	72,60	75,20	84,90
04-04-2008	E145	A	69,10	70,40	79,10
04-04-2008	C25B	A	70,30	73,40	83,50
04-04-2008	AT72	A	71,80	75,60	85,60
04-04-2008	E170	A	71,60	74,30	83,40
04-04-2008	B734	A	73,30	77,30	86,30

04-04-2008	A310	A	73,80	78,10	88,20
04-04-2008	E170	A	71,70	73,90	82,90
04-04-2008	AT72	A	72,10	75,60	85,50
04-04-2008	E170	A	70,30	72,70	83,10
04-04-2008	B735	A	74,80	77,50	86,50
04-04-2008	A320	A	74,20	77,60	87,60
04-04-2008	AT72	A	73,20	76,50	85,00
04-04-2008	E145	A	69,90	71,20	79,90
04-04-2008	B737	A	71,50	74,40	84,50
04-04-2008	E145	A	68,90	71,30	80,40
04-04-2008	BE40	A	68,20	70,20	78,20
04-04-2008	A319	A	71,50	74,70	83,80
04-04-2008	AT72	A	74,00	76,30	86,30
04-04-2008	RJ85	A	73,70	76,50	84,50
04-04-2008	A320	A	71,40	73,60	83,10
04-04-2008	B733	A	72,40	76,40	84,90
04-04-2008	AT72	A	72,50	75,30	83,90
04-04-2008	B733	A	74,90	78,40	87,00
04-04-2008	A319	A	72,90	76,10	85,40
04-04-2008	AT45	A	70,50	72,30	81,30
04-04-2008	A320	A	71,40	73,00	82,90
04-04-2008	A321	A	72,30	76,50	85,90
04-04-2008	RJ1H	A	68,90	70,90	80,90
04-04-2008	A320	A	72,00	75,60	85,00
04-04-2008	B733	A	73,40	76,40	85,10
04-04-2008	E170	A	71,50	75,40	84,90
04-04-2008	A320	A	73,70	77,10	85,70
04-04-2008	E170	A	72,10	76,40	85,50
04-04-2008	AT72	A	70,90	72,90	82,90
04-04-2008	A318	A	72,70	75,10	84,80
04-04-2008	MD11	A	79,60	84,80	95,40
04-04-2008	B735	A	73,30	76,40	85,60
04-04-2008	E170	A	71,10	73,90	83,20
04-04-2008	E170	A	71,90	74,80	83,60
04-04-2008	AT72	A	74,00	78,80	87,10
04-04-2008	E145	A	68,80	70,90	79,20
04-04-2008	DH8D	A	69,70	72,10	81,50
04-04-2008	B733	A	72,80	75,70	85,80
04-04-2008	B738	A	72,80	77,20	87,60
04-04-2008	E170	A	70,10	73,30	83,30
04-04-2008	C560	A	69,80	72,10	80,20
04-04-2008	YK40	A	73,70	76,90	85,50
04-04-2008	B735	A	73,00	77,80	85,50
04-04-2008	F100	A	70,70	72,70	82,40
04-04-2008	B763	A	73,50	76,40	87,50
04-04-2008	CRJ2	A	69,90	72,90	82,20
04-04-2008	CRJ2	A	70,60	74,00	82,10
04-04-2008	AT72	A	73,60	77,10	87,40
04-04-2008	B735	A	72,40	74,70	84,70
04-04-2008	AT72	A	72,10	73,80	83,50
04-04-2008	SF34	A	69,70	71,30	80,10
04-04-2008	B738	A	72,40	75,40	85,40
04-04-2008	E170	A	71,40	73,80	83,40
04-04-2008	AT72	A	74,70	77,50	87,70
04-04-2008	B738	A	72,90	76,30	86,10
04-04-2008	E170	A	71,10	73,00	82,90

04-04-2008	B735	A	74,50	78,80	86,50
04-04-2008	B737	A	73,10	76,10	86,10
04-04-2008	A320	A	73,10	76,30	85,90
04-04-2008	B735	A	72,60	76,60	85,40
04-04-2008	B735	A	74,00	77,70	86,00
04-04-2008	E170	A	70,90	73,50	83,00
04-04-2008	B734	A	74,20	79,20	87,20
04-04-2008	B735	A	72,70	75,80	85,00
04-04-2008	E170	A	71,20	73,80	82,70
04-04-2008	AT43	A	70,90	72,70	82,90
04-04-2008	E170	A	71,30	74,10	82,80
04-04-2008	AT45	A	69,80	71,20	80,30
04-04-2008	AT72	A	73,70	77,10	86,70
04-04-2008	E170	A	70,70	73,30	82,80
04-04-2008	SF34	A	70,30	71,90	80,30
04-04-2008	E145	A	68,80	70,50	79,60
04-04-2008	E170	A	71,00	74,20	84,80
04-04-2008	SF34	A	68,40	69,90	79,50
04-04-2008	AT45	A	71,10	72,40	82,60
04-04-2008	B734	A	72,80	74,70	84,50
04-04-2008	B738	A	74,50	78,00	87,80
05-04-2008	SF34	A	69,60	72,10	80,00
05-04-2008	B735	A	73,90	79,70	86,00
05-04-2008	E170	A	72,00	74,80	83,50
05-04-2008	E170	A	71,10	73,60	82,60
05-04-2008	B752	A	73,30	76,10	86,30
05-04-2008	AT45	A	72,30	75,50	84,80
05-04-2008	E170	A	69,90	72,40	81,40
05-04-2008	AT72	A	74,30	77,00	86,60
05-04-2008	AT72	A	73,70	76,60	85,40
05-04-2008	AT72	A	74,70	77,70	87,00
05-04-2008	A320	A	71,80	73,80	83,50
05-04-2008	A320	A	72,30	74,70	84,60
05-04-2008	A319	A	70,60	73,10	82,90
05-04-2008	RJ85	A	70,90	72,50	82,10
05-04-2008	B736	A	73,00	75,30	85,30
05-04-2008	AT72	A	71,80	76,60	85,30
05-04-2008	CRJ2	A	70,20	71,50	80,60
05-04-2008	B734	A	76,50	81,20	89,30
05-04-2008	AT45	A	70,70	73,10	82,50
05-04-2008	E190	A	71,30	77,30	88,50
05-04-2008	B763	A	74,40	77,80	88,60
05-04-2008	F100	A	71,30	72,90	82,40
05-04-2008	B762	A	74,50	78,20	88,10
05-04-2008	B735	A	71,40	75,20	82,80
05-04-2008	E170	A	70,70	72,90	83,20
05-04-2008	B733	A	74,30	78,50	85,10
05-04-2008	DH8D	A	70,00	71,20	80,70
05-04-2008	B763	A	75,00	78,10	88,60
05-04-2008	B735	A	74,40	77,20	85,80
05-04-2008	E170	A	70,10	72,70	81,90
05-04-2008	E145	A	69,70	71,60	79,70
05-04-2008	E170	A	70,80	72,80	83,60
05-04-2008	E145	A	67,90	68,60	77,90
05-04-2008	AT72	A	72,80	75,50	84,60
05-04-2008	AT72	A	73,20	76,00	85,50

05-04-2008	F2TH	A	69,50	72,70	81,20
05-04-2008	T154	A	75,20	80,80	89,90
05-04-2008	B735	A	72,10	74,10	83,90
05-04-2008	AT72	A	73,00	76,30	85,30
05-04-2008	B735	A	72,50	75,40	84,80
05-04-2008	AT72	A	73,50	78,30	87,20
05-04-2008	B733	A	70,70	72,70	82,50
05-04-2008	B733	A	72,30	74,80	84,40
05-04-2008	AT45	A	72,10	73,90	82,90
05-04-2008	B763	A	73,50	75,90	86,70
05-04-2008	A320	A	70,30	73,20	83,10
05-04-2008	P180	A	77,20	82,10	92,50
05-04-2008	E170	A	70,00	72,90	81,80
05-04-2008	A320	A	71,10	73,50	82,90
05-04-2008	E145	A	69,00	71,00	80,20
05-04-2008	B733	A	73,00	76,40	84,40
05-04-2008	A319	A	72,70	76,40	84,40
05-04-2008	E170	A	72,30	74,80	84,30
05-04-2008	B733	A	72,70	75,00	84,70
05-04-2008	E145	A	69,60	72,20	80,00
05-04-2008	A320	A	71,30	73,30	82,40
05-04-2008	MD82	A	73,90	76,50	86,20
05-04-2008	E170	A	69,70	72,80	83,10
05-04-2008	B734	A	72,30	74,80	84,00
05-04-2008	B763	A	75,60	80,50	89,50
05-04-2008	E170	A	70,30	73,20	82,30
05-04-2008	RJ85	A	71,20	73,50	83,00
05-04-2008	E170	A	70,40	72,00	81,60
05-04-2008	B734	A	75,20	80,30	88,20
05-04-2008	E170	A	73,10	76,20	85,10
05-04-2008	B762	A	72,90	75,50	85,70
05-04-2008	B735	A	72,00	73,80	83,70
05-04-2008	A319	A	72,50	74,70	84,00
05-04-2008	B735	A	73,30	75,40	84,70
05-04-2008	AT72	A	71,10	72,20	81,50
05-04-2008	F100	A	69,70	70,80	80,10
05-04-2008	E170	A	69,70	71,80	80,90
05-04-2008	E170	A	71,00	72,50	82,50
05-04-2008	AT72	A	71,10	72,70	82,20
05-04-2008	AT72	A	72,80	75,40	84,60
05-04-2008	T154	A	75,90	80,10	88,90
05-04-2008	B735	A	73,60	77,80	85,30
05-04-2008	DH8D	A	70,80	73,00	82,20
05-04-2008	AT72	A	73,90	77,00	86,40
05-04-2008	E170	A	69,90	71,70	81,90
05-04-2008	E170	A	70,70	72,80	81,80
05-04-2008	E170	A	70,20	72,70	81,30
05-04-2008	E170	A	70,00	72,30	80,40
05-04-2008	AT72	A	72,90	74,90	84,30
05-04-2008	A319	A	70,60	73,90	83,70
05-04-2008	YK40	A	71,70	74,80	82,50
05-04-2008	AT45	A	68,80	71,00	79,20
05-04-2008	B733	A	71,80	76,00	84,90
05-04-2008	B737	A	71,60	73,80	83,10
05-04-2008	E170	A	70,50	73,60	81,90
05-04-2008	E170	A	70,70	72,60	82,20

05-04-2008	B734	A	72,70	75,70	83,80
05-04-2008	AT72	A	73,00	75,70	84,10
05-04-2008	B735	A	71,70	73,90	84,00
05-04-2008	B737	A	72,20	74,40	84,00
05-04-2008	E145	A	70,50	72,70	81,30
05-04-2008	RJ85	A	70,90	74,20	82,60
05-04-2008	A319	A	70,20	72,60	81,30
05-04-2008	A320	A	73,10	74,90	84,20
05-04-2008	B734	A	73,00	74,80	84,40
05-04-2008	E170	A	70,10	71,80	80,90
05-04-2008	A320	A	70,60	72,70	81,80
05-04-2008	A319	A	73,40	76,00	85,20
05-04-2008	AT72	A	71,90	73,70	83,40
05-04-2008	AT72	A	72,50	74,90	84,00
05-04-2008	A320	A	73,00	75,60	85,10
05-04-2008	E170	A	70,60	72,50	82,10
05-04-2008	B733	A	74,20	78,00	86,50
05-04-2008	B735	A	73,70	76,70	85,20
05-04-2008	B735	A	73,20	76,40	84,40
05-04-2008	RJ1H	A	69,80	71,20	79,80
05-04-2008	B735	A	71,90	74,60	83,40
05-04-2008	E170	A	70,20	71,80	81,00
05-04-2008	AT72	A	71,00	72,90	83,00
05-04-2008	A319	A	73,60	76,80	85,40
05-04-2008	B735	A	72,20	73,80	83,60
05-04-2008	A319	A	73,60	76,30	86,10
05-04-2008	B734	A	71,10	73,00	82,50
05-04-2008	E170	A	71,90	73,60	82,70
05-04-2008	E170	A	70,80	72,10	82,20
05-04-2008	B738	A	74,20	77,20	85,60
05-04-2008	E170	A	70,90	72,20	81,30
05-04-2008	E170	A	70,60	72,80	81,70
05-04-2008	B735	A	72,30	74,90	84,60
05-04-2008	E170	A	70,30	72,40	81,40
05-04-2008	B733	A	72,50	75,00	84,20
05-04-2008	E170	A	71,70	74,00	83,20
05-04-2008	E170	A	71,80	74,40	83,30
05-04-2008	E170	A	71,00	73,10	82,10
05-04-2008	E170	A	70,70	72,20	82,10
05-04-2008	AT72	A	73,80	76,60	86,50
05-04-2008	AT72	A	71,10	74,00	85,70
05-04-2008	A319	A	73,20	77,20	84,70
05-04-2008	B733	A	73,00	76,30	84,80
05-04-2008	E170	A	70,60	72,20	81,70
05-04-2008	AT72	A	74,40	77,50	85,80
05-04-2008	B733	A	73,00	75,90	84,10
05-04-2008	B733	A	73,50	76,20	85,30
05-04-2008	A320	A	71,20	73,70	82,30
06-04-2008	B733	A	73,50	77,40	85,30
06-04-2008	A321	A	72,40	75,20	84,20
06-04-2008	E170	A	71,80	74,00	83,30
06-04-2008	E170	A	71,50	74,00	82,70
06-04-2008	AT45	A	70,40	72,00	81,60
06-04-2008	B734	D	71,20	73,00	82,30
06-04-2008	B734	A	74,60	78,60	86,60
06-04-2008	B703	A	85,70	93,60	100,60

06-04-2008	RJ85	A	72,10	74,70	83,60
06-04-2008	B738	A	72,80	75,40	84,80
06-04-2008	B734	A	74,80	78,50	86,20
06-04-2008	AT72	A	70,60	72,70	81,40
06-04-2008	B738	A	73,10	75,20	84,60
06-04-2008	A319	A	76,00	80,50	89,00
06-04-2008	B762	A	74,50	77,20	87,00
06-04-2008	F100	A	69,50	70,60	80,00
06-04-2008	DH8D	A	69,70	71,00	80,20
06-04-2008	B735	A	73,50	75,70	84,90
06-04-2008	A320	A	71,40	73,40	82,80
06-04-2008	B763	A	74,70	78,40	87,70
06-04-2008	E170	A	70,90	73,40	82,30
06-04-2008	AT72	A	72,80	75,60	84,60
06-04-2008	AT72	A	74,00	76,60	85,80
06-04-2008	AT72	A	74,00	76,60	85,40
06-04-2008	T154	A	75,90	80,80	89,40
06-04-2008	B735	A	73,10	76,90	84,50
06-04-2008	B733	A	72,60	74,80	84,00
06-04-2008	AT72	A	74,20	76,80	86,50
06-04-2008	B733	A	73,50	76,40	85,30
06-04-2008	A319	A	72,90	75,90	85,20
06-04-2008	B735	A	73,50	76,70	84,60
06-04-2008	E170	A	71,10	72,90	82,50
06-04-2008	B733	A	74,50	80,00	86,00
06-04-2008	PC12	A	72,10	74,60	82,50
06-04-2008	A319	A	73,00	76,00	85,60
06-04-2008	MD82	A	75,20	78,20	87,00
06-04-2008	A320	A	72,50	75,00	84,20
06-04-2008	A320	A	72,30	74,60	83,80
06-04-2008	A319	A	71,90	74,60	83,30
06-04-2008	A320	A	73,00	75,80	84,40
06-04-2008	B733	A	73,80	75,90	85,50
06-04-2008	B734	A	72,40	77,20	90,10
06-04-2008	E170	A	69,30	73,00	79,70
06-04-2008	E170	A	70,10	73,50	82,20
06-04-2008	AT45	A	70,60	72,70	81,00
06-04-2008	B738	A	73,00	75,40	84,10
06-04-2008	E170	A	69,90	71,90	80,70
06-04-2008	RJ85	A	72,70	75,40	83,10
06-04-2008	E170	A	72,50	74,70	83,30
06-04-2008	AT72	A	72,10	74,00	83,90
06-04-2008	A320	A	73,50	75,70	85,00
06-04-2008	B762	A	73,80	76,90	86,30
06-04-2008	A319	A	71,40	73,20	82,60
06-04-2008	F100	A	73,70	76,00	84,10
06-04-2008	A320	A	71,90	73,80	83,30
06-04-2008	AT72	A	73,60	75,90	85,90
06-04-2008	E170	A	70,40	72,80	82,40
06-04-2008	AT45	A	72,00	74,10	83,20
06-04-2008	AT45	A	72,00	74,00	83,10
06-04-2008	AT72	A	74,70	77,60	86,50
06-04-2008	DH8D	A	69,10	71,20	79,90
06-04-2008	AT72	A	70,60	73,40	82,70
06-04-2008	E170	A	72,00	74,10	83,40
06-04-2008	AT72	A	74,40	77,20	86,40

06-04-2008	E170	A	71,70	73,50	82,50
06-04-2008	B735	A	72,70	75,50	84,40
06-04-2008	E170	A	71,50	74,20	83,20
06-04-2008	E170	A	70,50	73,20	81,90
06-04-2008	E170	A	71,10	73,30	81,90
06-04-2008	A318	A	72,60	76,70	84,60
06-04-2008	AT72	A	75,30	78,00	87,80
06-04-2008	AT72	A	71,70	73,90	83,70
06-04-2008	E170	A	72,50	75,60	84,60
06-04-2008	AT45	A	72,10	75,00	83,30
06-04-2008	B735	A	72,80	74,90	84,50
06-04-2008	E170	A	70,60	72,00	81,40
06-04-2008	B737	A	75,50	79,00	87,80
06-04-2008	E145	A	69,80	71,80	80,20
06-04-2008	A319	A	71,30	73,20	82,70
06-04-2008	B733	A	71,90	75,60	84,60
06-04-2008	AT45	A	74,60	77,60	85,70
06-04-2008	B733	A	74,60	77,30	85,00
06-04-2008	AT72	A	71,60	73,70	83,40
06-04-2008	B735	A	73,50	76,00	84,90
06-04-2008	A320	A	70,50	72,40	81,30
06-04-2008	B734	A	74,20	79,30	85,00
06-04-2008	B735	A	72,90	76,50	84,00
06-04-2008	RJ85	A	69,10	71,80	81,10
06-04-2008	A320	A	70,90	72,80	81,70
06-04-2008	B733	A	76,20	80,50	88,30
06-04-2008	B762	D	71,80	74,40	83,80
06-04-2008	A320	A	70,80	73,50	82,90
06-04-2008	AT72	A	73,70	78,10	85,80
06-04-2008	A319	A	72,40	74,80	83,90
06-04-2008	AT72	A	74,80	77,30	86,80
06-04-2008	YK40	A	70,60	74,10	82,00
06-04-2008	E170	A	72,90	75,70	84,60
06-04-2008	A319	A	71,60	74,10	83,90
06-04-2008	B735	A	72,60	74,70	84,00
06-04-2008	B733	A	72,70	75,40	84,20
06-04-2008	AT72	A	73,60	76,60	86,80
06-04-2008	B735	A	74,30	78,10	85,10
06-04-2008	E170	A	70,90	73,10	82,60
06-04-2008	DH8D	A	70,50	73,00	81,30
06-04-2008	E170	A	70,20	73,00	80,70
06-04-2008	AT45	A	72,50	74,50	83,70
06-04-2008	A319	A	74,50	76,90	85,60
06-04-2008	B733	A	72,30	74,20	83,50
06-04-2008	B736	A	75,70	78,90	88,30
06-04-2008	AT72	A	70,50	72,70	81,70
06-04-2008	E170	A	73,20	75,60	84,00
06-04-2008	C25B	A	72,70	75,40	83,80
06-04-2008	B735	A	72,50	74,30	83,60
06-04-2008	E170	A	71,10	72,80	81,90
06-04-2008	B733	A	72,90	77,00	84,60
06-04-2008	AT45	A	71,40	73,70	81,40
06-04-2008	E170	A	71,00	72,50	81,80
06-04-2008	E170	A	71,30	73,40	82,70
06-04-2008	E170	A	71,70	74,20	81,70
06-04-2008	B737	A	72,80	75,40	83,90

06-04-2008	A320	A	73,80	75,50	84,90
06-04-2008	B738	A	75,90	80,20	88,50
06-04-2008	E170	A	70,90	73,00	81,70
06-04-2008	B735	A	72,00	74,00	83,50
06-04-2008	B735	A	73,50	76,80	84,20
06-04-2008	E170	A	70,70	73,20	81,10
06-04-2008	E170	A	70,60	72,50	81,40
06-04-2008	AT72	A	74,70	76,90	86,70
06-04-2008	AT72	A	68,20	69,30	79,90
06-04-2008	H25B	A	74,20	76,80	84,60
06-04-2008	AT72	A	73,10	75,50	84,60
06-04-2008	E145	A	70,10	72,10	80,10
06-04-2008	E145	A	68,20	69,70	79,90
06-04-2008	E170	A	70,40	72,10	80,80
06-04-2008	E170	A	70,50	73,20	82,30
06-04-2008	E170	A	71,70	73,70	82,50
06-04-2008	B738	A	73,90	76,20	85,30
07-04-2008	AT72	A	71,70	73,90	82,50
07-04-2008	AT72	A	74,90	77,70	87,70
07-04-2008	E190	A	71,50	74,10	82,70
07-04-2008	AT72	A	71,30	73,10	82,40
07-04-2008	RJ85	A	70,80	72,20	80,80
07-04-2008	B763	A	74,80	77,30	87,30
07-04-2008	RJ1H	A	70,00	71,90	80,50
07-04-2008	B735	A	73,10	75,80	84,80
07-04-2008	E170	A	71,50	73,20	82,60
07-04-2008	B735	A	73,50	76,50	84,70
07-04-2008	DH8D	A	71,50	73,00	81,50
07-04-2008	B733	A	74,70	78,50	86,40
07-04-2008	E170	A	70,50	72,40	80,50
07-04-2008	B737	A	72,40	74,50	83,50
07-04-2008	E170	A	71,60	73,40	82,40
07-04-2008	E170	A	70,40	73,00	81,20
07-04-2008	A320	A	70,60	72,50	81,80
07-04-2008	E170	A	70,10	72,80	80,80
07-04-2008	B734	A	71,50	73,60	82,90
07-04-2008	AT72	A	74,70	77,40	86,40
07-04-2008	E170	A	71,10	73,00	82,60
07-04-2008	B752	A	73,30	75,50	85,00
07-04-2008	AT45	A	71,10	72,60	81,10
07-04-2008	B734	A	72,60	74,00	83,30
07-04-2008	AT72	A	72,30	76,90	85,30
07-04-2008	B733	A	74,10	77,10	84,90
07-04-2008	B734	A	71,80	75,60	84,10
07-04-2008	B462	A	69,80	71,20	79,80
07-04-2008	B735	A	72,60	74,90	83,80
07-04-2008	B763	A	74,10	77,00	86,70
07-04-2008	E170	A	73,00	76,10	83,80
07-04-2008	M28	A	71,20	73,60	81,20
07-04-2008	B735	A	72,60	76,10	83,80
07-04-2008	P180	A	74,80	79,50	88,60
07-04-2008	E170	D	71,30	74,10	82,80
07-04-2008	B735	D	70,40	75,70	83,80
07-04-2008	E170	D	67,60	71,50	80,60
07-04-2008	E170	D	68,40	71,10	79,20
07-04-2008	B738	D	69,60	71,50	80,10



07-04-2008	B733	D	70,80	75,20	82,50
07-04-2008	A320	D	69,30	72,00	81,30
07-04-2008	B735	D	70,30	72,40	82,60
07-04-2008	E170	D	67,80	70,90	80,60
07-04-2008	B735	D	69,70	72,30	80,50
07-04-2008	B735	D	67,40	70,30	78,90
07-04-2008	H25B	D	69,50	71,80	81,20
07-04-2008	B762	D	71,80	75,00	84,10
07-04-2008	B733	D	71,60	74,30	83,30
07-04-2008	B738	D	69,90	72,50	82,50
08-04-2008	AT72	A	70,70	73,70	82,50
08-04-2008	E170	A	71,60	74,30	83,10
08-04-2008	E170	A	71,40	74,10	83,50
08-04-2008	E170	A	71,00	72,90	81,80
08-04-2008	AT72	A	73,40	76,80	85,70
08-04-2008	E145	A	68,40	70,10	78,90
08-04-2008	B752	A	73,60	76,80	86,40
08-04-2008	E170	A	71,90	75,10	83,90
08-04-2008	AT43	A	71,70	76,90	84,50
08-04-2008	AT45	A	70,10	72,90	81,20
08-04-2008	B735	A	74,00	78,20	85,80
08-04-2008	RJ85	A	70,40	72,30	82,50
08-04-2008	RJ85	A	72,60	75,50	85,60
08-04-2008	E170	A	71,40	73,50	83,40
08-04-2008	B462	A	71,30	73,80	83,30
08-04-2008	B738	A	72,80	76,70	85,10
08-04-2008	T154	A	76,40	82,80	90,60
08-04-2008	CRJ2	A	70,30	72,70	80,70
08-04-2008	AT72	A	72,30	76,40	84,80
08-04-2008	CRJ2	A	69,80	72,30	81,30
08-04-2008	RJ85	A	70,40	73,40	81,90
08-04-2008	B737	A	74,00	77,30	85,80
08-04-2008	E145	A	70,60	71,70	80,60
08-04-2008	F100	A	70,60	74,00	82,60
08-04-2008	B763	A	75,30	79,90	90,90
08-04-2008	C650	A	71,60	74,70	82,00
08-04-2008	E170	A	72,20	75,50	85,20
08-04-2008	E190	A	73,40	78,30	87,20
08-04-2008	E170	A	72,10	74,50	84,10
08-04-2008	B735	A	73,00	76,90	85,30
08-04-2008	RJ85	A	70,20	72,60	81,30
08-04-2008	A320	A	72,60	75,10	84,40
08-04-2008	B735	A	72,50	77,60	87,70
08-04-2008	B735	A	69,20	74,00	81,90
08-04-2008	B737	A	70,80	77,50	87,80
08-04-2008	DH8D	A	73,00	76,30	84,40
08-04-2008	E170	A	72,00	75,00	83,80
08-04-2008	B735	A	72,50	74,80	84,80
08-04-2008	A319	A	72,50	76,30	83,90
08-04-2008	T154	A	76,30	82,00	90,30
08-04-2008	AT45	A	72,30	74,50	83,70
08-04-2008	B735	A	73,00	75,90	85,50
08-04-2008	B735	A	72,20	76,30	85,40
08-04-2008	AT72	A	69,30	71,20	82,10
08-04-2008	E170	A	71,40	75,60	83,10
08-04-2008	E145	A	68,40	69,90	78,40

08-04-2008	AT72	A	72,10	76,00	86,60
08-04-2008	B462	A	67,50	73,20	78,90
08-04-2008	AT72	A	70,70	74,60	83,30
08-04-2008	B734	A	75,00	79,10	85,40
08-04-2008	B733	A	75,10	79,70	86,60
08-04-2008	E170	A	72,10	75,20	84,70
08-04-2008	AT72	A	73,20	76,90	85,00
08-04-2008	E170	A	71,10	73,90	82,50
08-04-2008	B738	A	74,40	78,80	86,70
08-04-2008	H25B	A	73,80	76,90	83,80
08-04-2008	E170	A	72,30	75,20	84,60
08-04-2008	A319	A	73,60	77,10	85,90
08-04-2008	B733	A	73,10	76,00	85,10
08-04-2008	RJ1H	A	71,70	74,60	84,00
08-04-2008	A320	A	72,70	77,60	86,10
08-04-2008	AT72	A	69,90	74,60	83,20
08-04-2008	E145	A	71,90	74,40	81,90
08-04-2008	A320	A	70,90	73,80	83,70
08-04-2008	E170	A	71,90	75,10	83,70
08-04-2008	B734	A	73,50	78,40	86,70
08-04-2008	E170	A	71,10	73,50	82,50
08-04-2008	B735	A	73,80	77,00	85,60
08-04-2008	AT45	A	71,50	74,50	83,30
08-04-2008	B735	A	72,70	77,00	84,70
08-04-2008	A318	A	72,80	75,60	85,30
08-04-2008	DH8D	A	71,60	75,10	83,40
08-04-2008	E170	A	70,70	72,80	82,10
08-04-2008	AT72	A	70,20	72,40	81,70
08-04-2008	B733	A	74,70	78,20	85,80
08-04-2008	E170	A	70,00	72,60	82,60
08-04-2008	B736	A	72,10	75,10	84,60
08-04-2008	B734	A	73,80	77,50	85,60
08-04-2008	A321	A	71,80	73,60	83,30
08-04-2008	F100	A	69,60	73,70	83,80
08-04-2008	B733	A	73,90	78,00	85,60
08-04-2008	MD11	A	79,70	84,50	94,60
08-04-2008	AT72	A	73,40	76,40	85,20
08-04-2008	AT45	A	71,20	72,70	82,00
08-04-2008	CRJ2	A	70,50	72,30	81,30
08-04-2008	E145	A	69,80	70,90	80,20
08-04-2008	B738	A	72,70	75,40	84,70
08-04-2008	L410	A	69,10	71,00	79,10
08-04-2008	B735	A	72,90	76,40	85,00
08-04-2008	B738	A	72,60	75,70	85,20
08-04-2008	E170	A	71,30	73,40	83,10
08-04-2008	SF34	A	69,70	72,30	80,80
08-04-2008	B738	A	73,00	76,50	85,60
08-04-2008	B737	A	71,50	73,80	83,00
08-04-2008	A320	A	72,80	75,40	84,90
08-04-2008	E170	A	71,30	73,50	82,50
08-04-2008	B762	A	72,70	75,60	85,90
08-04-2008	E170	A	70,80	72,70	82,20
08-04-2008	E170	A	70,30	72,20	81,50
08-04-2008	E170	A	70,60	72,60	81,70
08-04-2008	P180	A	74,70	77,90	88,90
08-04-2008	B735	A	73,70	77,90	86,00

08-04-2008	E170	A	70,20	72,20	81,00
08-04-2008	E170	A	71,10	72,80	82,20
08-04-2008	E170	A	71,30	73,50	82,70
08-04-2008	AT72	A	70,10	71,90	80,90
08-04-2008	B738	A	72,30	74,70	84,00
08-04-2008	B735	A	71,80	73,80	83,20
08-04-2008	AT72	A	74,20	76,70	86,20
08-04-2008	AT72	A	74,10	77,30	86,40
08-04-2008	E170	A	70,60	72,80	81,70
08-04-2008	B733	A	73,20	76,60	85,00
08-04-2008	B735	A	71,70	73,80	83,20
08-04-2008	E145	A	70,90	75,40	82,90
08-04-2008	AT72	A	73,40	76,50	85,20
08-04-2008	A321	A	73,00	75,80	84,50
08-04-2008	AN26	A	73,20	77,10	84,00
08-04-2008	E170	A	70,70	72,80	81,90
09-04-2008	B735	A	71,40	73,20	82,20
09-04-2008	E170	A	71,00	72,70	81,40
09-04-2008	E170	A	70,30	72,20	80,70
09-04-2008	AT72	A	71,40	75,00	83,40
09-04-2008	AT72	A	70,00	72,10	81,50
09-04-2008	E170	A	71,40	74,40	82,60
09-04-2008	AT72	A	72,10	74,10	82,90
09-04-2008	E170	A	70,40	71,80	81,10
09-04-2008	B752	A	72,50	73,70	84,00
09-04-2008	AT45	A	71,90	73,30	82,30
09-04-2008	AT43	A	71,50	73,90	83,50
09-04-2008	AT72	A	73,40	76,30	85,20
09-04-2008	B734	A	73,30	75,50	84,40
09-04-2008	B734	A	73,00	75,90	83,80
09-04-2008	B762	A	71,80	73,80	84,40
09-04-2008	B737	A	71,00	73,80	83,30
09-04-2008	CRJ2	A	69,30	72,10	80,10
09-04-2008	AT72	A	70,10	71,80	80,90
09-04-2008	B763	A	73,80	75,80	85,80
09-04-2008	B735	A	74,00	76,30	84,40
09-04-2008	B738	A	73,00	75,70	84,40
09-04-2008	RJ85	A	73,80	76,50	84,20
09-04-2008	P180	A	73,30	78,20	86,30
09-04-2008	RJ85	A	71,70	73,90	82,50
09-04-2008	E170	A	71,60	74,90	82,40
09-04-2008	F100	A	68,40	69,00	78,40
09-04-2008	A320	A	71,60	75,90	84,90
09-04-2008	A320	A	71,70	73,50	82,80
09-04-2008	B735	A	72,40	76,00	83,90
09-04-2008	B737	A	71,80	73,90	82,60
09-04-2008	E170	A	73,90	78,10	89,60
09-04-2008	MD11	D	68,50	70,00	78,90
09-04-2008	B763	A	72,50	76,60	86,40
09-04-2008	B735	A	74,00	76,90	85,80
09-04-2008	A320	A	72,00	74,60	83,80
09-04-2008	B735	A	72,00	73,60	82,80
09-04-2008	DH8D	A	70,50	73,10	81,30
09-04-2008	E170	A	70,20	72,10	81,00
09-04-2008	E190	A	70,30	72,10	81,80
09-04-2008	E170	A	70,60	78,10	85,40

09-04-2008	T154	A	75,30	78,50	86,80
09-04-2008	B735	A	71,30	72,90	82,10
09-04-2008	E145	A	69,90	72,20	80,60
09-04-2008	AT72	A	70,20	72,70	81,70
09-04-2008	E170	A	71,70	74,10	83,20
09-04-2008	B738	D	70,40	72,80	81,20
09-04-2008	B735	D	68,50	70,10	78,90
09-04-2008	A320	D	68,40	69,90	80,20
09-04-2008	A320	D	69,10	70,80	82,50
09-04-2008	E170	D	68,30	71,30	83,50
09-04-2008	T154	D	72,50	77,30	88,90
09-04-2008	E170	D	70,10	72,40	82,90
09-04-2008	B763	D	72,50	74,90	84,80
09-04-2008	B735	D	69,20	71,00	80,90
09-04-2008	B735	D	69,80	74,20	82,90
09-04-2008	A320	D	68,00	69,40	78,80
09-04-2008	E170	D	67,70	69,70	80,00
09-04-2008	B763	D	72,20	74,50	86,00
09-04-2008	B763	D	73,30	76,90	86,90
09-04-2008	B738	D	69,40	73,30	83,20
09-04-2008	B733	D	71,60	74,00	82,40
09-04-2008	B735	D	70,70	73,80	83,50
09-04-2008	P180	D	68,70	70,20	79,10
09-04-2008	E170	D	68,60	70,60	79,40
09-04-2008	AN12	D	69,70	73,40	83,50
09-04-2008	B733	D	70,50	72,70	81,60
09-04-2008	E170	D	67,80	70,20	79,60
09-04-2008	YK40	D	73,10	75,90	86,90
09-04-2008	B733	D	69,40	70,80	80,20
09-04-2008	T154	D	75,10	79,40	89,40
09-04-2008	B735	D	70,00	71,70	81,10
10-04-2008	B733	D	72,30	75,20	83,70
10-04-2008	E170	A	70,90	73,20	82,00
10-04-2008	B752	A	73,20	76,50	86,60
10-04-2008	AT45	A	71,00	73,30	82,70
10-04-2008	AT43	A	72,70	76,70	86,50
10-04-2008	A320	A	73,00	76,00	84,80
10-04-2008	A319	A	74,20	78,30	87,50
10-04-2008	B733	D	73,80	77,40	85,90
10-04-2008	B733	D	73,00	76,10	84,80
10-04-2008	AT72	A	74,90	77,40	86,60
10-04-2008	A319	A	73,70	75,60	85,50
10-04-2008	RJ85	A	74,90	78,20	86,40
10-04-2008	F70	A	70,50	72,00	80,90
10-04-2008	A320	A	73,00	76,00	85,00
10-04-2008	AT72	A	74,90	77,60	86,90
10-04-2008	B462	A	72,20	74,40	82,20
10-04-2008	B463	A	71,90	74,30	83,10
10-04-2008	B763	A	76,30	79,60	88,90
10-04-2008	B738	A	74,80	77,20	86,30
10-04-2008	E190	A	72,60	74,20	83,70
10-04-2008	F100	A	71,80	73,10	82,20
10-04-2008	E175	A	71,70	73,40	82,80
10-04-2008	B733	A	72,20	74,50	83,90
10-04-2008	E170	A	72,20	74,90	83,60
10-04-2008	A320	A	73,00	75,60	84,40

10-04-2008	E145	A	70,10	72,90	81,60
10-04-2008	DH8D	A	74,60	76,70	85,40
10-04-2008	B737	A	71,80	73,40	82,60
10-04-2008	B735	A	72,40	75,30	83,60
10-04-2008	E170	A	71,50	74,10	83,00
10-04-2008	B735	A	74,30	77,20	85,10
10-04-2008	C25A	A	70,70	72,70	81,10
10-04-2008	T154	A	77,80	82,60	90,10
10-04-2008	E145	A	73,40	76,70	84,90
10-04-2008	E170	A	71,90	73,00	82,30
10-04-2008	B763	A	75,70	79,40	89,10
10-04-2008	B735	D	70,40	73,10	81,80
10-04-2008	A320	D	69,10	71,70	82,10
10-04-2008	E170	D	68,70	71,10	79,90
10-04-2008	E170	D	68,90	71,60	79,70
10-04-2008	T154	D	74,10	81,40	89,60
10-04-2008	B735	D	70,40	72,20	82,70
10-04-2008	E170	D	68,60	70,80	82,00
10-04-2008	E170	D	68,80	71,20	83,10
10-04-2008	B735	D	69,30	71,60	82,10
10-04-2008	B763	D	74,00	78,10	88,20
10-04-2008	B734	D	71,10	73,80	83,70
10-04-2008	MD82	D	72,80	78,70	88,70
10-04-2008	E170	D	68,60	70,10	80,00
10-04-2008	B738	A	71,50	76,40	85,50
10-04-2008	E170	A	70,90	73,80	81,70
10-04-2008	B735	A	72,50	75,00	83,60
10-04-2008	CRJ2	A	70,70	73,00	81,50
10-04-2008	AT72	A	72,00	75,40	85,20
10-04-2008	E170	A	72,10	74,50	83,80
10-04-2008	E170	A	70,30	73,70	81,40
10-04-2008	AT45	A	73,70	75,80	85,20
10-04-2008	F2TH	A	69,90	72,30	80,30
10-04-2008	F100	A	69,30	70,70	80,80
10-04-2008	B735	A	72,10	74,50	83,20
10-04-2008	DH8D	A	70,40	73,10	81,20
10-04-2008	B735	A	73,20	76,30	85,20
10-04-2008	E170	A	71,50	73,90	81,90
10-04-2008	E170	A	71,20	73,80	82,00
10-04-2008	E170	A	70,70	73,50	82,10
10-04-2008	B733	A	73,30	77,50	85,80
10-04-2008	B735	A	72,10	75,20	83,80
10-04-2008	E170	A	70,90	73,20	82,40
10-04-2008	B734	A	72,50	76,10	84,20
10-04-2008	AT72	A	75,00	78,20	86,50
10-04-2008	E170	A	71,60	75,60	84,20
10-04-2008	A320	A	71,40	74,30	84,70
10-04-2008	E170	A	68,40	72,40	85,00
10-04-2008	A319	A	72,90	75,90	84,70
10-04-2008	AT72	A	72,40	75,60	84,40
10-04-2008	B762	A	72,20	76,10	85,80
10-04-2008	B735	A	74,00	77,60	85,70
10-04-2008	B734	A	72,80	75,20	84,50
10-04-2008	AT72	A	74,90	78,70	86,70
10-04-2008	AT72	A	72,60	75,70	85,80
10-04-2008	A319	A	70,60	73,00	82,90

10-04-2008	AT43	A	70,30	72,10	81,40
10-04-2008	AT45	A	71,10	73,60	82,80
10-04-2008	RJ85	A	69,50	71,90	81,00
10-04-2008	A320	A	71,00	73,70	82,70
10-04-2008	AT45	A	70,70	72,80	81,40
10-04-2008	B733	A	71,80	74,50	83,60
10-04-2008	A319	A	72,80	76,20	85,60
10-04-2008	B735	A	73,50	77,60	84,70
10-04-2008	A318	A	70,60	73,50	83,20
10-04-2008	E170	A	72,40	74,40	83,90
10-04-2008	JS32	A	69,80	72,10	79,80
10-04-2008	B734	A	71,80	73,50	83,30
10-04-2008	AT72	A	72,80	76,10	84,30
10-04-2008	B734	A	72,90	77,60	84,90
10-04-2008	B735	A	72,50	76,70	84,60
10-04-2008	B733	A	73,30	75,50	85,10
10-04-2008	E170	A	71,60	73,10	83,00
10-04-2008	MD11	A	79,50	86,00	94,70
10-04-2008	DH8D	A	73,30	75,10	84,00
10-04-2008	RJ1H	A	71,30	73,00	81,30
10-04-2008	B733	A	73,40	78,00	86,60
10-04-2008	C25B	A	72,10	79,60	84,90
10-04-2008	AT72	A	72,30	74,40	84,10
10-04-2008	E170	A	70,70	73,00	82,20
10-04-2008	B737	A	73,30	77,10	86,10
10-04-2008	SF34	A	69,90	71,10	79,90
10-04-2008	AT72	A	70,50	72,30	82,50
10-04-2008	A319	A	71,20	74,40	83,50
10-04-2008	AT45	A	71,40	73,20	83,40
10-04-2008	AT72	A	70,50	73,30	83,00
10-04-2008	F100	A	70,60	73,00	81,70
10-04-2008	E170	A	70,80	72,80	82,20
10-04-2008	CRJ2	A	70,50	71,50	80,50
10-04-2008	B735	A	72,30	75,20	85,10
10-04-2008	GLF4	A	68,70	71,20	81,80
10-04-2008	E170	A	70,50	73,50	83,00
10-04-2008	E145	A	68,60	69,50	79,10
10-04-2008	B738	A	74,50	77,00	86,50
10-04-2008	E170	A	70,30	72,60	81,70
10-04-2008	AN26	A	72,80	75,60	83,60
10-04-2008	SF34	A	69,10	70,80	80,20
10-04-2008	B733	A	73,90	78,70	85,70
10-04-2008	A320	A	71,40	74,80	84,00
10-04-2008	B735	A	73,10	78,10	85,20
10-04-2008	B735	A	74,00	76,90	86,10
10-04-2008	AT45	A	71,20	73,90	82,90
10-04-2008	B737	A	71,90	74,70	84,90
10-04-2008	B752	A	72,70	76,00	86,40
10-04-2008	B734	A	72,80	74,40	84,20
10-04-2008	E170	A	70,00	72,80	82,60
10-04-2008	E170	A	72,00	75,00	84,30
10-04-2008	AT45	A	71,60	74,30	84,40
10-04-2008	E170	A	69,50	72,90	84,80
10-04-2008	E170	A	71,60	74,10	83,30
10-04-2008	E170	A	70,80	72,60	81,90
10-04-2008	B735	A	74,10	78,80	86,20

10-04-2008	E170	A	69,50	73,60	87,30
10-04-2008	B734	A	73,40	77,40	87,20
10-04-2008	E170	A	70,90	73,00	82,40
10-04-2008	SF34	A	68,40	69,60	78,40
10-04-2008	SF34	A	69,90	72,50	80,30
10-04-2008	AN26	A	69,50	74,90	87,20
11-04-2008	B733	A	73,90	77,60	85,70
11-04-2008	E170	A	70,20	71,80	81,40
11-04-2008	AT45	A	72,10	74,20	82,90
11-04-2008	B735	A	73,40	76,80	85,20
11-04-2008	E170	A	70,90	73,20	82,70
11-04-2008	AT45	A	72,40	74,10	83,50
11-04-2008	E170	A	71,50	73,10	82,70
11-04-2008	AT72	A	75,00	77,80	87,30
11-04-2008	B752	A	72,80	75,60	86,00
11-04-2008	AT72	A	74,00	76,60	86,10
11-04-2008	E170	A	70,20	72,80	81,70
11-04-2008	AT43	A	74,80	78,10	87,80
11-04-2008	E170	D	67,30	68,10	77,70
11-04-2008	B462	A	70,80	72,70	82,20
11-04-2008	CRJ2	A	71,40	73,00	81,90
11-04-2008	E190	A	71,70	75,30	84,00
11-04-2008	F70	A	72,90	78,70	87,70
11-04-2008	AT72	A	71,70	74,80	84,50
11-04-2008	F100	A	70,10	71,80	81,50
11-04-2008	B735	A	73,70	76,90	85,80
11-04-2008	RJ85	A	70,90	73,80	82,90
11-04-2008	E170	A	70,40	71,80	81,20
11-04-2008	E145	A	70,20	72,00	80,60
11-04-2008	B763	A	75,20	78,80	89,00
11-04-2008	B738	A	73,50	77,80	85,30
11-04-2008	B735	A	73,50	76,20	85,30
11-04-2008	DH8D	A	70,20	72,30	81,30
11-04-2008	B737	A	72,30	75,20	84,90
11-04-2008	B735	A	71,80	73,40	83,30
11-04-2008	A320	A	73,80	76,60	85,90
11-04-2008	E170	A	70,50	72,10	81,60
11-04-2008	E170	A	71,00	73,10	81,80
11-04-2008	E170	A	71,90	74,10	84,20
11-04-2008	AT72	A	75,20	78,40	88,00
11-04-2008	B734	A	75,10	80,50	86,30
11-04-2008	AT45	A	74,80	78,20	86,60
11-04-2008	B735	A	74,30	76,30	85,40
11-04-2008	T154	A	74,50	78,30	87,10
11-04-2008	E145	A	72,50	75,60	83,90
11-04-2008	E170	A	71,60	74,00	83,00
11-04-2008	AT72	A	74,90	78,10	87,20
11-04-2008	P180	A	74,00	79,60	89,30
11-04-2008	AT72	A	74,60	77,70	87,40
11-04-2008	B735	A	74,80	78,40	87,40
11-04-2008	B733	A	73,30	76,00	85,10
11-04-2008	B733	A	73,40	74,70	84,50
11-04-2008	B738	A	74,10	77,40	85,50
11-04-2008	A320	A	72,70	76,00	85,30
11-04-2008	E170	A	70,60	72,70	81,80
11-04-2008	E170	A	73,00	76,10	85,30

11-04-2008	AT45	A	72,20	73,60	82,20
11-04-2008	A320	A	71,30	73,10	82,40
11-04-2008	A320	A	69,00	70,40	80,20
11-04-2008	A319	A	73,40	76,40	86,10
11-04-2008	B733	A	72,60	74,70	83,70
11-04-2008	B735	A	72,40	74,20	83,80
11-04-2008	E170	A	70,50	72,10	80,90
11-04-2008	E170	A	70,60	72,70	81,40
11-04-2008	B752	A	73,40	75,70	85,70
11-04-2008	B734	A	72,00	73,80	83,20
11-04-2008	E145	A	69,40	71,00	79,80
11-04-2008	AT72	A	72,30	75,40	84,10
11-04-2008	AT72	A	74,20	76,50	86,20
11-04-2008	E170	A	70,90	72,70	82,00
11-04-2008	E170	A	70,40	73,10	81,50
11-04-2008	MD82	A	75,20	79,10	87,00
11-04-2008	RJ85	A	72,40	74,80	83,20
11-04-2008	E170	A	73,20	75,10	84,60
11-04-2008	E170	A	72,20	74,30	83,30
11-04-2008	B738	A	73,60	75,90	85,30
11-04-2008	B763	D	73,40	76,80	86,60
11-04-2008	RJ85	D	68,90	71,10	81,00
11-04-2008	B733	D	71,70	74,00	83,20
11-04-2008	B762	D	72,70	76,30	85,70
11-04-2008	E170	D	68,70	72,60	82,30
11-04-2008	B752	D	68,20	71,00	80,50
11-04-2008	B738	D	70,50	73,80	84,30
11-04-2008	F100	D	69,50	72,70	82,20
11-04-2008	A319	D	69,70	72,10	82,90
11-04-2008	B734	D	69,70	71,50	82,00
11-04-2008	GLEX	D	67,90	70,10	80,20
11-04-2008	E170	D	69,80	72,20	83,80
11-04-2008	T154	D	75,90	80,10	88,90
11-04-2008	B763	D	75,90	80,10	88,90
11-04-2008	E170	D	68,70	71,30	81,90
11-04-2008	B733	D	70,00	72,20	81,70
11-04-2008	B735	D	69,40	71,70	82,20
11-04-2008	A320	D	69,00	70,50	82,10
11-04-2008	B738	D	69,10	70,10	79,10
11-04-2008	AT72	D	67,40	71,00	78,80
12-04-2008	B752	A	71,80	73,60	83,80
12-04-2008	E170	A	71,40	73,70	82,80
12-04-2008	AT45	A	72,40	73,80	83,60
12-04-2008	AT72	A	73,50	75,80	85,50
12-04-2008	E170	A	71,80	74,30	83,00
12-04-2008	AT72	A	70,70	72,70	82,70
12-04-2008	E170	A	70,70	73,00	81,50
12-04-2008	E145	A	71,00	73,30	81,40
12-04-2008	A319	A	72,80	75,00	84,50
12-04-2008	B736	A	70,90	72,80	82,40
12-04-2008	B735	A	73,00	74,90	84,20
12-04-2008	A320	A	71,20	73,50	82,30
12-04-2008	CRJ2	A	68,80	70,10	79,60
12-04-2008	AT72	A	73,20	75,50	84,40
12-04-2008	RJ85	A	71,10	73,40	81,80
12-04-2008	AT45	A	72,00	74,60	83,80



12-04-2008	B734	A	76,40	80,40	88,70
12-04-2008	E190	A	71,20	72,90	82,00
12-04-2008	RJ1H	A	73,10	76,80	85,40
12-04-2008	E170	A	72,60	75,80	83,80
12-04-2008	B762	A	74,10	78,40	86,90
12-04-2008	B735	A	73,50	76,70	85,60
12-04-2008	B735	A	72,60	74,80	84,40
12-04-2008	B763	A	74,90	78,20	87,70
12-04-2008	E145	A	69,40	70,40	79,40
12-04-2008	E170	A	72,00	74,70	83,70
12-04-2008	E170	A	71,70	74,40	83,70
12-04-2008	AT72	A	74,60	77,40	87,40
12-04-2008	YK40	A	71,90	74,60	82,70
12-04-2008	E170	D	68,20	70,50	79,30
12-04-2008	T154	D	71,70	74,80	87,30
12-04-2008	E170	D	69,90	72,90	83,30
12-04-2008	B735	D	71,50	74,20	84,00
12-04-2008	E170	D	69,30	72,90	83,40
12-04-2008	B735	D	70,00	72,90	82,30
12-04-2008	B735	A	72,00	74,60	84,80
12-04-2008	AT45	A	70,00	72,60	82,00
12-04-2008	AT43	A	70,60	74,20	83,60
12-04-2008	E170	A	72,10	74,40	83,90
12-04-2008	B735	A	73,80	78,60	85,20
12-04-2008	DH8D	A	73,80	75,50	85,20
12-04-2008	A319	A	74,00	77,50	85,50
12-04-2008	E170	A	72,10	74,20	83,80
12-04-2008	AT45	A	71,50	75,20	84,10
12-04-2008	E170	A	71,40	74,20	82,90
12-04-2008	E170	A	72,80	75,90	84,00
12-04-2008	B735	A	73,60	78,30	85,90
12-04-2008	B737	A	72,60	76,90	86,10
12-04-2008	AT45	A	71,30	73,90	83,60
12-04-2008	E170	A	71,00	74,50	83,00
12-04-2008	E170	A	71,50	75,20	84,00
12-04-2008	B734	A	73,60	77,50	85,90
12-04-2008	E145	A	69,50	70,90	80,00
12-04-2008	AT72	A	72,30	74,40	83,80
12-04-2008	E170	A	70,60	74,10	82,00
12-04-2008	B735	A	72,80	75,10	84,80
12-04-2008	AT72	A	71,40	74,40	83,70
12-04-2008	A319	A	72,40	76,10	84,70
12-04-2008	CRJ7	A	70,80	74,10	81,90
12-04-2008	B734	A	72,70	75,70	84,80
12-04-2008	A320	A	72,00	75,40	84,30
12-04-2008	F2TH	A	71,90	74,60	82,70
12-04-2008	A320	A	71,70	74,10	84,10
12-04-2008	B734	A	75,10	79,30	88,10
12-04-2008	A320	A	71,80	74,20	83,50
12-04-2008	A319	A	71,70	74,40	84,50
12-04-2008	E170	A	70,50	72,80	82,00
12-04-2008	AT72	A	69,80	73,10	79,80
12-04-2008	RJ1H	A	69,00	70,90	79,00
12-04-2008	A320	A	73,40	76,30	85,70
12-04-2008	E170	A	70,50	74,20	82,30
12-04-2008	AT72	A	72,30	74,40	84,00

12-04-2008	B733	A	72,70	75,90	83,80
12-04-2008	E170	A	70,30	72,80	81,10
12-04-2008	E170	A	70,40	72,40	80,80
12-04-2008	A319	A	72,00	74,80	84,10
12-04-2008	DH8D	A	68,90	71,20	80,10
12-04-2008	B735	A	72,00	76,50	83,40
12-04-2008	F100	A	70,70	74,00	81,90
12-04-2008	B733	A	73,60	76,90	85,10
12-04-2008	AT72	A	73,30	75,60	85,10
12-04-2008	E170	A	70,10	72,20	81,90
12-04-2008	E145	A	67,90	69,20	78,30
12-04-2008	B738	A	73,30	78,00	86,30
12-04-2008	E145	A	69,70	71,80	79,70
12-04-2008	E170	A	71,50	74,40	83,80
12-04-2008	B733	A	72,90	77,40	86,50
12-04-2008	E170	A	71,10	74,30	82,90
12-04-2008	B735	A	71,80	76,30	85,60
12-04-2008	E145	A	68,10	69,10	78,10
12-04-2008	AT45	A	69,80	72,20	80,90
12-04-2008	E170	A	70,60	72,90	82,40
12-04-2008	E170	A	70,60	74,00	83,90
12-04-2008	E170	A	72,80	76,20	84,80
12-04-2008	E170	A	70,70	73,50	82,70
12-04-2008	AT45	A	72,10	75,20	84,70
12-04-2008	B733	A	74,40	78,30	86,20
12-04-2008	E145	A	68,30	69,50	78,30
12-04-2008	B734	A	73,70	79,20	86,20
12-04-2008	AT72	A	71,00	74,00	83,80
12-04-2008	AT72	A	70,60	73,70	83,40
12-04-2008	B734	A	74,60	78,40	86,30
13-04-2008	E170	A	71,60	73,60	84,10
13-04-2008	AT45	A	70,90	74,40	82,60
13-04-2008	E170	A	71,40	73,90	82,90
13-04-2008	AT72	A	72,10	74,80	85,30
13-04-2008	RJ85	A	71,30	73,60	82,70
13-04-2008	B738	A	73,30	77,50	86,30
13-04-2008	CRJ2	A	70,00	72,00	81,40
13-04-2008	B738	A	72,70	76,30	86,20
13-04-2008	AT72	A	70,10	72,90	82,10
13-04-2008	B734	A	73,70	77,50	86,00
13-04-2008	B762	A	72,80	77,30	87,40
13-04-2008	F100	A	70,40	74,10	81,90
13-04-2008	E190	A	71,40	73,70	83,40
13-04-2008	DH8D	A	71,30	75,20	84,30
13-04-2008	B735	A	72,70	75,50	85,00
13-04-2008	B733	A	74,10	79,30	87,20
13-04-2008	A320	A	71,70	74,30	83,80
13-04-2008	A319	A	71,90	75,10	84,20
13-04-2008	AT45	A	71,60	74,20	83,90
13-04-2008	B763	A	77,80	80,80	91,60
13-04-2008	AT72	A	72,70	74,80	84,50
13-04-2008	AT45	A	69,90	72,40	83,10
13-04-2008	T154	A	76,50	81,90	90,70
13-04-2008	B735	A	72,90	76,40	86,20
13-04-2008	E145	A	69,90	72,20	80,70
13-04-2008	B733	A	75,00	78,70	87,50

13-04-2008	AT72	A	72,50	75,60	85,50
13-04-2008	B738	A	72,60	75,50	85,40
13-04-2008	E145	A	67,30	68,60	77,30
13-04-2008	A320	A	73,60	76,40	86,40
13-04-2008	E170	A	71,30	72,80	83,30
13-04-2008	A320	A	73,80	77,70	86,80
13-04-2008	A320	A	71,50	74,00	83,50
13-04-2008	A320	A	71,40	75,10	86,50
13-04-2008	E170	A	70,80	74,00	82,80
13-04-2008	A319	A	72,80	76,20	84,80
13-04-2008	F2TH	A	70,30	72,00	81,10
13-04-2008	MD82	A	72,30	74,90	84,30
13-04-2008	A319	A	73,30	76,40	84,80
13-04-2008	B733	A	71,80	74,10	84,30
13-04-2008	B734	A	73,50	80,20	86,10
13-04-2008	B735	A	74,90	79,60	86,70
13-04-2008	AT72	A	70,90	72,80	83,70
13-04-2008	E170	A	71,40	74,30	82,80
13-04-2008	RJ85	A	69,10	70,60	80,20
13-04-2008	E145	A	69,10	70,80	80,30
13-04-2008	GLF4	A	68,90	71,30	79,60
13-04-2008	E170	A	70,20	73,10	83,60
13-04-2008	B738	A	74,20	78,10	88,00
13-04-2008	E170	A	72,00	74,90	83,80
13-04-2008	AT72	A	71,00	73,90	83,60
13-04-2008	AT45	A	70,90	72,50	82,00
13-04-2008	B763	A	78,40	82,10	92,20
13-04-2008	A320	A	72,20	76,90	85,20
13-04-2008	AT72	A	73,10	77,20	86,30
13-04-2008	F100	A	69,30	70,80	80,10
13-04-2008	E170	A	71,00	75,30	84,60
13-04-2008	E170	A	71,50	74,50	83,50
13-04-2008	AT45	A	70,00	73,20	82,30
13-04-2008	A319	A	72,80	75,00	85,10
13-04-2008	AT45	A	71,30	73,60	83,00
13-04-2008	E170	A	72,40	75,40	83,80
13-04-2008	DH8D	A	69,60	73,70	83,30
13-04-2008	A318	A	71,60	75,30	85,60
13-04-2008	AT72	A	72,20	76,80	85,00
13-04-2008	E170	A	71,10	75,10	82,80
13-04-2008	B735	A	73,50	78,00	85,60
13-04-2008	E170	A	71,00	73,50	82,10
13-04-2008	E170	A	71,70	74,40	83,50
13-04-2008	AT72	A	72,80	76,20	85,30
13-04-2008	E170	A	71,60	75,00	83,90
13-04-2008	A320	A	72,50	76,30	85,30
13-04-2008	AT72	A	70,50	73,90	82,30
13-04-2008	E170	A	71,80	74,30	83,20
13-04-2008	AT45	A	71,80	74,10	83,80
13-04-2008	B734	A	71,20	77,20	86,60
13-04-2008	B735	A	73,60	78,50	86,20
13-04-2008	E170	A	71,40	73,40	83,70
13-04-2008	E170	A	71,00	73,30	82,40
13-04-2008	B734	A	73,10	75,50	84,80
13-04-2008	A319	A	74,60	78,70	87,40
13-04-2008	AT72	A	71,90	74,40	83,90

13-04-2008	B735	A	73,90	78,10	85,70
13-04-2008	A320	A	71,30	74,10	84,60
13-04-2008	B733	A	73,10	76,50	85,10
13-04-2008	AT72	A	75,30	77,50	86,80
13-04-2008	B735	A	72,50	75,70	84,60
13-04-2008	A320	A	71,40	73,90	83,40
13-04-2008	P180	A	75,10	81,30	91,60
13-04-2008	A320	A	71,30	73,70	82,70
13-04-2008	B733	A	71,90	74,60	83,30
13-04-2008	AT72	A	74,40	76,80	86,90
13-04-2008	A319	A	72,30	74,70	84,30
13-04-2008	B733	A	72,80	77,10	85,60
13-04-2008	B735	A	71,80	74,30	83,60
13-04-2008	YK40	A	73,00	75,90	84,10
13-04-2008	AT72	A	71,30	74,40	83,90
13-04-2008	AT72	A	72,70	77,40	85,50
13-04-2008	DH8D	A	69,00	70,00	79,00
13-04-2008	B735	A	75,10	80,20	87,40
13-04-2008	B733	A	74,40	78,70	86,40
13-04-2008	B735	A	67,60	72,50	78,40
13-04-2008	B735	A	72,40	79,90	88,80
13-04-2008	B735	A	73,40	76,80	85,10
13-04-2008	E145	A	69,10	70,50	79,50
13-04-2008	F100	A	72,10	74,80	84,40
13-04-2008	B733	A	73,10	76,30	84,90
13-04-2008	AT72	A	72,10	74,40	84,40
13-04-2008	F70	A	69,10	70,80	80,20
13-04-2008	E170	A	71,90	74,20	84,00
13-04-2008	B735	A	72,50	75,50	84,30
13-04-2008	E170	A	70,40	72,60	81,60
13-04-2008	E145	A	69,80	71,00	79,80
13-04-2008	C25A	A	69,50	70,50	79,50
13-04-2008	E170	A	70,00	72,10	81,20
13-04-2008	B737	A	72,00	74,40	83,80
13-04-2008	A320	A	73,50	78,20	85,50
13-04-2008	B735	A	73,90	78,90	85,30
13-04-2008	E170	A	71,20	73,30	82,90
13-04-2008	E170	A	69,80	71,30	80,60
13-04-2008	E170	A	70,40	72,90	81,60
13-04-2008	B738	A	73,80	76,40	85,00
13-04-2008	E170	A	70,20	72,70	81,30
13-04-2008	B734	A	73,10	77,40	85,90
13-04-2008	AT72	A	72,80	75,10	84,50
13-04-2008	E170	A	70,70	72,30	82,10
13-04-2008	AT72	A	71,10	73,70	82,50
13-04-2008	E170	A	70,90	72,70	81,70
13-04-2008	AT45	A	71,10	73,10	82,90
13-04-2008	E170	A	70,20	72,00	81,70
13-04-2008	E170	A	71,20	75,90	84,50
13-04-2008	B734	A	74,30	77,30	85,80
13-04-2008	AT72	A	73,00	75,60	84,50
14-04-2008	B752	A	73,20	75,40	85,20
14-04-2008	E170	A	70,70	72,60	81,50
14-04-2008	AT72	A	71,40	73,70	84,20
14-04-2008	AT72	A	74,10	76,00	85,20
14-04-2008	E170	A	70,20	71,90	81,60

14-04-2008	E170	A	71,20	73,50	82,70
14-04-2008	AT72	A	73,80	76,80	85,80
14-04-2008	AT72	A	72,10	74,00	82,90
14-04-2008	E170	A	70,00	72,20	81,70
14-04-2008	AT45	A	71,40	73,20	82,10
14-04-2008	B734	A	73,80	77,50	85,20
14-04-2008	AT72	A	72,10	74,20	83,60
14-04-2008	B734	A	73,90	78,10	85,10
14-04-2008	B735	A	73,20	74,80	84,00
14-04-2008	F70	A	69,60	71,80	80,00
14-04-2008	B738	A	72,90	75,30	84,40
14-04-2008	AT72	A	72,80	75,10	84,60
14-04-2008	B763	A	74,20	77,50	87,20
14-04-2008	FA20	A	68,80	70,40	79,20
14-04-2008	CRJ2	A	69,80	72,00	80,90
14-04-2008	CRJ2	A	70,20	72,70	81,00
14-04-2008	B733	A	74,00	76,00	84,40
14-04-2008	F100	A	69,70	71,50	80,50
14-04-2008	B735	A	73,20	76,20	85,00
14-04-2008	E190	A	71,50	74,70	83,00
14-04-2008	DH8D	A	70,30	71,80	81,40
14-04-2008	B735	A	72,00	74,20	83,20
14-04-2008	B737	A	71,70	74,60	82,80
14-04-2008	A320	A	71,00	72,70	82,20
14-04-2008	B735	A	73,30	76,00	83,70
14-04-2008	B735	A	73,30	77,00	84,80
14-04-2008	F900	A	70,00	72,30	80,80
14-04-2008	E170	A	70,30	72,70	80,70
14-04-2008	E170	A	70,90	72,40	81,30
14-04-2008	AT72	A	71,20	74,70	82,30
14-04-2008	B735	A	72,30	75,00	83,40
14-04-2008	E145	A	67,60	68,50	77,60
14-04-2008	IL62	A	79,00	83,30	92,00
14-04-2008	AT72	A	72,10	73,90	82,90
14-04-2008	E170	A	70,90	73,20	82,40
14-04-2008	T154	A	74,20	78,30	87,50
14-04-2008	E170	A	71,00	73,50	81,80
14-04-2008	B735	A	72,40	74,60	83,10
14-04-2008	E170	A	70,90	73,30	82,10
14-04-2008	B733	A	71,60	74,30	83,30
14-04-2008	AT72	A	72,80	75,00	83,90
14-04-2008	AT72	A	72,80	75,70	84,20
14-04-2008	B733	A	72,90	75,00	84,00
14-04-2008	B735	A	72,70	76,20	84,10
14-04-2008	B763	A	72,80	75,80	86,20
14-04-2008	B703	A	74,50	78,60	89,90
14-04-2008	E170	A	70,80	74,00	83,60
14-04-2008	E170	A	70,90	73,10	81,70
14-04-2008	B703	A	80,10	86,00	94,60
14-04-2008	E170	A	70,90	73,30	82,40
14-04-2008	YK40	A	71,60	73,80	81,60
14-04-2008	AT72	A	71,20	76,30	85,50
14-04-2008	AT72	A	66,90	69,90	80,50
14-04-2008	B733	A	74,20	78,60	84,60
14-04-2008	A320	A	71,40	73,60	83,70
14-04-2008	A319	A	72,30	75,10	84,40

14-04-2008	A320	A	72,30	75,30	84,60
14-04-2008	A320	A	72,10	75,10	83,50
14-04-2008	E170	A	71,60	73,90	82,00
14-04-2008	AT72	A	73,60	76,30	84,10
14-04-2008	MD82	A	72,90	75,60	84,90
14-04-2008	E170	A	71,40	73,30	82,20
14-04-2008	B734	A	74,50	78,80	85,30
14-04-2008	E145	A	68,80	70,80	79,20
14-04-2008	A321	A	72,10	74,70	82,50
14-04-2008	E170	A	71,50	73,70	82,30
14-04-2008	E170	A	74,00	78,00	84,00
14-04-2008	E170	A	71,60	73,30	82,30
14-04-2008	B763	A	75,00	79,00	87,30
14-04-2008	B762	A	73,20	76,60	85,30
14-04-2008	D328	A	70,20	72,40	81,00
14-04-2008	B733	A	74,60	79,20	85,00
14-04-2008	A320	A	72,70	75,30	83,10
14-04-2008	A320	A	72,60	75,70	84,70
14-04-2008	B733	A	71,30	73,20	82,10
14-04-2008	B735	A	72,10	73,70	82,90
14-04-2008	B735	A	73,20	76,30	83,60
14-04-2008	B763	A	73,30	76,80	85,60
14-04-2008	E170	A	70,90	73,60	82,00
14-04-2008	AT72	A	70,60	72,90	81,40
14-04-2008	E170	A	70,20	72,30	81,00
14-04-2008	B735	A	73,00	75,50	83,00
14-04-2008	E170	A	70,60	72,60	81,00
14-04-2008	E170	A	70,10	72,20	80,10
14-04-2008	E170	A	71,30	72,90	82,50
14-04-2008	A319	A	72,50	74,70	83,30
14-04-2008	B734	A	71,80	74,50	83,50
14-04-2008	E170	A	70,20	72,80	81,30
14-04-2008	AT72	A	72,40	75,20	83,50
14-04-2008	AT72	A	72,60	75,00	84,10
14-04-2008	B733	A	71,50	74,80	82,70
14-04-2008	A320	A	71,90	74,30	82,30
14-04-2008	E170	A	69,10	71,70	79,50
14-04-2008	B734	A	72,20	74,70	83,00
14-04-2008	T154	A	73,10	76,10	85,90
14-04-2008	E170	A	71,40	73,70	81,40
14-04-2008	B735	A	72,70	77,30	84,50
14-04-2008	A320	A	74,00	77,10	86,10
14-04-2008	AT72	A	71,20	75,90	84,80
14-04-2008	B734	D	70,60	74,00	84,60
14-04-2008	B735	D	68,50	70,50	79,30
14-04-2008	B762	D	69,90	73,10	83,10
14-04-2008	FA20	D	68,80	71,70	79,60
14-04-2008	B733	D	71,00	73,20	82,20
14-04-2008	YK40	D	69,90	72,70	83,70
15-04-2008	A320	D	69,90	71,40	81,90
15-04-2008	YK40	D	71,30	73,90	84,30
15-04-2008	B738	D	68,80	71,30	80,60
15-04-2008	A320	D	69,10	71,70	81,90
15-04-2008	E170	D	67,70	70,20	77,70
15-04-2008	B734	D	71,20	74,30	84,00
15-04-2008	MD11	D	75,10	80,40	91,60

15-04-2008	B733	D	70,70	72,80	83,00
15-04-2008	B763	D	73,20	75,40	85,80
15-04-2008	B738	D	70,60	73,70	83,60
15-04-2008	E170	D	68,40	70,60	80,70
15-04-2008	B734	D	69,30	72,10	82,50
15-04-2008	B735	D	68,90	72,30	81,70
15-04-2008	B735	D	68,60	71,00	78,60
15-04-2008	E170	D	68,40	69,70	78,80
15-04-2008	B763	D	73,10	77,40	86,50
15-04-2008	AT72	D	66,00	69,50	78,00
16-04-2008	B733	D	71,80	74,90	83,50
16-04-2008	B752	D	70,90	73,50	83,70
16-04-2008	E145	A	68,80	71,40	79,60
16-04-2008	E170	A	69,60	71,50	80,70
16-04-2008	AT72	A	70,40	72,70	81,50
16-04-2008	E170	A	70,80	72,90	82,00
16-04-2008	B733	A	69,50	71,70	82,50
16-04-2008	C550	A	67,20	68,10	77,20
16-04-2008	E170	A	71,40	73,30	82,80
16-04-2008	B735	A	73,60	77,90	85,30
16-04-2008	A320	A	73,00	76,30	85,30
16-04-2008	B733	A	71,90	74,90	84,40
16-04-2008	A320	A	68,30	69,80	78,30
16-04-2008	A320	A	74,10	77,20	86,60
16-04-2008	AT72	A	73,30	76,10	85,60
16-04-2008	B733	A	74,20	77,50	85,70
16-04-2008	A319	A	72,60	75,80	85,60
16-04-2008	E170	A	73,20	76,30	84,40
16-04-2008	B735	A	72,80	77,00	85,30
16-04-2008	MD82	A	75,30	79,70	87,60
16-04-2008	AT72	A	73,00	74,90	85,00
16-04-2008	AT72	A	73,50	77,00	85,50
16-04-2008	E170	A	69,80	72,00	81,60
16-04-2008	B734	A	74,40	78,50	85,60
16-04-2008	AT72	A	70,30	74,10	85,00
16-04-2008	E170	A	69,60	71,10	80,10
16-04-2008	A320	A	76,40	80,10	89,40
16-04-2008	B738	A	73,00	75,20	85,00
16-04-2008	B738	A	74,90	79,20	88,10
16-04-2008	E170	A	71,70	74,70	83,40
16-04-2008	E170	A	71,10	75,00	83,40
16-04-2008	E170	A	71,60	75,00	84,20
16-04-2008	AT72	A	71,10	72,40	81,90
16-04-2008	B733	A	72,30	74,60	84,00
16-04-2008	A320	A	73,10	75,80	84,30
16-04-2008	A320	A	69,90	71,60	81,40
16-04-2008	A319	A	74,60	77,70	86,90
16-04-2008	A319	A	73,20	78,10	85,50
17-04-2008	E170	A	69,20	70,50	79,60
17-04-2008	E170	A	72,10	74,50	83,90
17-04-2008	A319	A	70,70	72,10	81,10
17-04-2008	A320	A	73,00	76,10	83,80
17-04-2008	E170	A	70,80	73,10	81,20
17-04-2008	CRJ2	A	70,80	72,60	82,30
17-04-2008	B735	A	75,80	79,00	88,80
17-04-2008	B735	A	74,20	76,60	86,00

17-04-2008	GLEX	A	71,30	74,30	83,60
17-04-2008	AT72	A	75,80	79,10	88,90
17-04-2008	B735	A	72,30	74,40	83,10
17-04-2008	E145	A	70,70	72,80	81,50
17-04-2008	E170	A	71,60	73,80	83,00
17-04-2008	B735	A	71,10	73,00	81,90
17-04-2008	RJ1H	A	72,70	74,60	84,10
17-04-2008	AT72	A	70,90	74,00	82,70
17-04-2008	E145	A	72,20	75,40	84,50
17-04-2008	B738	A	73,70	77,00	85,70
17-04-2008	B734	A	70,70	73,00	82,50
17-04-2008	A320	A	71,30	73,60	82,10
17-04-2008	E170	A	71,60	74,90	82,40
17-04-2008	A320	A	71,90	75,90	84,20
17-04-2008	E170	A	70,00	73,00	81,80
17-04-2008	PC12	A	76,60	80,80	89,10
17-04-2008	A320	A	70,10	72,30	81,60
17-04-2008	AT72	A	70,90	73,00	82,00
17-04-2008	E170	A	73,10	77,30	84,80
17-04-2008	AT45	A	73,30	75,70	84,40
17-04-2008	B734	A	72,00	76,20	83,50
17-04-2008	B735	A	69,90	71,50	81,40
17-04-2008	B735	A	70,80	72,60	81,20
17-04-2008	B733	A	69,70	71,40	80,50
17-04-2008	E170	A	74,20	77,10	86,30
17-04-2008	E145	A	71,40	74,50	83,90
17-04-2008	A320	A	74,60	80,30	86,10
17-04-2008	AT72	A	72,00	74,40	83,10
17-04-2008	H25B	A	69,50	72,90	81,50
17-04-2008	E145	A	73,40	76,00	85,90
17-04-2008	T154	A	71,80	75,90	84,60
17-04-2008	JS32	A	73,90	79,40	85,90
17-04-2008	A320	A	74,40	77,00	87,40
17-04-2008	B735	A	70,50	74,60	82,80
17-04-2008	E170	A	74,10	77,20	85,50
17-04-2008	B735	A	73,50	76,20	85,00
17-04-2008	DH8D	A	72,40	74,90	83,80
17-04-2008	B733	A	68,90	70,40	78,90
17-04-2008	CRJ2	A	70,40	72,60	80,40
17-04-2008	E145	A	71,20	73,60	82,00
17-04-2008	B462	A	73,40	76,40	86,80
17-04-2008	H25B	A	70,80	74,10	84,80
17-04-2008	E170	A	71,00	74,20	83,10
17-04-2008	B735	A	71,40	74,10	82,50
17-04-2008	E170	A	72,10	76,00	85,50
17-04-2008	E170	A	70,70	72,80	82,50
17-04-2008	AT72	A	71,10	73,10	82,20
17-04-2008	AT72	A	73,50	76,40	86,50
17-04-2008	E170	A	72,90	78,30	89,30
17-04-2008	B735	A	70,40	73,10	81,20
18-04-2008	E170	A	70,90	73,00	82,40
18-04-2008	AT72	A	73,60	76,40	86,40
18-04-2008	E170	A	71,60	73,40	82,70
18-04-2008	AT72	A	74,10	77,20	86,90
18-04-2008	AT72	A	74,10	76,50	86,40
18-04-2008	E170	A	70,60	72,60	82,40



18-04-2008	E170	A	71,40	73,40	82,90
18-04-2008	AT72	A	73,50	76,10	85,80
18-04-2008	B462	A	73,70	76,30	85,10
18-04-2008	AT45	A	71,10	73,50	82,80
18-04-2008	AT72	A	71,90	74,20	83,60
18-04-2008	AT43	A	74,60	78,90	88,40
18-04-2008	B462	A	72,60	75,20	84,40
18-04-2008	B733	A	72,50	75,90	84,80
18-04-2008	A320	A	74,00	77,50	87,00
18-04-2008	AT72	A	73,60	79,20	87,70
18-04-2008	RJ85	A	72,60	75,30	83,80
18-04-2008	E170	A	71,40	73,40	82,90
18-04-2008	YK40	D	72,90	77,30	84,30
18-04-2008	A320	A	72,20	75,50	84,80
18-04-2008	A320	A	72,20	75,10	85,00
18-04-2008	F70	A	70,80	73,60	82,60
18-04-2008	B462	A	72,10	75,10	83,80
18-04-2008	CRJ2	A	69,30	70,70	80,10
18-04-2008	AT72	A	71,50	73,40	83,30
18-04-2008	E190	A	72,60	75,00	84,30
18-04-2008	B738	A	73,30	76,20	85,80
18-04-2008	B735	A	72,90	76,30	85,70
18-04-2008	DH8D	A	71,00	73,10	81,00
18-04-2008	B735	A	74,10	77,00	85,50
18-04-2008	A320	A	72,20	74,50	84,00
18-04-2008	JS32	A	68,60	70,60	79,00
18-04-2008	E170	A	70,50	72,90	82,60
18-04-2008	E170	A	71,20	73,40	81,60
18-04-2008	B737	A	72,20	76,50	85,90
18-04-2008	A320	A	72,30	73,80	83,40
18-04-2008	B752	A	75,40	79,60	87,90
18-04-2008	AT72	A	70,70	73,00	81,50
18-04-2008	B735	A	74,40	78,30	86,20
18-04-2008	B738	A	73,20	77,10	86,50
18-04-2008	B735	A	72,90	78,50	85,50
18-04-2008	E170	A	70,20	72,50	81,70
18-04-2008	T154	A	75,60	79,90	88,60
18-04-2008	E170	A	73,40	76,50	85,40
18-04-2008	B735	A	75,00	78,60	86,80
18-04-2008	E170	A	71,50	74,20	84,10
18-04-2008	B763	A	75,60	78,40	89,40
18-04-2008	SF34	A	69,90	73,60	82,50
18-04-2008	B733	A	73,30	76,10	85,40
18-04-2008	B735	A	75,10	79,40	86,20
18-04-2008	AT72	A	71,10	73,00	82,20
18-04-2008	AT72	A	73,20	76,50	85,50
18-04-2008	B733	A	73,80	76,70	85,80
18-04-2008	B762	A	74,00	77,90	87,00
18-04-2008	P180	A	74,90	80,20	90,60
18-04-2008	E170	A	72,10	74,50	83,50
18-04-2008	A320	A	73,20	76,30	85,50
18-04-2008	E170	A	70,60	72,70	82,30
18-04-2008	B733	A	73,60	78,00	85,30
18-04-2008	A320	A	71,90	74,90	84,20
18-04-2008	A319	A	71,50	74,10	84,30
18-04-2008	B752	A	72,10	74,60	85,50

18-04-2008	B735	A	71,50	74,30	84,00
18-04-2008	T154	A	75,10	78,40	87,70
18-04-2008	E170	A	69,60	71,70	80,00
18-04-2008	MD82	A	73,50	76,60	86,30
18-04-2008	F2TH	A	69,70	71,60	80,40
18-04-2008	AT72	A	71,30	73,60	83,30
18-04-2008	AT45	A	72,40	74,80	84,10
18-04-2008	B734	A	73,80	78,50	86,30
18-04-2008	E170	A	71,90	74,10	82,70
18-04-2008	AT72	A	74,60	77,70	87,20
18-04-2008	B738	A	73,80	78,00	87,40
18-04-2008	E170	A	70,90	73,30	82,00
18-04-2008	RJ85	A	70,70	74,80	83,20
18-04-2008	AT72	A	73,80	76,40	85,50
18-04-2008	E170	A	72,00	76,70	84,80
18-04-2008	E190	A	72,00	74,60	83,50
18-04-2008	PC12	A	71,60	76,50	84,70
18-04-2008	B733	A	72,90	76,80	85,20
18-04-2008	B733	A	72,90	75,70	84,30
18-04-2008	B763	A	74,50	78,30	88,70
18-04-2008	A320	A	72,80	76,20	85,90
18-04-2008	A320	A	72,50	75,20	84,80
18-04-2008	AT72	A	73,90	76,60	86,70
18-04-2008	F100	A	70,60	72,90	82,00
18-04-2008	AT72	A	70,60	73,40	82,60
18-04-2008	A319	A	72,60	75,60	84,70
18-04-2008	FA10	A	70,30	72,00	80,30
18-04-2008	E170	A	71,30	73,70	82,40
18-04-2008	AT45	A	72,10	74,60	83,90
18-04-2008	E170	A	73,30	76,40	85,90
18-04-2008	DH8D	A	72,50	74,50	83,60
18-04-2008	B735	A	72,40	75,00	84,10
18-04-2008	B735	A	73,60	76,40	84,70
18-04-2008	A320	A	72,50	75,60	84,50
18-04-2008	A319	A	72,60	75,80	84,70
18-04-2008	AT45	A	71,00	73,30	82,10
18-04-2008	B735	A	73,10	76,60	84,90
18-04-2008	B735	A	73,40	77,40	85,40
18-04-2008	E170	A	70,90	73,30	82,40
18-04-2008	E170	A	71,10	73,30	82,50
18-04-2008	E170	A	71,20	72,90	82,70
18-04-2008	AT72	A	73,50	77,70	87,10
18-04-2008	C56X	A	70,90	72,90	81,70
18-04-2008	B734	A	73,80	77,60	85,80
18-04-2008	E145	A	70,20	72,70	81,40
18-04-2008	A320	A	71,50	74,30	84,10
18-04-2008	E170	A	70,90	73,60	82,40
18-04-2008	B734	A	73,70	79,30	86,50
18-04-2008	B735	A	72,50	76,80	85,50
18-04-2008	E170	A	71,70	74,00	83,20
18-04-2008	E145	A	70,30	73,00	82,10
18-04-2008	E170	A	72,10	76,50	85,30
18-04-2008	BE20	A	73,20	76,80	83,20
18-04-2008	B734	A	75,30	79,80	86,80
18-04-2008	AT72	A	72,60	76,80	85,20
18-04-2008	E170	A	71,80	74,80	83,80

18-04-2008	A320	A	72,70	74,40	84,10
18-04-2008	AT72	A	75,50	78,30	87,30
18-04-2008	AT72	A	71,70	74,00	84,00
18-04-2008	A319	A	70,40	72,90	83,00
18-04-2008	AT45	A	71,40	73,40	82,90
18-04-2008	A320	A	70,00	72,90	83,00
18-04-2008	A320	A	72,20	75,40	85,00
18-04-2008	B733	A	72,70	76,30	85,70
18-04-2008	RJ85	A	70,30	72,20	81,40
18-04-2008	AT72	A	73,60	78,10	88,20
18-04-2008	RJ1H	A	69,00	71,30	80,50
18-04-2008	A320	A	71,50	73,60	82,70
18-04-2008	B733	A	73,10	75,90	85,40
18-04-2008	A320	A	73,00	75,70	85,00
18-04-2008	E170	A	75,00	79,00	86,70
18-04-2008	A318	A	72,40	75,50	85,80
18-04-2008	AT72	A	74,80	77,80	86,30
18-04-2008	E170	A	71,30	74,20	83,00
18-04-2008	E170	A	71,90	75,10	83,90
18-04-2008	E170	A	71,60	74,50	83,30
18-04-2008	B752	A	72,10	74,40	85,50
18-04-2008	B733	A	72,70	75,30	84,80
18-04-2008	E170	A	71,50	73,70	83,50
18-04-2008	AT72	A	73,20	76,30	85,70
18-04-2008	E170	A	70,90	73,60	83,90
18-04-2008	DH8D	A	69,40	71,10	80,90
18-04-2008	A320	A	73,80	77,00	85,80
18-04-2008	SF34	A	69,10	70,40	79,10
18-04-2008	B735	A	73,70	77,50	85,50
18-04-2008	MD11	A	76,80	81,30	91,80
18-04-2008	A320	A	72,40	75,60	84,70
18-04-2008	AT45	A	72,40	74,50	83,20
18-04-2008	B736	A	71,10	74,10	84,60
18-04-2008	GLF4	A	71,80	75,80	84,10
18-04-2008	CRJ2	A	70,40	72,30	81,90
18-04-2008	F100	A	71,50	73,60	83,00
18-04-2008	E145	A	70,00	71,30	80,40
18-04-2008	B462	A	72,40	74,80	83,50
18-04-2008	L410	A	68,90	70,70	78,90
18-04-2008	AT72	A	71,00	73,60	82,80
18-04-2008	B738	A	74,70	77,40	87,00
18-04-2008	B738	A	72,90	75,60	85,20
18-04-2008	E170	A	69,10	70,80	80,30
18-04-2008	CRJ2	A	68,90	70,10	79,30
18-04-2008	E170	A	70,50	72,50	81,70
18-04-2008	AT72	A	72,00	75,10	85,40
18-04-2008	B735	A	74,10	78,20	85,90
18-04-2008	B735	A	72,90	74,80	84,70
18-04-2008	B737	A	72,10	74,50	83,90
18-04-2008	E170	A	71,10	73,50	82,60
18-04-2008	E170	A	71,60	74,20	83,30
18-04-2008	E170	A	70,50	72,70	81,60
18-04-2008	E145	A	68,60	69,40	78,60
18-04-2008	E170	A	71,60	73,90	83,40
18-04-2008	E170	A	70,20	72,30	81,70
18-04-2008	AT45	A	74,50	76,80	86,30

18-04-2008	B735	A	73,80	78,00	85,60
18-04-2008	E170	A	72,00	74,70	83,80
18-04-2008	AT72	A	73,60	76,00	86,20
18-04-2008	SF34	A	70,70	72,50	80,70
18-04-2008	B734	A	75,50	79,70	88,10
18-04-2008	AT72	A	70,80	72,60	82,20
18-04-2008	E170	A	70,50	72,90	81,90
18-04-2008	B738	A	73,20	76,10	85,70
18-04-2008	A320	A	73,60	76,20	85,90
18-04-2008	SF34	A	70,60	73,10	81,00
19-04-2008	A320	A	73,10	76,10	85,40
19-04-2008	B735	A	72,30	74,40	83,70
19-04-2008	B735	A	73,50	77,00	84,60
19-04-2008	E170	A	72,20	74,30	84,00
19-04-2008	E170	A	70,60	72,60	81,70
19-04-2008	AT72	A	74,20	76,70	85,90
19-04-2008	E170	A	70,90	73,40	82,00
19-04-2008	AT72	A	73,70	75,70	86,30
19-04-2008	AT45	A	71,70	73,80	83,70
19-04-2008	AT72	A	73,30	75,90	83,70
19-04-2008	RJ85	A	70,80	73,60	82,30
19-04-2008	AT72	A	72,10	74,40	83,50
19-04-2008	CRJ2	A	69,20	70,50	79,60
19-04-2008	AT45	A	71,40	72,70	81,80
19-04-2008	AT72	A	74,40	77,60	87,50
19-04-2008	B736	A	70,30	73,60	81,40
19-04-2008	E190	A	74,00	77,70	85,80
19-04-2008	B734	A	75,00	79,80	88,00
19-04-2008	E145	A	70,20	72,70	81,40
19-04-2008	B763	A	74,70	78,50	88,50
19-04-2008	CRJ2	A	70,50	74,00	82,30
19-04-2008	A320	A	72,30	74,00	83,50
19-04-2008	E170	A	71,30	73,50	82,50
19-04-2008	B735	A	73,20	76,80	85,00
19-04-2008	B735	A	73,10	75,10	84,20
19-04-2008	B733	A	73,50	75,40	84,60
19-04-2008	E170	A	72,20	74,20	83,70
19-04-2008	E170	A	70,20	71,90	81,00
19-04-2008	B735	A	73,70	76,20	85,10
19-04-2008	E170	A	70,50	72,20	81,60
19-04-2008	AT72	A	71,50	74,20	82,60
19-04-2008	B763	A	74,60	79,40	87,80
19-04-2008	AT72	A	74,60	78,00	87,40
19-04-2008	T154	A	76,20	79,50	88,50
19-04-2008	AT72	A	73,50	77,30	86,50
19-04-2008	B762	A	74,70	77,30	87,30
19-04-2008	B735	A	72,70	75,70	85,20
19-04-2008	AT72	A	74,60	76,80	86,90
19-04-2008	AT72	A	74,20	78,00	86,50
19-04-2008	B763	A	74,60	78,30	88,20
19-04-2008	B735	A	73,40	77,30	85,70
19-04-2008	E170	A	69,90	72,20	81,40
19-04-2008	B733	A	72,00	74,60	84,10
19-04-2008	B735	A	73,60	78,70	85,90
19-04-2008	A320	A	72,10	74,30	84,10
19-04-2008	T154	A	75,00	78,40	88,10

19-04-2008	AT72	A	74,10	76,80	85,60
19-04-2008	A320	A	71,60	73,50	83,40
19-04-2008	B733	A	72,50	77,60	86,70
19-04-2008	B733	A	74,50	77,80	86,30
19-04-2008	B752	A	73,60	76,60	86,10
19-04-2008	A319	A	72,60	75,20	85,20
19-04-2008	E170	A	70,70	72,10	81,80
19-04-2008	E170	A	71,90	74,30	84,20
19-04-2008	B734	A	72,00	74,40	84,10
19-04-2008	E170	A	71,60	73,10	82,70
19-04-2008	E170	A	70,00	71,70	81,10
19-04-2008	RJ85	A	69,30	71,60	81,10
19-04-2008	MD82	A	72,50	76,00	84,50
19-04-2008	E170	A	74,80	77,40	85,90
19-04-2008	E170	A	71,20	73,20	83,00
19-04-2008	RJ85	A	68,90	70,20	79,70
19-04-2008	B763	A	75,80	79,00	89,00
19-04-2008	B735	A	74,30	78,40	87,10
19-04-2008	A319	A	71,60	74,10	83,70
19-04-2008	AT72	A	74,20	77,70	86,00
19-04-2008	F100	A	70,20	71,80	81,30
19-04-2008	B735	A	73,50	76,40	84,90
19-04-2008	E170	A	70,00	73,60	83,00
19-04-2008	AT45	A	70,40	71,90	81,50
19-04-2008	AT45	A	71,90	73,50	82,30
19-04-2008	B735	A	73,20	77,20	85,30
19-04-2008	E170	A	70,80	73,10	81,90
19-04-2008	B752	A	72,60	74,90	84,70
19-04-2008	DH8D	A	71,80	75,00	84,40
19-04-2008	A319	A	71,90	74,60	83,90
19-04-2008	T154	A	75,70	82,10	88,70
19-04-2008	E170	A	70,90	73,50	82,90
19-04-2008	AT72	A	73,40	76,10	85,10
19-04-2008	AT72	A	73,40	75,80	85,40
19-04-2008	B734	A	73,40	77,40	84,90
19-04-2008	E170	A	70,80	74,20	82,50
19-04-2008	GLEX	A	69,50	71,30	80,60
19-04-2008	AT72	A	72,40	75,00	84,20
19-04-2008	E170	A	71,30	73,70	82,80
19-04-2008	A320	A	72,00	73,60	83,50
19-04-2008	E170	A	70,80	72,70	82,90
19-04-2008	B737	A	72,60	76,00	85,10
19-04-2008	B735	A	73,00	77,90	85,80
19-04-2008	AT72	A	72,40	75,20	85,40
19-04-2008	E170	A	70,30	73,40	81,80
19-04-2008	E170	A	71,60	73,80	83,10
19-04-2008	AT72	A	73,70	76,40	86,00
19-04-2008	B734	A	74,60	79,10	86,40
19-04-2008	B735	A	71,40	74,20	83,40
19-04-2008	B752	A	73,50	76,60	85,80
19-04-2008	AT45	A	70,00	72,40	80,80
19-04-2008	E145	A	68,60	69,80	79,00
19-04-2008	A319	A	71,60	73,90	83,60
19-04-2008	RJ85	A	72,50	75,10	84,00
19-04-2008	P180	A	74,20	78,10	89,00
19-04-2008	A320	A	73,30	75,30	85,00

19-04-2008	B734	A	73,20	75,60	85,00
19-04-2008	E170	A	72,20	75,10	84,50
19-04-2008	A320	A	70,80	73,50	83,40
19-04-2008	AT72	A	70,40	73,00	83,40
19-04-2008	A319	A	71,80	75,10	85,20
19-04-2008	B461	A	70,60	72,40	82,10
19-04-2008	E170	A	72,20	74,30	84,20
19-04-2008	AT72	A	75,10	79,00	88,30
19-04-2008	A319	A	71,00	74,70	84,40
19-04-2008	E170	A	72,60	74,50	84,40
19-04-2008	B735	A	74,50	80,40	87,20
19-04-2008	DH8D	A	71,10	72,80	81,60
19-04-2008	B735	A	74,10	77,60	86,10
19-04-2008	AT45	A	71,30	73,10	82,40
19-04-2008	B733	A	74,80	80,40	87,30
19-04-2008	B733	A	73,90	78,20	86,20
19-04-2008	F100	A	73,40	77,20	85,50
19-04-2008	B735	A	72,60	75,30	84,90
19-04-2008	A320	A	72,20	74,70	85,00
19-04-2008	B733	A	72,90	75,00	85,20
19-04-2008	AT72	A	74,10	77,80	87,30
19-04-2008	E170	A	70,80	73,40	83,40
19-04-2008	E145	A	70,30	72,80	81,80
19-04-2008	E170	A	71,90	74,30	84,40
19-04-2008	B738	A	75,80	79,20	88,60
19-04-2008	E170	A	71,20	74,40	82,30
19-04-2008	B734	A	72,10	74,80	83,30
19-04-2008	E170	A	71,00	74,10	83,00
19-04-2008	E170	A	70,10	72,00	81,80
19-04-2008	AT72	A	70,80	72,60	83,10
19-04-2008	B735	A	74,20	78,40	87,40
19-04-2008	B733	A	73,60	77,50	85,90
19-04-2008	E170	A	71,70	74,00	83,80
19-04-2008	AT45	A	71,40	73,00	83,90
19-04-2008	AT72	A	72,30	75,30	85,40
19-04-2008	E170	A	70,50	72,90	81,60
19-04-2008	B735	A	73,00	78,30	86,00
19-04-2008	B733	A	74,20	78,80	86,20
20-04-2008	AT72	A	72,40	74,20	83,80
20-04-2008	E170	A	70,60	73,60	82,70
20-04-2008	E170	A	70,10	72,30	80,90
20-04-2008	AT72	A	73,20	76,10	85,50
20-04-2008	RJ85	A	69,30	70,90	80,10
20-04-2008	B737	A	71,90	74,60	84,00
20-04-2008	AT72	A	69,80	73,00	81,90
20-04-2008	CRJ2	A	68,60	69,50	79,00
20-04-2008	E170	A	70,40	72,40	81,50
20-04-2008	A319	A	74,10	78,00	86,60
20-04-2008	B738	A	72,90	76,10	86,30
20-04-2008	F100	A	69,80	71,50	80,90
20-04-2008	B738	A	72,60	75,60	85,10
20-04-2008	B734	A	73,80	77,30	85,60
20-04-2008	B762	A	74,70	77,90	87,50
20-04-2008	B735	A	74,70	79,10	86,40
20-04-2008	AT72	A	71,80	74,70	84,10
20-04-2008	B733	A	71,60	72,70	83,00

20-04-2008	E170	A	71,50	74,60	83,60
20-04-2008	E170	A	71,40	73,90	82,60
20-04-2008	A320	A	72,50	76,60	85,80
20-04-2008	A320	A	74,40	77,20	86,90
20-04-2008	B733	A	73,40	77,10	86,40
20-04-2008	E145	A	67,00	68,30	77,00
20-04-2008	A320	A	71,80	74,00	83,60
20-04-2008	MD82	A	73,80	76,70	85,80
20-04-2008	B734	A	74,30	78,80	86,60
20-04-2008	B735	A	73,70	76,90	86,30
20-04-2008	A319	A	70,30	77,00	81,50
20-04-2008	A319	A	72,50	76,10	85,50
20-04-2008	B733	A	74,10	77,20	85,20
20-04-2008	E145	A	68,80	70,20	79,60
20-04-2008	AT45	A	72,30	75,20	84,40
20-04-2008	A319	A	71,40	73,80	84,40
20-04-2008	AT72	A	72,50	74,80	85,10
20-04-2008	E170	A	70,90	72,10	81,70
20-04-2008	RJ85	A	71,40	74,80	83,70
20-04-2008	B738	A	74,30	78,70	87,70
20-04-2008	AN26	A	75,60	80,70	87,00
20-04-2008	E170	A	70,70	72,80	81,80
20-04-2008	E190	A	73,90	75,80	85,60
20-04-2008	AT72	A	72,90	76,40	86,60
20-04-2008	AT72	A	73,00	77,10	86,40
20-04-2008	A320	A	73,30	76,60	85,60
20-04-2008	B763	A	76,70	80,60	91,00
20-04-2008	A319	A	72,80	75,10	84,60
20-04-2008	P46T	A	69,40	71,90	80,90
20-04-2008	AT72	A	73,90	76,50	86,70
20-04-2008	F100	A	70,80	73,20	82,60
20-04-2008	B735	A	73,80	77,80	86,10
20-04-2008	AT45	A	70,80	73,70	82,50
20-04-2008	E170	A	71,90	73,70	83,00
20-04-2008	AT45	A	71,70	74,10	84,00
20-04-2008	DH8D	A	69,10	69,90	79,10
20-04-2008	E170	A	70,90	73,60	83,00
20-04-2008	A319	A	72,00	74,80	84,30
20-04-2008	E145	A	69,30	71,10	81,00
20-04-2008	B734	A	75,00	79,90	88,00
20-04-2008	B735	A	74,50	78,70	86,50
20-04-2008	E170	A	71,70	73,90	83,20
20-04-2008	AT72	A	71,20	74,70	84,40
20-04-2008	E170	A	71,70	74,30	82,90
20-04-2008	E170	A	70,80	73,00	82,80
20-04-2008	E170	A	71,90	74,80	83,90
20-04-2008	E170	A	71,10	73,10	82,90
20-04-2008	B734	A	73,60	77,50	85,70
20-04-2008	AT72	A	70,80	72,70	81,60
20-04-2008	E170	A	71,30	73,60	82,80
20-04-2008	E170	A	70,70	72,70	82,50
20-04-2008	A320	A	72,00	74,80	84,60
20-04-2008	B735	A	72,80	74,90	84,50
20-04-2008	C525	A	68,90	69,80	78,90
20-04-2008	AT72	A	74,30	79,40	88,90
20-04-2008	B734	A	74,20	77,90	86,50

20-04-2008	E170	A	71,50	74,50	83,80
20-04-2008	A319	A	71,80	73,10	83,30
20-04-2008	AT72	A	73,50	75,30	86,10
20-04-2008	RJ85	A	71,20	72,80	82,40
20-04-2008	A320	A	71,30	73,50	83,30
20-04-2008	B733	A	73,10	76,40	85,60
20-04-2008	B733	A	72,10	74,70	83,90
20-04-2008	B735	A	76,70	81,60	89,50
20-04-2008	T154	A	74,80	80,30	89,40
20-04-2008	AT72	A	72,90	76,10	85,70
20-04-2008	B734	A	74,00	78,20	86,60
20-04-2008	RJ1H	A	72,40	74,90	83,60
20-04-2008	B733	A	72,30	76,10	85,00
20-04-2008	A320	A	71,20	72,80	83,00
20-04-2008	AT72	A	71,00	72,70	82,40
20-04-2008	B735	A	72,70	76,80	85,30
20-04-2008	B735	A	73,00	75,50	85,80
20-04-2008	E170	A	72,50	75,60	84,50
20-04-2008	B738	A	74,20	78,00	87,40
20-04-2008	B733	A	71,90	74,20	84,70
20-04-2008	A319	A	72,20	75,30	85,20
20-04-2008	DH8D	A	70,80	72,60	82,30
20-04-2008	B738	A	73,00	75,50	85,50
20-04-2008	E145	A	68,90	70,20	78,90
20-04-2008	B735	A	73,30	77,70	85,40
20-04-2008	AT45	A	74,20	77,70	86,80
20-04-2008	A321	A	73,20	76,70	85,90
20-04-2008	F70	A	69,70	71,10	80,80
20-04-2008	AT45	A	73,50	76,50	86,30
20-04-2008	B735	A	72,50	74,80	84,50
20-04-2008	F100	A	70,50	72,60	81,60
20-04-2008	E170	A	71,90	74,30	83,90
20-04-2008	AT72	A	74,40	78,10	88,00
20-04-2008	E170	A	72,30	74,50	84,60
20-04-2008	SF34	A	72,00	74,90	83,10
20-04-2008	CRJ2	A	69,50	70,50	79,90
20-04-2008	B735	A	72,90	77,20	85,70
20-04-2008	AT45	A	70,60	72,20	82,40
20-04-2008	B737	A	71,60	74,30	84,10
20-04-2008	E170	A	71,40	74,00	83,40
20-04-2008	E170	A	71,50	74,10	84,70
20-04-2008	B738	A	74,20	77,70	86,70
20-04-2008	E170	A	71,50	74,30	84,30
20-04-2008	B735	A	74,00	77,60	85,70
20-04-2008	A320	A	72,70	77,80	85,70
20-04-2008	B735	A	73,40	76,50	85,10
20-04-2008	F2TH	A	70,70	72,30	81,20
20-04-2008	E145	A	68,20	68,90	78,20
20-04-2008	E170	A	71,90	74,60	83,00
20-04-2008	E170	A	72,10	74,40	84,10
20-04-2008	B734	A	73,10	77,70	86,50
20-04-2008	B735	A	73,80	78,00	85,60
20-04-2008	AT72	A	73,70	77,40	86,70
20-04-2008	E170	A	70,60	72,80	82,70
20-04-2008	T154	A	77,40	82,90	90,10
20-04-2008	E170	A	70,90	74,10	83,00



20-04-2008	AT72	A	73,90	76,70	86,70
20-04-2008	E170	A	70,40	72,90	83,00
20-04-2008	AT72	A	75,40	78,10	87,70
20-04-2008	E170	A	71,20	73,40	83,00
20-04-2008	E170	A	72,00	74,30	84,00
20-04-2008	AT72	A	73,10	75,60	86,10
20-04-2008	E170	A	71,80	74,30	83,60
21-04-2008	B463	A	73,70	76,60	84,10
21-04-2008	AT72	A	70,10	71,80	80,90
21-04-2008	AT72	A	75,20	78,40	88,00
21-04-2008	E170	A	71,80	74,10	83,20
21-04-2008	AT45	A	71,60	73,50	83,40
21-04-2008	B462	A	70,60	72,00	82,00
21-04-2008	AT72	A	74,70	77,80	86,10
21-04-2008	E170	A	71,50	73,80	83,00
21-04-2008	E170	A	71,40	74,10	83,10
21-04-2008	E145	A	69,80	70,90	79,80
21-04-2008	AT72	A	73,70	75,90	85,50
21-04-2008	E170	A	71,30	73,10	82,40
21-04-2008	YK40	D	73,30	76,90	84,50
21-04-2008	AT45	A	72,20	73,80	83,60
21-04-2008	B733	A	73,00	74,90	84,50
21-04-2008	AT72	A	71,60	73,50	83,00
21-04-2008	RJ85	A	72,30	73,80	82,30
21-04-2008	B735	A	73,70	78,20	85,50
21-04-2008	A319	A	73,30	75,40	85,40
21-04-2008	B734	A	72,80	76,20	84,50
21-04-2008	B462	A	70,30	71,80	80,80
21-04-2008	F70	A	68,70	70,00	79,40
21-04-2008	B738	A	73,60	76,80	85,60
21-04-2008	E190	A	72,00	74,30	83,80
21-04-2008	CRJ2	A	70,50	72,70	81,60
21-04-2008	CRJ2	A	69,90	71,40	80,30
21-04-2008	F100	A	71,60	74,10	83,10
21-04-2008	B763	A	75,50	79,40	89,10
21-04-2008	B735	A	73,10	76,40	84,90
21-04-2008	B737	A	72,50	74,80	84,30
21-04-2008	E170	A	71,00	73,30	82,50
21-04-2008	B735	A	73,60	78,90	85,70
21-04-2008	B735	A	73,00	76,90	85,60
21-04-2008	RJ1H	A	72,00	73,80	83,10
21-04-2008	A320	A	72,70	75,70	85,00
21-04-2008	B735	A	72,90	75,90	85,00
21-04-2008	AT72	A	73,80	77,80	90,80
21-04-2008	AT45	A	71,60	73,60	83,10
21-04-2008	E170	A	71,10	73,60	82,20
21-04-2008	E170	A	71,30	73,60	83,10
21-04-2008	T154	A	75,90	79,90	88,70
21-04-2008	B735	A	72,30	74,50	84,30
21-04-2008	E170	A	72,00	74,60	83,50
21-04-2008	B733	A	73,30	76,90	84,70
21-04-2008	AT72	A	72,40	74,70	84,70
21-04-2008	E170	A	71,50	73,60	82,20
21-04-2008	C295	A	72,00	74,30	82,80
21-04-2008	B735	A	73,50	77,40	85,00
21-04-2008	AT72	A	70,90	73,30	81,70

21-04-2008	E170	A	70,30	72,90	81,80
21-04-2008	E170	A	71,10	72,40	82,50
21-04-2008	E170	A	71,50	74,10	83,60
21-04-2008	A321	A	73,60	76,30	85,10
21-04-2008	B733	A	73,60	77,30	85,60
21-04-2008	A320	A	71,60	73,30	82,40
21-04-2008	E170	A	71,70	73,90	82,50
21-04-2008	B763	A	74,80	77,60	87,10
21-04-2008	AT72	A	71,40	73,10	82,90
21-04-2008	A319	A	71,60	74,20	84,20
21-04-2008	E170	A	70,80	74,00	82,30
21-04-2008	AT72	A	73,20	76,00	85,80
21-04-2008	B734	A	72,80	77,40	84,60
21-04-2008	E170	A	71,20	72,70	82,00
21-04-2008	B738	A	72,90	75,30	83,40
21-04-2008	E170	A	70,20	71,70	81,00
21-04-2008	E170	A	71,20	74,30	83,50
21-04-2008	E170	A	70,10	71,50	81,60
21-04-2008	AT72	A	74,00	76,80	85,70
21-04-2008	AT72	A	72,60	75,90	85,40
21-04-2008	E170	A	71,70	75,10	83,40
21-04-2008	AT72	A	74,30	77,10	86,10
21-04-2008	B733	A	71,30	74,20	82,70
21-04-2008	A320	A	72,50	76,30	84,80
21-04-2008	AT72	A	75,50	78,40	87,50
21-04-2008	F100	A	73,00	75,90	84,70
21-04-2008	B763	A	74,20	78,00	88,20
21-04-2008	T154	A	75,30	79,50	88,40
21-04-2008	A319	A	73,60	76,00	85,10
21-04-2008	B735	A	72,70	75,00	84,10
21-04-2008	CRJ2	A	69,60	71,90	80,70
21-04-2008	B762	A	74,60	78,70	87,60
21-04-2008	AT45	A	72,30	74,50	83,10
21-04-2008	E170	A	71,30	73,60	82,10
21-04-2008	A320	A	71,80	73,70	82,20
21-04-2008	B734	A	73,10	77,20	84,90
21-04-2008	DH8D	A	72,40	76,30	85,20
21-04-2008	AN30	A	74,20	78,60	85,30
21-04-2008	B735	A	73,80	77,40	85,60
21-04-2008	MD82	A	70,80	74,60	84,20
21-04-2008	B735	A	74,70	78,80	85,90
21-04-2008	E170	A	70,70	72,80	81,80
21-04-2008	AT72	A	72,60	74,60	84,90
21-04-2008	AT45	A	72,90	75,00	83,30
21-04-2008	E170	A	71,00	73,10	81,40
21-04-2008	B735	D	69,00	71,10	81,80
21-04-2008	E170	D	69,80	71,60	81,60
21-04-2008	B762	D	72,40	75,90	85,40
21-04-2008	B733	D	70,60	73,60	83,20
21-04-2008	B733	D	71,10	74,80	84,10
21-04-2008	A320	D	70,10	71,60	81,90
21-04-2008	YK40	D	70,50	72,20	81,90
22-04-2008	B733	D	70,50	73,60	83,90
22-04-2008	MD11	D	75,20	82,30	91,80
22-04-2008	E190	D	65,80	68,30	76,30
22-04-2008	B737	D	65,30	67,10	75,30

22-04-2008	B735	D	69,70	74,20	82,90
22-04-2008	B735	D	69,90	72,90	81,40
22-04-2008	B738	D	70,20	73,20	82,80
22-04-2008	B737	D	67,50	69,40	77,90
22-04-2008	B735	D	69,20	71,60	81,80
22-04-2008	E170	D	67,20	70,10	77,60
22-04-2008	E170	D	69,40	72,30	81,50
22-04-2008	T154	D	73,80	78,30	90,20
22-04-2008	B735	D	68,30	71,40	80,60
22-04-2008	B734	D	71,70	74,60	84,00
22-04-2008	E170	D	68,00	72,30	82,40
22-04-2008	B737	D	68,50	71,30	80,50
22-04-2008	A320	D	71,50	74,60	84,60
22-04-2008	A320	D	71,20	75,30	84,60
22-04-2008	B763	D	73,50	77,90	87,70
22-04-2008	E170	D	66,80	69,70	79,60
22-04-2008	B738	D	73,10	77,40	84,80
22-04-2008	E170	D	69,60	73,00	82,40
22-04-2008	B735	D	70,50	72,80	81,70
22-04-2008	B735	D	68,60	72,60	82,50
22-04-2008	YK40	D	71,40	75,60	85,60
22-04-2008	B734	D	70,70	74,10	85,10
22-04-2008	E170	D	69,10	71,40	82,30
22-04-2008	B733	D	70,20	72,70	82,50
22-04-2008	E170	D	69,20	71,00	80,40
22-04-2008	B733	D	71,70	75,00	84,50
23-04-2008	A320	D	67,60	69,00	78,00
23-04-2008	B735	A	71,10	73,70	82,90
23-04-2008	E170	A	70,50	72,50	81,70
23-04-2008	E170	A	71,10	74,10	82,30
23-04-2008	E170	A	70,40	72,80	81,60
23-04-2008	AT72	A	70,10	72,20	81,90
23-04-2008	E170	A	70,30	72,60	81,40
23-04-2008	E145	A	68,60	70,30	79,00
23-04-2008	AT72	A	72,00	75,20	83,80
23-04-2008	B752	A	72,80	74,60	84,80
23-04-2008	A320	A	73,00	76,20	85,70
23-04-2008	AT45	A	69,40	70,50	79,40
23-04-2008	A320	A	74,50	78,20	86,90
23-04-2008	AT43	A	70,40	72,60	80,90
23-04-2008	AT72	A	67,50	69,70	77,50
23-04-2008	B463	A	70,60	72,20	81,40
23-04-2008	RJ85	A	75,20	79,40	87,60
23-04-2008	B735	A	74,50	77,40	86,30
23-04-2008	B462	A	72,20	73,70	82,60
23-04-2008	E170	A	70,10	72,70	82,70
23-04-2008	B736	A	72,30	75,40	84,40
23-04-2008	B738	A	72,60	78,20	89,20
23-04-2008	E190	A	73,70	77,60	86,50
23-04-2008	B763	A	75,10	77,90	87,70
23-04-2008	B752	A	72,00	75,20	85,00
23-04-2008	T154	A	74,40	77,40	87,00
23-04-2008	F100	A	69,80	71,30	80,90
23-04-2008	E170	A	70,90	73,60	82,00
23-04-2008	A320	A	70,10	71,30	80,90
23-04-2008	B735	A	74,90	79,70	86,40

23-04-2008	DH8D	A	70,30	72,30	81,40
23-04-2008	B735	A	71,40	74,80	84,00
23-04-2008	RJ85	A	70,40	73,60	82,20
23-04-2008	B737	A	72,10	74,80	83,90
23-04-2008	E170	A	70,70	73,20	83,00
23-04-2008	E170	A	71,20	74,10	83,00
23-04-2008	E145	A	69,60	72,20	84,00
23-04-2008	AT72	A	71,50	74,10	83,20
23-04-2008	AT45	A	70,50	73,40	81,60
23-04-2008	T154	A	74,80	79,30	87,50
23-04-2008	B735	A	73,50	76,50	85,80
23-04-2008	E170	A	71,70	74,00	82,90
23-04-2008	AT72	A	72,10	76,50	83,60
23-04-2008	E145	A	67,60	69,50	77,60
23-04-2008	AT72	A	72,30	75,00	84,60
23-04-2008	B735	A	72,10	74,40	83,60
23-04-2008	B733	A	72,40	75,60	83,50
23-04-2008	B733	A	72,40	75,50	83,20
23-04-2008	A320	A	78,80	82,20	90,30
23-04-2008	A321	A	73,40	77,40	85,20
23-04-2008	B735	A	72,90	78,30	84,00
23-04-2008	B733	A	72,60	78,90	84,60
23-04-2008	A319	A	71,50	74,10	83,80
23-04-2008	E170	A	70,40	73,50	82,50
23-04-2008	E170	A	71,20	73,90	82,30
23-04-2008	B735	A	73,30	79,10	85,40
23-04-2008	AT72	A	72,40	74,40	83,50
23-04-2008	B734	A	74,00	76,70	84,50
23-04-2008	AT45	A	69,90	72,20	81,60
23-04-2008	MD82	A	72,10	75,40	84,90
23-04-2008	E170	A	70,20	72,20	81,60
23-04-2008	RJ85	A	69,50	70,70	79,90
23-04-2008	E170	A	74,10	78,80	86,40
23-04-2008	A320	A	72,40	75,80	85,60
23-04-2008	E170	A	70,60	72,70	81,00
23-04-2008	E190	A	73,30	75,80	84,40
23-04-2008	AT72	A	69,70	72,90	81,70
23-04-2008	B738	A	72,70	76,20	85,70
23-04-2008	B733	A	73,70	78,70	85,50
23-04-2008	B763	A	73,90	78,40	88,10
23-04-2008	A320	A	71,60	74,00	83,10
23-04-2008	B735	A	70,10	72,80	82,70
23-04-2008	A320	A	72,50	76,20	85,50
23-04-2008	AT72	A	71,90	73,90	83,70
23-04-2008	A319	A	71,70	74,50	83,20
23-04-2008	A319	A	71,20	73,20	83,00
23-04-2008	F100	A	69,90	71,10	80,40
23-04-2008	E170	A	69,50	71,70	80,30
23-04-2008	B734	A	72,90	74,70	84,10
23-04-2008	E170	A	69,80	71,80	80,60
23-04-2008	B738	A	71,80	74,30	84,10
23-04-2008	P180	A	76,30	81,30	91,80
23-04-2008	B734	A	72,00	75,30	82,80
23-04-2008	C25A	A	70,00	71,90	81,10
23-04-2008	AT45	A	69,70	71,50	80,10
23-04-2008	B735	A	73,30	77,20	85,00

23-04-2008	AT45	A	68,30	69,70	78,70
23-04-2008	B735	A	72,50	75,80	83,30
23-04-2008	A319	A	70,70	73,20	83,00
23-04-2008	AT72	A	71,70	75,30	84,50
23-04-2008	E170	A	72,00	74,30	84,10
23-04-2008	E170	A	71,00	72,70	81,70
23-04-2008	B735	A	75,00	79,40	86,40
23-04-2008	E170	A	71,20	73,60	83,20
23-04-2008	E145	A	69,00	70,30	79,40
23-04-2008	B735	A	73,90	77,10	84,70
23-04-2008	B734	A	73,50	77,10	85,30
23-04-2008	E170	A	69,50	72,30	80,30
23-04-2008	E170	A	69,20	70,50	80,30
23-04-2008	B734	A	73,20	77,50	85,50
23-04-2008	A320	A	70,40	74,60	83,40
23-04-2008	AT72	A	73,00	75,50	84,10
23-04-2008	AT72	A	71,10	73,90	83,40
23-04-2008	AT45	A	69,70	71,20	80,10
23-04-2008	AT45	A	70,50	73,10	82,00
23-04-2008	E170	A	70,50	73,40	82,00
23-04-2008	A319	A	70,40	72,60	81,20
23-04-2008	RJ85	A	70,00	73,20	82,30
23-04-2008	A320	A	73,50	75,50	85,20
23-04-2008	AT72	A	69,30	71,20	81,40
23-04-2008	B734	A	73,30	77,80	85,30
23-04-2008	E170	A	70,70	72,90	81,10
23-04-2008	A320	A	70,60	72,40	80,60
23-04-2008	YK40	A	69,50	71,60	81,00
23-04-2008	B733	A	73,70	76,00	84,50
23-04-2008	E170	A	70,80	72,40	81,60
23-04-2008	A318	A	71,80	73,70	83,20
23-04-2008	E170	A	70,30	72,80	81,10
23-04-2008	B462	A	70,70	72,80	81,50
23-04-2008	B738	A	73,50	76,10	84,90
23-04-2008	B734	A	78,20	83,60	90,30
23-04-2008	AT72	A	72,60	75,30	84,00
23-04-2008	AT72	A	70,90	73,00	82,30
23-04-2008	B733	A	74,80	78,20	86,30
23-04-2008	E170	A	69,50	72,10	81,80
23-04-2008	B735	A	71,30	73,60	82,50
23-04-2008	F70	A	70,30	72,60	80,30
23-04-2008	E170	A	70,10	72,50	81,30
23-04-2008	B735	A	72,50	74,70	84,00
23-04-2008	E170	A	69,00	70,60	80,10
23-04-2008	AT72	A	70,80	74,80	82,80
23-04-2008	B733	A	74,00	77,60	85,50
23-04-2008	F100	A	70,00	71,50	80,80
23-04-2008	AT72	A	71,00	73,40	82,80
23-04-2008	MD11	A	78,30	83,80	92,90
23-04-2008	E145	A	69,30	70,90	79,30
23-04-2008	CRJ2	A	69,70	70,90	80,20
23-04-2008	L410	A	69,70	71,50	81,20
23-04-2008	B738	A	72,40	74,90	84,70
23-04-2008	B733	A	72,70	75,80	83,80
23-04-2008	AT45	A	71,30	73,00	82,10
23-04-2008	B462	A	69,40	70,90	79,40

23-04-2008	B734	A	73,90	77,80	85,60
23-04-2008	E170	A	69,90	71,40	80,70
23-04-2008	B735	A	71,00	73,20	82,80
23-04-2008	A320	A	72,90	77,20	84,30
23-04-2008	B735	A	71,80	73,80	83,80
23-04-2008	B734	A	73,30	76,70	84,80
23-04-2008	E170	A	71,10	73,40	82,20
23-04-2008	B737	A	70,60	75,70	85,90
23-04-2008	E170	A	70,60	72,60	81,40
23-04-2008	B735	A	73,20	77,00	85,00
23-04-2008	B734	A	73,30	75,80	84,70
23-04-2008	AT45	A	70,60	72,90	82,10
23-04-2008	AT72	A	70,50	72,30	80,90
23-04-2008	E170	A	70,00	72,20	81,10
23-04-2008	E170	A	70,40	72,20	81,50
23-04-2008	E170	A	71,00	73,30	82,50
23-04-2008	B735	A	72,20	74,40	83,60
23-04-2008	E170	A	71,50	73,60	82,60
23-04-2008	E170	A	71,30	73,90	83,10
23-04-2008	AT72	A	71,70	73,50	82,80
23-04-2008	AT72	A	71,90	74,80	84,50
23-04-2008	E170	A	70,80	72,70	81,90
23-04-2008	AT72	A	71,50	75,40	84,90
24-04-2008	B738	A	72,70	75,60	84,10
24-04-2008	E170	A	69,70	71,20	80,10
24-04-2008	E170	A	70,20	72,00	81,00
24-04-2008	AT72	A	73,70	75,80	84,50
24-04-2008	A320	A	71,40	73,00	82,50
24-04-2008	E170	A	71,70	74,00	83,20
24-04-2008	B752	A	72,20	74,40	84,00
24-04-2008	AT72	A	70,60	72,80	82,00
24-04-2008	E170	A	70,50	72,80	81,60
24-04-2008	AT72	A	71,00	73,20	82,50
24-04-2008	E170	A	71,20	73,30	82,30
24-04-2008	AT45	A	71,00	72,90	81,40
24-04-2008	AT43	A	72,20	74,20	82,60
24-04-2008	A320	A	72,40	74,50	83,60
24-04-2008	AT72	A	70,60	73,00	82,90
24-04-2008	C56X	A	70,10	71,60	80,10
24-04-2008	RJ85	A	71,70	73,40	81,70
24-04-2008	A319	A	71,00	73,20	82,20
24-04-2008	E190	A	72,10	74,80	84,20
24-04-2008	B738	A	73,00	75,80	84,80
24-04-2008	AT72	A	70,40	72,60	82,70
24-04-2008	A320	A	72,10	75,20	84,20
24-04-2008	A320	A	73,80	77,50	86,50
24-04-2008	BE20	A	71,10	74,60	82,50
24-04-2008	B763	A	74,00	77,50	87,50
24-04-2008	B737	A	72,00	74,60	84,80
24-04-2008	DH8D	A	71,60	74,10	83,90
24-04-2008	B735	A	73,20	77,60	84,30
24-04-2008	B762	A	74,90	79,00	87,20
24-04-2008	B763	A	75,30	80,20	88,30
24-04-2008	E170	A	71,00	73,00	81,80
24-04-2008	RJ85	A	68,60	69,50	78,60
24-04-2008	B735	A	71,90	73,50	82,70

24-04-2008	A319	A	71,70	73,40	82,50
24-04-2008	AT72	A	70,40	74,20	82,50
24-04-2008	T154	A	74,90	78,40	87,00
24-04-2008	B735	A	72,60	74,70	83,80
24-04-2008	E170	A	70,10	71,50	80,50
24-04-2008	E170	A	71,60	74,20	83,30
24-04-2008	B735	A	72,70	75,30	84,20
24-04-2008	E170	A	69,90	72,80	80,60
24-04-2008	AT72	A	73,20	76,50	85,20
24-04-2008	AT72	A	72,70	75,20	84,70
24-04-2008	AT45	A	70,80	73,70	83,10
24-04-2008	B733	A	73,90	77,50	85,10
24-04-2008	B735	A	71,30	72,80	81,70
24-04-2008	B735	A	72,40	74,50	83,60
24-04-2008	B738	A	72,10	74,80	83,30
24-04-2008	B763	A	73,50	76,50	86,10
24-04-2008	AT72	A	69,40	71,50	79,80
24-04-2008	A320	A	72,40	75,00	83,20
24-04-2008	B733	A	71,90	75,30	83,40
24-04-2008	A320	A	71,20	73,00	82,60
24-04-2008	PC12	A	70,60	73,90	82,10
24-04-2008	E170	A	70,50	73,30	82,00
24-04-2008	B738	A	74,20	76,90	85,70
24-04-2008	AT72	A	72,70	75,60	84,20
24-04-2008	AT72	A	72,40	74,60	83,60
24-04-2008	E170	A	71,90	73,90	82,30
24-04-2008	AT45	A	71,10	73,20	81,50
24-04-2008	A319	A	71,90	74,40	83,00
24-04-2008	B734	A	73,20	78,20	85,50
24-04-2008	E170	A	70,20	72,60	81,30
24-04-2008	A320	A	69,80	71,70	80,60
24-04-2008	E170	A	70,30	71,90	80,70
24-04-2008	MD82	A	71,90	74,20	83,40
24-04-2008	E190	A	71,70	73,70	82,90
24-04-2008	A320	A	75,20	79,30	87,70
24-04-2008	A319	A	70,90	73,90	82,70
24-04-2008	AT45	A	70,70	73,80	81,10
24-04-2008	E170	A	70,30	72,80	81,80
24-04-2008	B735	A	72,10	74,00	82,50
24-04-2008	B735	A	72,00	75,00	83,40
24-04-2008	AT45	A	69,90	71,70	80,60
24-04-2008	E170	A	70,40	72,10	81,10
24-04-2008	AT45	A	71,20	73,10	81,60
24-04-2008	YK40	A	70,70	72,70	81,80
24-04-2008	E170	A	70,80	73,10	82,30
24-04-2008	AN30	A	72,00	75,00	82,00
24-04-2008	B735	A	71,80	74,20	82,20
24-04-2008	B735	A	73,60	78,30	84,40
24-04-2008	A319	A	70,80	73,00	82,30
24-04-2008	P180	A	73,40	76,90	86,60
24-04-2008	B735	A	73,20	77,10	84,00
24-04-2008	AT72	A	72,60	74,90	83,30
24-04-2008	E170	A	70,50	73,10	82,20
24-04-2008	E170	A	70,80	73,00	81,90
24-04-2008	A320	A	72,20	74,30	83,60
24-04-2008	E170	A	69,80	72,20	80,20

24-04-2008	B733	A	73,60	75,90	84,00
24-04-2008	B734	A	75,30	78,90	86,80
24-04-2008	B762	A	75,00	77,80	87,00
24-04-2008	AT72	A	70,10	73,20	82,60
24-04-2008	E170	A	70,20	72,00	80,60
24-04-2008	E170	A	70,20	72,00	81,00
24-04-2008	B734	A	73,50	76,60	84,60
24-04-2008	E170	A	70,10	72,00	81,20
24-04-2008	B733	A	73,40	77,00	84,20
24-04-2008	A319	A	72,90	74,90	84,70
24-04-2008	E170	A	70,10	71,80	80,90
24-04-2008	AT72	A	71,60	74,30	82,00
24-04-2008	A320	A	72,00	74,00	82,40
24-04-2008	A319	A	72,20	76,30	83,40
24-04-2008	A320	A	69,70	70,70	80,10
24-04-2008	B735	A	71,00	75,70	83,80
24-04-2008	B733	A	71,50	73,70	82,30
24-04-2008	A320	A	72,10	74,70	83,60
24-04-2008	RJ1H	A	70,90	72,70	81,30
24-04-2008	A320	A	71,00	73,10	82,10
24-04-2008	A320	A	72,20	75,40	83,40
24-04-2008	E170	A	73,20	75,90	84,70
24-04-2008	B733	A	72,20	74,60	82,60
24-04-2008	B734	A	71,40	73,60	82,80
24-04-2008	A318	A	70,80	73,00	82,30
24-04-2008	A320	A	71,90	74,10	83,40
24-04-2008	MD11	A	76,40	81,40	90,40
24-04-2008	AT72	A	72,00	73,90	82,40
24-04-2008	E170	A	70,30	72,50	80,70
24-04-2008	B735	A	71,80	73,80	82,90
24-04-2008	E170	A	69,80	72,00	80,60
24-04-2008	A319	A	71,30	73,40	82,10
24-04-2008	E170	A	68,30	69,90	78,70
24-04-2008	DH8D	A	69,90	71,80	79,90
24-04-2008	E170	A	70,80	73,40	81,60
24-04-2008	AT72	A	69,80	71,70	80,20
24-04-2008	B736	A	71,60	74,90	83,70
24-04-2008	B733	A	73,70	76,80	84,10
24-04-2008	AT72	A	70,70	72,60	81,10
24-04-2008	CRJ2	A	68,70	71,80	81,00
24-04-2008	B738	A	71,70	75,00	84,00
24-04-2008	E170	A	70,60	72,30	81,40
24-04-2008	E170	A	70,70	72,80	81,50
24-04-2008	AT45	A	70,30	71,90	80,70
24-04-2008	B462	A	68,80	70,00	79,30
24-04-2008	B735	A	69,10	76,30	81,70
24-04-2008	B735	A	71,00	72,20	81,80
24-04-2008	A320	A	72,30	74,90	83,50
24-04-2008	B737	A	71,60	73,80	82,40
24-04-2008	E170	A	74,80	78,00	87,10
24-04-2008	B734	A	74,20	77,90	85,90
24-04-2008	B763	A	73,20	75,30	85,50
24-04-2008	E170	A	69,60	71,50	80,40
24-04-2008	E170	A	70,10	73,00	81,90
24-04-2008	E170	A	69,70	71,40	80,50



24-04-2008	E170	A	69,90	71,40	80,30
24-04-2008	B734	A	73,30	76,50	84,50
24-04-2008	B735	A	72,90	77,40	84,60
24-04-2008	E170	A	71,30	73,50	82,40
24-04-2008	AT72	A	70,70	72,50	81,10
24-04-2008	AT72	A	71,40	73,70	82,80
24-04-2008	E170	A	70,20	71,90	81,00
24-04-2008	AT72	A	72,50	75,00	83,60
24-04-2008	E170	A	70,30	72,40	81,10
24-04-2008	B735	A	73,60	77,30	84,80
24-04-2008	B734	A	73,00	76,00	84,50
24-04-2008	GLF4	A	69,00	70,70	79,80
24-04-2008	AT72	A	70,40	72,20	82,40
25-04-2008	B735	A	73,40	78,60	84,20
25-04-2008	B733	A	72,80	74,70	84,00
25-04-2008	E170	A	70,70	73,20	81,80
25-04-2008	AT72	A	72,30	74,70	83,10
25-04-2008	AT72	A	70,30	71,90	81,10
25-04-2008	E170	A	70,40	72,40	81,50
25-04-2008	AT72	A	71,40	73,20	82,10
25-04-2008	E170	A	70,40	73,00	81,60
25-04-2008	E170	A	70,20	71,90	80,60
25-04-2008	E170	A	69,20	70,30	79,20
25-04-2008	B752	A	68,90	70,20	78,90
25-04-2008	AT72	A	74,00	76,40	85,80
25-04-2008	B462	A	72,60	74,70	83,30
25-04-2008	AT45	A	69,80	71,10	80,30
25-04-2008	AT43	A	71,80	74,00	84,10
25-04-2008	A320	A	70,80	72,80	82,00
25-04-2008	AT72	A	71,10	73,10	81,90
25-04-2008	B734	A	73,80	78,20	84,90
25-04-2008	RJ85	A	70,70	72,50	81,10
25-04-2008	B734	A	72,80	75,60	83,90
25-04-2008	A320	A	72,90	75,10	84,60
25-04-2008	AT72	A	72,70	75,70	85,50
25-04-2008	B462	A	67,70	68,50	77,70
25-04-2008	E190	A	75,30	78,70	86,10
25-04-2008	CRJ2	A	70,40	72,90	82,40
25-04-2008	B738	A	72,70	75,90	84,20
25-04-2008	F100	A	70,40	72,20	81,20
25-04-2008	DH8D	A	71,20	73,10	82,00
25-04-2008	B733	A	73,30	76,30	84,00
25-04-2008	E170	A	70,70	72,80	81,80
25-04-2008	B737	A	73,20	75,30	83,60
25-04-2008	E170	A	71,00	73,60	83,30
25-04-2008	E170	A	69,00	71,20	79,80
25-04-2008	A320	A	69,10	71,50	81,40
25-04-2008	B752	A	72,60	74,90	83,70
25-04-2008	B763	A	73,50	76,60	86,70
25-04-2008	E170	A	70,30	71,90	80,70
25-04-2008	AT72	A	73,00	76,50	84,70
25-04-2008	E170	A	69,90	72,10	81,00
25-04-2008	B738	A	73,80	76,70	85,30
25-04-2008	T154	A	73,00	76,10	85,60
25-04-2008	B734	A	75,10	79,70	87,10
25-04-2008	B735	A	73,50	77,70	84,90

25-04-2008	AT45	A	70,80	73,50	82,30
25-04-2008	E170	A	70,60	72,50	81,70
25-04-2008	B735	A	73,60	76,70	85,00
25-04-2008	B733	A	72,30	74,50	83,70
25-04-2008	YK40	A	71,70	74,70	83,50
25-04-2008	AT72	A	72,80	74,80	82,80
25-04-2008	T154	A	74,10	76,70	85,90
25-04-2008	AT72	A	73,50	76,40	85,00
25-04-2008	B733	A	70,30	72,40	81,50
25-04-2008	E170	A	70,30	71,70	80,70
25-04-2008	A320	A	72,80	77,80	87,70
25-04-2008	B735	A	72,40	75,60	82,80
25-04-2008	A320	A	72,40	75,00	83,20
25-04-2008	E170	A	71,40	74,40	82,50
25-04-2008	A320	A	71,70	74,40	83,20
25-04-2008	B733	A	72,40	75,10	83,60
25-04-2008	A319	A	72,30	75,20	83,50
25-04-2008	AT72	A	72,90	75,90	83,40
25-04-2008	E170	A	70,90	73,60	81,40
25-04-2008	AT45	A	69,00	71,00	79,00
25-04-2008	E170	A	69,70	71,40	80,10
25-04-2008	B738	A	72,40	75,80	84,70
25-04-2008	MD82	A	72,10	75,40	83,80
25-04-2008	AT72	A	73,50	76,80	84,30
25-04-2008	E170	A	71,60	74,60	84,40
25-04-2008	C295	A	71,40	73,10	81,40
25-04-2008	B735	A	72,40	74,20	82,80
25-04-2008	E190	A	68,30	69,80	79,70
25-04-2008	A320	A	72,30	75,40	83,70
25-04-2008	AT45	A	70,70	72,80	80,70
25-04-2008	B763	A	73,80	77,30	86,90
25-04-2008	A320	A	69,90	72,10	81,90
25-04-2008	B733	A	72,60	76,00	83,70
25-04-2008	A319	A	71,70	74,00	82,10
25-04-2008	A319	A	71,30	72,90	82,80
25-04-2008	AT72	A	71,00	73,80	83,30
25-04-2008	E170	A	73,20	76,50	84,90
25-04-2008	E170	A	70,50	73,20	82,20
25-04-2008	A320	A	71,40	74,40	83,70
25-04-2008	B735	A	70,00	71,40	81,10
25-04-2008	B735	A	73,80	76,50	84,60
25-04-2008	B735	A	73,30	75,20	83,70
25-04-2008	B733	A	70,40	73,00	82,20
25-04-2008	B735	A	73,50	76,20	83,50
25-04-2008	B752	A	72,20	74,20	84,20
25-04-2008	E170	A	69,70	71,40	80,10
25-04-2008	A319	A	72,00	75,60	82,40
25-04-2008	AT72	A	73,60	76,90	84,40
25-04-2008	E170	A	70,70	71,70	81,10
25-04-2008	B734	A	71,10	73,60	82,30
25-04-2008	E170	A	70,40	71,60	80,80
25-04-2008	E170	A	70,70	72,70	81,80
25-04-2008	B734	A	72,70	76,50	83,90
25-04-2008	PC12	A	72,60	75,50	83,80
25-04-2008	A320	A	76,00	80,50	88,80
25-04-2008	B735	A	72,30	74,50	82,70

25-04-2008	E170	A	69,50	70,80	79,90
25-04-2008	AT72	A	73,60	76,90	85,40
25-04-2008	A320	A	73,10	76,20	84,80
25-04-2008	B735	A	73,20	75,80	84,00
25-04-2008	E170	A	71,70	74,10	82,90
25-04-2008	E170	A	69,40	71,50	80,20
25-04-2008	A319	A	70,60	72,20	81,00
25-04-2008	B733	A	73,30	76,40	84,40
25-04-2008	AT45	A	70,10	72,00	80,50
25-04-2008	AT45	A	71,20	73,30	81,20
25-04-2008	F2TH	A	68,40	70,20	78,40
25-04-2008	A319	A	70,80	73,10	82,00
25-04-2008	B733	A	74,10	78,20	84,90
25-04-2008	A320	A	70,50	72,60	81,70
25-04-2008	A320	A	70,80	72,90	82,30
25-04-2008	E170	A	72,10	75,40	83,60
25-04-2008	B735	A	72,10	73,90	82,50
25-04-2008	A318	A	70,60	72,70	81,00
25-04-2008	B733	A	72,90	75,30	83,70
25-04-2008	A319	A	74,10	77,80	85,60
25-04-2008	A320	A	70,60	72,00	81,40
25-04-2008	AT72	A	71,20	72,90	82,30
25-04-2008	E170	A	72,80	76,50	83,20
25-04-2008	E170	A	71,90	73,70	82,40
25-04-2008	E170	A	70,80	72,40	81,20
25-04-2008	B733	A	70,90	72,90	81,70
25-04-2008	E170	A	69,40	70,80	79,80
25-04-2008	MD11	A	76,40	81,10	90,00
25-04-2008	F100	A	70,50	72,20	80,50
25-04-2008	B733	A	72,50	75,10	83,30
25-04-2008	B733	A	71,60	74,90	82,00
25-04-2008	B737	A	80,70	84,30	98,50
25-04-2008	B462	A	70,20	71,70	80,60
25-04-2008	B738	A	73,50	75,70	84,30
25-04-2008	AN26	A	73,00	76,10	83,40
25-04-2008	AT72	A	71,30	73,50	83,10
25-04-2008	B738	A	73,10	75,80	84,60
25-04-2008	AN28	A	76,70	80,70	94,50
25-04-2008	AT72	A	75,30	80,00	93,10
25-04-2008	E170	A	73,50	77,00	91,30
25-04-2008	E170	A	69,80	71,30	79,80
25-04-2008	B737	A	71,60	74,00	83,10
25-04-2008	A320	A	72,10	74,50	83,20
25-04-2008	B735	A	72,40	75,60	83,20
25-04-2008	E170	A	70,60	72,90	81,70
25-04-2008	B735	A	71,60	73,30	82,40
25-04-2008	B734	A	71,60	73,50	82,40
25-04-2008	E170	A	69,50	71,70	80,30
25-04-2008	AT72	A	71,80	74,50	83,30
25-04-2008	E145	A	68,20	70,30	79,70
25-04-2008	E170	A	68,80	72,10	81,80
25-04-2008	AT72	A	70,30	71,60	81,50
25-04-2008	E170	A	71,10	72,70	81,90
25-04-2008	E170	A	70,30	73,20	83,10
25-04-2008	B735	A	72,90	75,80	83,30
25-04-2008	B734	A	72,90	75,50	83,30

25-04-2008	AT45	A	69,40	72,10	81,50
25-04-2008	B734	A	73,70	76,60	84,10
25-04-2008	B734	A	70,50	72,40	80,90
25-04-2008	B738	A	72,60	75,20	83,80
26-04-2008	B752	A	72,20	74,50	84,30
26-04-2008	E170	A	70,50	72,50	81,20
26-04-2008	AT72	A	72,10	74,60	82,90
26-04-2008	E170	A	70,90	72,60	82,10
26-04-2008	E170	A	71,20	73,70	82,00
26-04-2008	AT72	A	74,20	76,60	86,80
26-04-2008	E170	A	70,20	72,60	80,60
26-04-2008	B734	A	69,90	71,40	81,10
26-04-2008	A320	A	72,10	74,90	84,10
26-04-2008	AT72	A	74,00	75,90	85,40
26-04-2008	RJ85	A	70,00	71,60	80,50
26-04-2008	B733	A	72,90	75,30	84,00
26-04-2008	B735	A	71,70	75,50	82,50
26-04-2008	A320	A	70,20	72,00	80,20
26-04-2008	E170	A	70,60	72,20	82,10
26-04-2008	B735	A	72,30	73,70	82,70
26-04-2008	B734	A	71,80	73,60	82,90
26-04-2008	B736	A	71,40	73,20	82,10
26-04-2008	E190	A	72,40	74,60	83,80
26-04-2008	B763	A	73,50	77,30	86,90
26-04-2008	F100	A	68,00	69,20	78,40
26-04-2008	E170	A	69,70	71,20	79,70
26-04-2008	B735	A	74,30	77,70	85,40
26-04-2008	E170	A	69,60	72,30	80,40
26-04-2008	B735	A	73,00	75,50	84,10
26-04-2008	B763	A	73,80	76,40	86,30
26-04-2008	T154	A	74,90	78,90	87,20
26-04-2008	E170	A	69,80	71,30	80,60
26-04-2008	AT72	A	72,20	75,80	85,00
26-04-2008	B762	A	73,20	76,90	85,80
26-04-2008	AT72	A	73,50	75,90	85,20
26-04-2008	B735	A	71,40	73,40	82,80
26-04-2008	AT45	A	69,90	71,70	80,70
26-04-2008	E170	A	69,80	72,40	80,90
26-04-2008	AT72	A	70,40	72,30	82,40
26-04-2008	B734	A	73,30	75,80	84,70
26-04-2008	E170	A	71,40	73,20	82,20
26-04-2008	B763	A	73,70	76,10	86,00
26-04-2008	B733	A	73,20	75,70	84,30
26-04-2008	B735	A	71,60	73,60	82,70
26-04-2008	P180	A	73,70	77,20	86,70
26-04-2008	B733	A	72,10	73,50	82,50
26-04-2008	B733	A	72,80	75,70	84,50
26-04-2008	E170	A	69,60	70,90	80,00
26-04-2008	A319	A	71,20	73,80	82,70
26-04-2008	B734	A	74,60	78,00	85,00
26-04-2008	A320	A	72,10	74,70	83,20
26-04-2008	E170	A	70,10	73,70	81,60
26-04-2008	MD82	A	71,10	72,50	82,30
26-04-2008	B733	A	70,60	72,90	81,80
26-04-2008	E170	A	71,40	73,90	82,20
26-04-2008	E170	A	69,70	72,00	81,50

26-04-2008	RJ85	A	69,50	71,30	80,30
26-04-2008	B752	A	73,70	76,80	85,50
26-04-2008	A319	A	76,20	81,30	87,60
26-04-2008	E170	A	69,30	71,40	79,70
26-04-2008	B763	A	73,50	76,00	85,80
26-04-2008	A320	A	70,60	73,10	82,10
26-04-2008	A320	A	71,90	75,90	83,10
26-04-2008	B752	A	71,70	74,40	82,90
26-04-2008	T154	A	74,60	78,00	86,60
26-04-2008	B735	A	71,40	74,50	83,10
26-04-2008	AT45	A	69,60	70,80	80,40
26-04-2008	B734	A	72,40	74,30	82,80
26-04-2008	B735	A	71,30	74,70	82,10
26-04-2008	DH8D	A	71,10	73,40	82,20
26-04-2008	E170	A	69,50	71,90	80,30
26-04-2008	B734	A	71,00	73,00	82,10
26-04-2008	AT72	A	72,20	75,00	84,50
26-04-2008	E170	A	68,60	71,50	79,40
26-04-2008	B735	A	71,80	73,50	82,60
26-04-2008	E170	A	69,90	72,20	81,00
26-04-2008	E170	A	70,20	72,30	81,40
26-04-2008	B737	A	71,00	73,20	82,20
26-04-2008	AT45	A	70,10	71,80	81,60
26-04-2008	B734	A	71,10	72,60	81,90
26-04-2008	E170	A	68,70	70,10	79,80
26-04-2008	A320	A	72,60	75,40	84,30
26-04-2008	E170	A	70,00	71,40	80,40
26-04-2008	AT72	A	71,20	73,80	83,20
26-04-2008	B735	A	71,90	73,80	83,10
26-04-2008	E145	A	69,20	71,20	79,60
26-04-2008	E170	A	73,40	76,50	84,90
26-04-2008	A319	A	70,90	72,90	81,70
26-04-2008	A320	A	72,60	75,80	85,20
26-04-2008	AT45	A	70,00	72,00	80,40
26-04-2008	AT72	A	69,80	72,40	80,60
26-04-2008	B734	A	72,70	76,20	83,90
26-04-2008	E170	A	70,60	72,20	81,40
26-04-2008	A320	A	70,50	72,20	81,70
26-04-2008	B734	A	74,10	77,70	85,30
26-04-2008	A319	A	71,50	74,00	82,30
26-04-2008	B734	A	72,70	76,60	85,00
26-04-2008	A320	A	72,90	76,00	85,70
26-04-2008	RJ1H	A	69,40	70,70	80,20
26-04-2008	YK40	A	71,20	73,40	81,20
26-04-2008	B735	A	71,00	72,70	82,20
26-04-2008	B735	A	73,10	76,40	84,30
26-04-2008	YK40	A	70,60	72,70	81,40
26-04-2008	AT72	A	70,70	72,90	82,10
26-04-2008	A319	A	71,30	73,50	82,80
26-04-2008	E170	A	70,70	73,00	82,50
26-04-2008	E170	A	69,90	71,80	81,40
26-04-2008	B734	A	71,70	73,70	83,80
26-04-2008	B735	A	72,40	74,00	83,60
26-04-2008	F100	A	72,20	75,00	84,00
26-04-2008	E170	A	70,10	72,30	81,50
26-04-2008	B738	A	72,70	75,00	85,00

26-04-2008	E170	A	72,60	74,70	84,90
26-04-2008	C25B	A	69,80	72,10	80,60
26-04-2008	B734	A	74,20	78,50	87,30
26-04-2008	E170	A	70,70	72,20	81,80
26-04-2008	B735	A	73,30	77,00	85,30
26-04-2008	E170	A	71,10	73,10	85,40
26-04-2008	AT72	A	71,60	73,90	83,70
26-04-2008	E145	A	69,80	71,20	80,20
26-04-2008	E170	A	70,60	72,20	81,30
26-04-2008	AT45	A	71,20	73,30	83,00
26-04-2008	B733	A	73,60	77,90	85,90
26-04-2008	E170	A	70,20	72,00	81,00
26-04-2008	E170	A	71,20	73,20	83,20
26-04-2008	B735	A	72,20	76,70	85,00
26-04-2008	B734	A	73,80	78,00	86,10
26-04-2008	AT72	A	68,00	69,10	78,40
26-04-2008	E145	A	68,00	69,00	78,00
27-04-2008	B735	A	71,80	73,60	82,90
27-04-2008	E170	A	70,90	73,30	82,40
27-04-2008	AT72	A	74,20	77,10	87,00
27-04-2008	AT45	A	71,80	73,60	82,60
27-04-2008	B703	A	82,90	89,10	97,20
27-04-2008	RJ85	A	73,00	75,90	84,50
27-04-2008	AT72	A	73,00	76,50	86,00
27-04-2008	CRJ2	A	69,80	72,60	81,80
27-04-2008	E190	A	71,30	73,40	81,70
27-04-2008	B762	A	74,40	77,70	87,40
27-04-2008	B734	A	75,00	79,30	88,20
27-04-2008	B738	A	73,30	75,90	85,60
27-04-2008	F100	A	68,50	69,90	80,80
27-04-2008	B734	D	71,60	74,50	84,60
27-04-2008	A320	A	73,60	76,40	85,70
27-04-2008	B763	A	73,90	78,00	88,50
27-04-2008	B738	A	73,60	77,80	86,80
27-04-2008	B735	A	73,00	77,00	85,00
27-04-2008	A320	A	69,40	71,70	81,70
27-04-2008	E170	A	71,00	73,30	83,00
27-04-2008	A319	A	71,60	74,00	83,30
27-04-2008	PA46	A	69,10	72,40	82,10
27-04-2008	AT72	A	72,50	81,20	85,00
27-04-2008	AT72	A	73,70	76,70	86,50
27-04-2008	T154	A	75,70	79,20	88,50
27-04-2008	B735	A	72,10	73,90	83,60
27-04-2008	AT72	A	72,30	74,40	83,50
27-04-2008	B733	A	72,60	75,10	83,80
27-04-2008	AT72	A	71,20	73,10	81,60
27-04-2008	E170	A	70,70	72,30	81,20
27-04-2008	B733	A	72,60	75,10	84,70
27-04-2008	A320	A	73,50	77,00	84,90
27-04-2008	B752	A	69,50	72,80	85,20
27-04-2008	E170	A	70,80	72,70	82,20
27-04-2008	A320	A	70,90	73,10	82,90
27-04-2008	B733	A	73,00	75,40	83,40
27-04-2008	A320	A	71,40	74,10	83,10
27-04-2008	A319	A	71,70	73,90	84,40
27-04-2008	B734	A	74,60	80,50	86,60

27-04-2008	E170	A	68,60	70,40	80,10
27-04-2008	P180	A	75,50	79,50	89,50
27-04-2008	A319	A	71,90	75,10	83,10
27-04-2008	AT45	A	70,30	71,90	81,80
27-04-2008	B733	A	73,50	76,70	84,70
27-04-2008	MD82	A	74,80	78,80	87,10
27-04-2008	RJ85	A	70,90	72,80	82,40
27-04-2008	E170	A	71,00	74,00	83,50
27-04-2008	E190	A	71,40	73,30	82,50
27-04-2008	B735	A	73,30	75,80	85,10
27-04-2008	B738	A	73,00	75,90	85,30
27-04-2008	E170	A	70,60	72,90	81,70
27-04-2008	AT72	A	69,70	71,60	80,90
27-04-2008	P180	D	69,10	71,80	79,50
27-04-2008	A320	A	70,50	72,50	81,60
27-04-2008	A320	A	72,50	76,20	85,10
27-04-2008	B763	A	75,20	80,50	88,40
27-04-2008	A319	A	72,30	75,10	83,70
27-04-2008	AT72	A	69,40	71,00	80,60
27-04-2008	B733	A	71,40	74,30	83,70
27-04-2008	F100	A	69,10	71,20	79,90
27-04-2008	E170	A	71,70	74,00	82,80
27-04-2008	B734	A	72,90	74,90	84,00
27-04-2008	AT45	A	70,20	71,60	81,70
27-04-2008	AT72	A	72,20	74,10	84,00
27-04-2008	B734	A	73,60	75,30	84,80
27-04-2008	E170	A	70,70	73,30	81,50
27-04-2008	E170	A	70,10	72,10	80,10
27-04-2008	AT72	A	71,10	74,20	81,90
27-04-2008	A318	A	71,50	73,40	82,70
27-04-2008	E170	A	70,00	71,60	80,40
27-04-2008	P180	A	73,10	76,60	86,60
27-04-2008	B734	A	70,00	74,50	84,40
27-04-2008	DH8D	A	68,20	69,70	78,20
27-04-2008	E170	A	71,30	73,50	82,80
27-04-2008	A320	A	71,10	73,50	82,50
27-04-2008	B734	A	71,00	74,80	84,50
27-04-2008	E170	A	71,40	73,40	83,10
27-04-2008	AT45	A	70,00	71,70	81,50
27-04-2008	E170	A	69,70	71,30	80,90
27-04-2008	B735	A	73,60	76,60	84,80
27-04-2008	AT72	A	71,10	73,40	82,30
27-04-2008	AT45	A	71,00	72,40	81,40
27-04-2008	A319	A	72,80	75,00	83,90
27-04-2008	RJ85	A	70,30	72,90	82,30
27-04-2008	MD82	A	71,20	73,40	82,30
27-04-2008	A320	A	70,00	71,40	80,00
27-04-2008	B735	A	72,00	74,20	83,10
27-04-2008	AT72	A	73,80	76,20	85,00
27-04-2008	B733	A	71,50	74,20	83,20
27-04-2008	B735	A	71,90	74,70	82,70
27-04-2008	RJ1H	A	72,10	74,40	82,10
27-04-2008	A320	A	71,50	73,00	82,30
27-04-2008	B733	A	71,60	73,70	82,40
27-04-2008	A320	A	70,70	72,50	81,90
27-04-2008	B735	A	72,10	74,90	83,50

27-04-2008	E170	A	70,20	72,20	80,60
27-04-2008	B733	A	72,10	74,10	83,20
27-04-2008	B735	A	71,50	73,40	82,70
27-04-2008	F2TH	A	69,20	71,00	80,00
27-04-2008	A320	A	72,10	74,60	84,10
27-04-2008	AT72	A	70,30	71,60	80,70
27-04-2008	B735	A	72,10	76,50	84,60
27-04-2008	E170	A	72,10	74,40	83,60
27-04-2008	AT72	A	69,80	71,20	80,60
27-04-2008	B735	A	72,60	76,10	83,70
27-04-2008	AT72	A	73,20	75,40	84,40
27-04-2008	B735	A	73,50	75,50	84,70
27-04-2008	E170	A	72,10	74,60	83,60
27-04-2008	B733	A	74,60	78,60	86,90
27-04-2008	AT72	A	71,70	77,00	85,10
27-04-2008	B738	A	71,90	74,60	83,70
27-04-2008	B735	A	71,40	73,80	83,20
27-04-2008	B738	A	73,40	75,70	84,80
27-04-2008	E170	A	70,40	71,80	80,80
27-04-2008	B737	A	72,20	74,40	83,60
27-04-2008	E170	A	69,90	71,70	80,70
27-04-2008	AT72	A	72,30	75,60	84,30
27-04-2008	E170	A	70,10	71,50	80,90
27-04-2008	B190	A	70,80	73,10	81,20
27-04-2008	B734	A	75,10	80,00	86,50
27-04-2008	B734	A	72,90	75,50	84,00
27-04-2008	A320	A	73,00	76,70	84,70
27-04-2008	E170	A	70,20	71,90	81,00
27-04-2008	E170	A	70,10	71,90	80,90
27-04-2008	E170	A	70,40	72,00	81,20
27-04-2008	E170	A	69,00	73,90	79,80
27-04-2008	AT45	A	69,50	71,10	79,50
27-04-2008	AT72	A	71,40	73,50	83,40
27-04-2008	E170	A	69,30	71,50	80,80
27-04-2008	AT72	A	72,30	74,10	83,80
27-04-2008	E170	A	71,60	74,10	83,10
27-04-2008	E170	A	70,30	72,50	81,10
27-04-2008	E170	A	70,60	72,30	81,40
27-04-2008	E170	A	70,60	72,90	81,80
27-04-2008	B735	A	72,90	76,30	84,10
27-04-2008	AT72	A	72,90	74,90	84,40
28-04-2008	AT72	A	73,20	75,60	85,00
28-04-2008	B752	A	72,40	74,70	84,20
28-04-2008	AT72	A	72,80	75,70	84,20
28-04-2008	E170	A	70,10	72,00	80,10
28-04-2008	E170	A	70,70	72,80	81,50
28-04-2008	E170	A	69,60	71,40	80,10
28-04-2008	AT72	A	70,60	72,20	81,70
28-04-2008	E170	A	70,90	72,70	82,00
28-04-2008	AT45	A	71,70	73,10	81,70
28-04-2008	AT72	A	72,10	74,40	82,90
28-04-2008	B738	A	72,30	75,00	83,80
28-04-2008	RJ85	A	70,40	71,90	81,20
28-04-2008	AT72	A	73,80	75,90	84,90
28-04-2008	F70	A	68,30	69,00	79,10
28-04-2008	B733	A	73,20	75,80	84,00



28-04-2008	B734	A	74,80	78,70	86,80
28-04-2008	B462	A	70,20	71,40	80,20
28-04-2008	E190	A	73,90	76,90	85,00
28-04-2008	A320	D	68,10	70,40	81,50
28-04-2008	B735	D	69,30	71,20	80,10
28-04-2008	B735	D	68,80	70,50	78,80
28-04-2008	T154	D	73,10	78,80	88,50
28-04-2008	AN26	D	69,90	72,80	80,70
28-04-2008	B735	D	68,70	71,70	80,70
28-04-2008	B734	D	70,50	74,00	84,20
28-04-2008	B763	D	73,90	78,60	87,40
28-04-2008	A320	D	69,70	72,40	82,00
28-04-2008	E170	D	67,50	69,60	81,70
28-04-2008	B738	D	69,40	72,50	83,00
28-04-2008	B733	D	71,20	74,20	82,00
28-04-2008	B735	D	69,90	72,70	80,70
28-04-2008	B735	D	69,30	72,80	80,80
28-04-2008	B735	D	66,60	68,20	77,40
28-04-2008	B763	D	69,30	71,60	79,70
28-04-2008	B733	D	68,70	69,70	79,50
29-04-2008	A320	D	68,80	70,20	80,50
29-04-2008	T154	D	69,30	70,20	80,40
29-04-2008	MD11	D	75,20	79,20	90,10
29-04-2008	E190	D	68,80	70,90	80,30
29-04-2008	AN26	D	74,50	78,60	89,10
29-04-2008	B735	D	69,00	71,30	80,10
29-04-2008	B738	D	70,40	73,80	82,70
29-04-2008	E170	D	66,60	68,40	76,60
29-04-2008	E170	D	67,80	69,80	78,90
29-04-2008	T154	D	74,30	80,00	90,80
29-04-2008	B735	D	69,20	71,80	81,50
29-04-2008	B733	D	72,10	74,90	85,70
29-04-2008	B738	D	71,10	73,90	83,20
29-04-2008	B733	D	71,60	75,90	84,40
29-04-2008	B763	D	74,00	78,60	87,80
29-04-2008	E170	D	70,10	74,10	84,70
29-04-2008	B763	D	75,00	79,40	88,80
29-04-2008	E170	D	69,70	72,30	81,20
29-04-2008	E190	D	66,90	68,30	78,00
29-04-2008	B733	D	69,50	70,80	80,60
29-04-2008	B735	D	71,40	74,80	84,20
29-04-2008	T154	D	70,50	73,10	81,60
29-04-2008	AN26	D	74,30	78,50	85,80
29-04-2008	B763	D	74,60	77,40	87,80
29-04-2008	B733	D	71,70	75,80	83,20
29-04-2008	B733	D	72,30	75,70	84,90
29-04-2008	E170	D	68,80	70,10	81,10
29-04-2008	B738	D	72,10	75,20	84,70
29-04-2008	P180	D	68,40	69,90	79,20
30-04-2008	A320	D	68,50	70,20	78,50
30-04-2008	B733	D	69,50	71,40	80,70
30-04-2008	MD11	D	75,60	81,70	92,00
30-04-2008	B735	D	68,30	71,10	78,70
30-04-2008	B738	D	72,30	74,50	84,70
30-04-2008	A320	D	70,50	73,10	81,90
30-04-2008	A320	D	69,30	72,50	82,70

30-04-2008	B752	D	67,40	69,70	79,20
30-04-2008	E170	D	68,60	71,10	81,60
30-04-2008	E170	D	67,90	69,70	78,70
30-04-2008	B733	D	71,70	74,90	83,70
30-04-2008	B763	D	76,70	82,10	90,20
30-04-2008	E170	D	67,90	71,70	79,60
30-04-2008	B735	D	70,80	73,30	81,90
30-04-2008	E170	D	67,90	70,10	79,10
30-04-2008	B733	D	68,90	72,00	79,60
30-04-2008	B733	D	70,70	75,20	85,00
30-04-2008	B738	D	70,40	73,80	84,50
30-04-2008	BE40	D	68,00	69,90	78,80
30-04-2008	B752	D	67,90	69,00	78,30
30-04-2008	B763	D	69,60	72,30	81,90
30-04-2008	B763	D	75,10	79,40	87,90
30-04-2008	YK40	D	70,90	74,50	85,60
30-04-2008	AN26	D	70,60	74,50	85,90
30-04-2008	E190	D	66,60	70,20	77,00
30-04-2008	B733	D	70,40	74,60	83,20
Średnia $L_{AE}$					84,16
Odchylenie stand. $\sigma$					2,66
Przedział ufności $\Delta$					0,09

Poziom równoważny dla pory dnia określony dla 6 kolejnych najmniej korzystnych (pod względem liczby zdarzeń akustycznych) miesięcy w roku 2007 (maj - październik):

$L_{Aeq}$ , LT = 57,53 dB

### Pora dnia

Data	samolot	operacja	$L_{Aeq}$	$L_{Amax}$	$L_{AE}$
01-04-2008	AN26	A	71,70	74,80	81,70
01-04-2008	E170	A	69,70	71,60	80,10
01-04-2008	B734	A	72,40	74,20	83,20
01-04-2008	B734	A	73,40	76,80	84,20
01-04-2008	A320	A	70,70	72,30	81,50
01-04-2008	AN26	A	73,70	76,70	83,70
01-04-2008	B733	A	71,40	73,30	82,20
01-04-2008	B734	A	73,30	76,20	84,10
01-04-2008	B735	A	75,30	78,90	86,70
01-04-2008	A321	A	71,60	73,80	82,40
01-04-2008	SF34	A	72,80	75,10	82,80
01-04-2008	A320	A	71,50	73,10	82,30
01-04-2008	A320	A	70,50	72,20	81,30
01-04-2008	AN26	D	74,00	78,10	85,40
01-04-2008	B733	A	73,50	76,70	84,20
02-04-2008	B735	A	72,90	76,20	83,70
02-04-2008	B733	A	72,50	74,70	83,60
02-04-2008	MD11	A	77,50	82,60	91,20
02-04-2008	E170	D	70,50	73,10	83,50
03-04-2008	E170	A	70,30	72,10	81,40
03-04-2008	B735	A	73,20	76,80	84,70
03-04-2008	MD11	A	78,20	82,80	92,20
03-04-2008	SF34	A	69,90	71,80	79,90

03-04-2008	AT72	A	71,80	74,40	84,80
03-04-2008	CRJ2	A	70,10	72,00	81,60
03-04-2008	B733	A	72,80	75,80	84,20
03-04-2008	B735	A	75,20	81,20	87,50
03-04-2008	B733	A	71,40	73,60	83,20
03-04-2008	AN26	A	74,10	78,20	85,20
03-04-2008	A320	A	71,20	73,00	82,60
03-04-2008	A320	A	71,80	73,90	84,40
03-04-2008	B735	A	71,80	73,60	83,60
03-04-2008	B734	A	72,30	75,20	84,00
03-04-2008	A320	A	71,10	72,90	83,10
03-04-2008	AT45	A	72,00	74,40	84,00
04-04-2008	MD11	A	77,10	81,30	91,40
04-04-2008	SF34	A	69,40	70,70	78,40
04-04-2008	AN26	A	73,60	77,90	85,10
04-04-2008	E170	A	71,20	73,30	83,00
04-04-2008	E170	A	70,00	72,40	82,00
04-04-2008	E170	A	70,90	73,30	82,70
04-04-2008	AN26	A	75,00	80,10	86,10
04-04-2008	B733	A	73,70	76,00	85,20
04-04-2008	A320	A	71,70	75,20	84,70
04-04-2008	B734	A	72,90	76,60	86,30
04-04-2008	B733	A	71,90	76,00	84,90
04-04-2008	B735	A	73,60	77,40	85,90
04-04-2008	YK40	A	72,30	75,30	83,70
04-04-2008	AT72	A	75,20	77,80	87,00
04-04-2008	B733	A	73,00	76,80	84,70
04-04-2008	A320	A	70,90	73,60	83,50
04-04-2008	A320	A	72,20	74,20	83,70
05-04-2008	T154	A	76,00	80,40	89,80
05-04-2008	A320	A	72,50	75,80	85,70
05-04-2008	B752	A	71,50	74,00	84,30
05-04-2008	E170	A	71,50	73,80	83,20
05-04-2008	B735	A	73,60	78,50	85,10
05-04-2008	SF34	A	69,20	70,80	79,20
05-04-2008	B734	D	69,90	72,70	83,30
05-04-2008	B734	A	73,90	77,30	85,10
05-04-2008	B735	A	73,80	76,70	85,60
05-04-2008	A320	A	72,10	74,30	84,20
05-04-2008	A320	A	73,70	76,90	86,20
05-04-2008	B734	D	71,80	75,80	85,60
06-04-2008	AT43	A	71,80	74,40	84,10
06-04-2008	E170	A	70,60	72,50	81,70
06-04-2008	B733	A	73,50	75,60	85,20
06-04-2008	E170	D	71,00	74,70	85,30
08-04-2008	B462	A	69,20	70,90	79,70
08-04-2008	MD11	A	78,90	83,00	92,10
08-04-2008	SF34	A	68,90	69,80	77,40
08-04-2008	B734	A	73,30	77,80	85,10
08-04-2008	AN26	A	74,50	78,30	85,30
08-04-2008	A320	A	71,10	73,40	82,50
08-04-2008	B733	A	73,60	76,90	85,10
08-04-2008	B733	A	73,20	76,20	84,70
08-04-2008	A320	A	68,80	70,20	79,30
08-04-2008	B735	A	72,20	74,40	83,90
08-04-2008	A320	A	70,60	72,80	82,00

08-04-2008	AN26	D	79,80	84,50	91,30
09-04-2008	T154	A	75,50	80,60	89,80
09-04-2008	B733	A	72,80	76,40	83,90
09-04-2008	MD11	A	77,00	81,30	90,80
09-04-2008	SF34	A	68,40	69,20	78,00
09-04-2008	B735	A	73,30	76,60	84,80
09-04-2008	E170	D	69,90	72,10	82,50
09-04-2008	E170	D	69,60	71,60	81,00
10-04-2008	SF34	A	70,10	72,00	80,50
10-04-2008	AT72	A	74,00	77,30	88,20
10-04-2008	E170	A	70,10	72,30	82,10
10-04-2008	AN26	A	74,10	77,90	84,80
10-04-2008	B733	A	72,40	74,50	84,20
10-04-2008	AT72	A	71,80	74,20	83,60
10-04-2008	A320	A	70,70	72,30	82,50
10-04-2008	B734	A	73,30	77,10	85,60
10-04-2008	A320	A	72,50	74,60	84,20
10-04-2008	AT72	A	75,20	78,30	87,80
10-04-2008	B733	A	74,10	77,60	85,90
10-04-2008	E145	A	69,10	70,80	79,10
10-04-2008	B735	A	71,90	74,00	83,60
10-04-2008	A320	A	72,80	75,90	85,60
10-04-2008	P180	A	76,20	79,90	91,30
10-04-2008	CRJ2	A	70,20	72,20	81,00
10-04-2008	AN26	D	72,70	75,50	86,50
11-04-2008	T154	A	78,80	83,60	91,80
11-04-2008	T154	A	76,70	81,90	89,90
11-04-2008	MD11	A	77,90	82,40	92,40
11-04-2008	E170	A	70,60	72,60	82,10
11-04-2008	SF34	A	69,20	70,90	79,20
11-04-2008	B734	D	72,00	75,10	87,00
12-04-2008	E170	A	70,90	73,00	81,70
12-04-2008	B735	A	74,10	77,70	85,60
12-04-2008	A320	A	72,70	75,30	84,50
12-04-2008	B738	A	74,30	77,50	87,10
12-04-2008	B734	A	72,40	76,20	85,40
12-04-2008	B735	A	75,20	78,90	87,20
12-04-2008	A320	A	72,30	75,30	84,60
12-04-2008	E145	A	68,50	70,70	79,30
12-04-2008	A320	A	71,80	75,00	85,40
12-04-2008	C295	A	71,00	73,30	82,80
13-04-2008	AT43	A	71,60	74,00	83,60
13-04-2008	E170	A	73,10	75,00	85,20
13-04-2008	B733	A	73,60	77,90	86,60
13-04-2008	B735	A	72,80	76,30	83,90
13-04-2008	B733	A	73,70	76,80	84,80
13-04-2008	B734	A	73,00	76,30	84,50
13-04-2008	A320	A	70,90	72,60	82,00
13-04-2008	B733	A	73,50	76,70	85,30
13-04-2008	P180	A	75,80	80,10	90,70
13-04-2008	B735	A	73,10	76,50	84,60
13-04-2008	A320	A	71,10	73,30	82,80
13-04-2008	A320	A	69,80	70,60	80,30
13-04-2008	B734	D	71,60	74,50	84,70
14-04-2008	B752	A	74,10	76,90	87,30
14-04-2008	B733	A	72,10	74,00	83,50

14-04-2008	E170	A	70,90	72,70	81,60
15-04-2008	MD11	A	77,50	81,70	91,00
15-04-2008	B735	D	69,60	71,60	81,30
15-04-2008	B734	D	72,00	74,90	86,00
16-04-2008	B735	A	73,30	76,30	84,10
16-04-2008	B733	A	71,30	73,50	82,80
16-04-2008	B735	D	70,90	73,80	82,10
16-04-2008	E170	D	68,10	70,20	80,90
16-04-2008	E170	D	69,20	70,60	80,40
18-04-2008	B734	A	73,70	77,40	86,00
18-04-2008	PA34	A	71,70	74,40	80,70
18-04-2008	MD11	A	77,80	83,00	92,30
18-04-2008	B735	A	73,40	76,70	85,10
18-04-2008	SF34	A	70,30	72,40	79,90
18-04-2008	B735	A	73,40	77,20	85,50
18-04-2008	B734	A	73,80	77,10	85,50
18-04-2008	E170	A	71,70	73,60	83,50
18-04-2008	YK40	A	72,60	75,60	84,10
18-04-2008	AT72	A	74,30	77,00	86,80
18-04-2008	AN26	A	74,20	78,00	85,00
18-04-2008	B733	A	72,80	75,00	84,20
18-04-2008	A320	A	72,90	75,60	85,00
18-04-2008	B735	A	71,20	73,20	83,50
18-04-2008	B733	A	72,20	73,80	83,60
18-04-2008	B735	A	72,90	76,40	84,70
18-04-2008	A320	A	71,70	73,90	83,70
18-04-2008	E170	A	71,40	74,10	82,90
18-04-2008	AT43	A	71,40	73,50	82,90
18-04-2008	B734	A	73,70	77,50	85,50
18-04-2008	A320	A	70,00	70,90	81,50
18-04-2008	B734	D	72,70	75,90	85,50
19-04-2008	E170	A	70,70	72,70	81,50
19-04-2008	SF34	A	69,50	71,50	79,50
19-04-2008	AT72	A	75,60	78,40	88,10
19-04-2008	B738	A	74,30	77,30	86,40
19-04-2008	B734	A	74,80	77,80	86,60
19-04-2008	B734	A	73,30	76,00	85,10
19-04-2008	A320	A	71,80	74,30	83,80
19-04-2008	E170	A	71,20	73,10	83,00
19-04-2008	E145	A	69,30	70,50	79,30
19-04-2008	B734	D	71,50	75,00	84,90
19-04-2008	A320	A	71,40	74,20	84,00
20-04-2008	AT43	A	73,70	76,50	85,50
20-04-2008	B733	A	73,40	76,30	84,20
20-04-2008	B734	A	74,40	78,30	86,20
20-04-2008	B733	A	72,50	75,30	84,80
20-04-2008	B733	A	73,00	76,40	84,80
20-04-2008	B735	A	73,30	77,00	85,40
20-04-2008	A320	A	71,60	73,70	83,60
20-04-2008	B734	A	73,50	77,50	86,00
20-04-2008	E145	A	70,70	73,20	82,80
20-04-2008	A320	A	71,60	73,00	83,10
21-04-2008	B752	A	74,50	77,50	87,70
21-04-2008	B752	A	76,50	79,80	89,70
21-04-2008	E170	A	70,40	73,00	81,80
21-04-2008	E170	D	67,70	68,80	78,10

22-04-2008	B735	D	70,30	73,10	82,60
22-04-2008	E170	D	67,70	69,70	78,80
22-04-2008	AN26	D	72,90	76,80	83,70
23-04-2008	B733	A	72,60	74,60	84,10
23-04-2008	AN26	A	73,10	76,50	83,80
23-04-2008	B733	A	72,80	75,60	83,60
23-04-2008	B734	A	73,10	76,60	84,60
23-04-2008	B734	A	73,80	77,70	85,50
23-04-2008	E170	A	71,90	74,10	83,30
23-04-2008	A320	A	72,90	75,40	85,20
23-04-2008	A320	A	70,80	73,00	83,60
24-04-2008	B735	A	72,90	75,90	84,10
24-04-2008	MD11	A	77,80	81,70	90,80
24-04-2008	SF34	A	69,90	72,10	78,90
24-04-2008	B735	A	71,90	73,60	83,00
24-04-2008	B733	A	70,90	72,60	82,10
24-04-2008	AN26	A	73,00	76,60	83,40
24-04-2008	A320	A	70,80	72,30	81,20
24-04-2008	B733	A	73,20	75,10	84,30
24-04-2008	B735	A	73,30	76,50	84,40
24-04-2008	B734	A	72,80	75,90	84,00
24-04-2008	A320	A	72,30	74,00	83,70
24-04-2008	E145	A	70,60	72,20	80,60
24-04-2008	A320	A	70,60	72,10	82,10
25-04-2008	MD11	A	76,40	80,60	89,90
25-04-2008	AN26	A	72,70	75,80	82,70
25-04-2008	B738	A	72,50	75,10	83,60
25-04-2008	A320	A	70,70	72,30	80,70
25-04-2008	B733	A	72,70	75,50	83,10
25-04-2008	B734	A	73,00	76,60	83,80
25-04-2008	B733	A	71,20	73,30	82,00
25-04-2008	E170	A	70,60	72,00	81,00
25-04-2008	B735	A	71,70	73,20	82,10
25-04-2008	AT72	A	72,40	74,00	82,40
25-04-2008	B735	D	71,30	73,70	82,10
25-04-2008	B734	D	72,40	75,60	85,60
26-04-2008	B735	A	72,00	74,20	83,10
26-04-2008	B735	A	72,70	74,90	84,10
26-04-2008	B752	A	71,60	73,60	83,40
26-04-2008	SF34	A	69,40	70,70	79,40
26-04-2008	E170	A	70,90	73,70	82,40
26-04-2008	A320	A	72,80	75,50	85,10
26-04-2008	B734	A	72,70	75,20	84,20
26-04-2008	B733	A	74,60	78,00	86,90
26-04-2008	A320	A	71,10	73,10	82,60
26-04-2008	B738	A	73,20	76,70	85,00
26-04-2008	B735	A	74,20	79,40	86,00
27-04-2008	B734	A	72,50	74,60	84,20
27-04-2008	AT43	A	70,30	71,40	80,70
27-04-2008	B734	A	74,90	77,60	85,70
27-04-2008	B733	A	72,40	74,30	83,80
27-04-2008	B734	A	73,70	76,80	85,10
27-04-2008	A320	A	72,80	74,80	84,30
27-04-2008	B733	A	72,80	76,10	83,90
27-04-2008	B734	A	74,20	78,10	85,30
27-04-2008	B734	A	73,00	75,60	84,10

27-04-2008	A320	A	70,70	72,60	81,80
27-04-2008	A320	A	70,40	71,80	81,20
27-04-2008	T154	A	74,60	77,30	86,60
27-04-2008	B735	A	73,30	77,00	84,50
28-04-2008	B752	A	72,90	74,80	84,70
28-04-2008	B752	A	70,90	72,40	82,00
28-04-2008	B462	A	72,00	74,00	82,80
28-04-2008	E170	A	70,10	71,40	80,10
28-04-2008	B763	D	67,80	69,30	78,20
29-04-2008	B735	D	71,00	73,50	83,30
29-04-2008	E170	D	67,40	68,00	77,40
29-04-2008	AT72	D	67,30	68,50	77,70
30-04-2008	B735	A	73,30	77,70	84,40
30-04-2008	B733	A	72,10	74,20	83,30
30-04-2008	MD11	A	78,00	82,60	91,60
30-04-2008	SF34	A	70,60	72,60	81,30
30-04-2008	B735	D	70,30	72,80	82,80
30-04-2008	E170	D	69,90	72,80	81,40
Średnia $L_{AE}$					85,15
Odchylenie stand. $\sigma$					3,07
Przedział ufności $\Delta$					0,37

Poziom równoważny dla pory nocy określony dla 6 kolejnych najmniej korzystnych (pod względem liczby zdarzeń akustycznych) miesięcy w roku 2007 (maj - październik):

$L_{Aeq, LT} = 52,33$  dB